



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE	:	ACCIDENT REPAIRS
WORKSHOP	:	UBI ROAD 1
CONTACT NO	:	6366 2323
FAX NO	:	6841 1183
REFERENCE	:	PA/OD/0199/2022/JT
DATE	:	15-Mar-22
WIP	:	15787

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 16/3/22

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME	:	MR ROBERT CLARKE
ADDRESS	:	74 ENG NEO AVE
	:	SINGAPORE 289548
TELEPHONE	:	HP +65 81829229
TYPE OF CLAIM	:	OWN DAMAGE CLAIM
POLICY NO	:	7210067405
VEHICLE NO	:	SNA 6558 Y
MODEL CODE	:	AUDI Q5 S LINE 2.0 TFSI
MODEL YEAR	:	15/3/2022
ENGINE NO	:	DGK 002185
CHASSIS NO	:	WAUZZZFY0M2043341
MILEAGE	:	-
DATE IN	:	-
ESTIMATED BY	:	JOHNNY BOO / ALLAN WU
ACCIDENT DATE	:	15-Mar-22
PLACE OF ACCIDENT	:	JUNCTION ROAD AT COMMONWEALTH DRIVE AND QUEENSWAY



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SNA 6558 Y

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION.	S/N \$ 360.00 / ✓	✓
2	TO REMOVE AND REINSTALL REAR LID'S CONVENIENCE LOCK SYSTEM, WIRE HARNESS FOR TAIL LIGHTS AND REAR LID WIPER ASSY.	S/N \$ 480.00 / ✓	✓
3	TO DISLodge AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY.	S/N \$ 1,400.00 / ✓	✓
4	TO RENEW REAR WINDSCREEN TO FACILITATE RENEWAL FOR REAR LID.	S/N \$ 480.00 / ✓	✓
5	TO INSTALL SOLAR FILM FOR REAR WINDSCREEN.	S/N \$ 400.00 X	
SUB TOTAL LABOUR CHARGES		: \$ <u>3,120.00</u>	

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SNA 6558 Y

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
6	TO CARRY OUT WATER SEEPAGE FOR REAR WINDSCREEN. S/N \$	200.00	150 / ✓
7	TO DISMANTLE AND RENEW REAR BUMPER AND REAR LID. TO CUT OUT AND WELD REAR END PANELLING. RE- ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED. 500 x 2	\$ 4,800.00	1200 2500 / ✓
8	TO RESPRAY REAR UPPER BUMPER, REAR LOWER BUMPER, REAR LID, HINGES, REAR END PANELLING AND BOTH REAR WHEEL ARCH TRIMS. 200 400	\$ 4,500.00	2315 2875 / ✓
9	TO CARRY OUT DIAGNOSTIC CHECK. S/N \$	192.00	/ ✓
TOTAL LABOUR CHARGES		: \$ 12,812.00	

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNA 6558 Y

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
1	REAR BUMPER / BR	1	\$	2,548.00	2038.40
2	REAR BUMPER LOWER / BR	1	\$	1,316.00	1052.80
3	REAR BUMPER TRIM - LH / RH X NN	2	\$	258.00	
4	REAR BUMPER TOWING EYE COVER - LH / RH X NN	2	\$	107.00	
5	REAR BUMPER SPOILER / cut (chrome)	1	\$	968.00	774.40
6	REAR BUMPER TRIM - CENTER 1 / BR	1	\$	300.00	240
7	REAR BUMPER CLOSING ELEMENT - LH / RH X NN	2	\$	636.00	
8	REAR BUMPER CHROME TRIM - LH / RH X NN	2	\$	574.00	
9	REAR BUMPER TAIL LIGHT - LH / RH BR /	2	\$	1,558.00	622.80
10	REAR BOOT LID TAIL LAMP - LH / RH X NN	2	\$	12,520.00	
11	LICENCE PLATE LIGHT ? X NN	2	\$	113.00	
12	BOOT LID CONTROL UNIT ? X NN	1	\$	454.00	
13	TAILGATE SENSOR LINE ? X NN	1	\$	128.00	
14	REAR BUMPER REINFORCEMENT BEAM ? / DO	1	\$	1,043.00	834.40
15	REAR BUMPER SEAL - LH / RH / MC	2	\$	7.00	5.12
16	REAR BUMPER HOLDING STRAP / MC	1	\$	189.00	151.20
17	REAR BUMPER GUIDE SECTION - LH / RH ? X NN	2	\$	190.00	
18	REAR PARKING AID SENSOR ? X NN	3	\$	798.00	
19	REAR PARKING AID SENSOR SEAL RING / MC X NN	4	\$	10.00	
20	REAR BUMPER WIRING SET ? X NN	1	\$	544.00	
SUB TOTAL SPARE PARTS		:	\$	24,261.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNA 6558 Y

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
21	REAR LID / <i>nn</i>	1	\$ 4,975.00	3980
22	REAR LID HINGE - LH / RH X <i>nn</i>	2	\$ 510.00	
23	REAR LID ATTACHMENT PARTS X <i>nn</i>	1	\$ 170.00	
24	REAR LID FLAP GASKET ? / <i>CRY</i>	1	\$ 431.00	344.80
25	REAR LID DRIVE UNIT ? X <i>nn</i>	2	\$ 4,062.00	
26	REAR LID LOCK STRIKER ? X <i>nn</i>	1	\$ 96.00	
27	REAR LID LOCK MICROSWITCH ? / <i>BT</i>	1	\$ 252.00	201.60
28	REAR LOCK COVER ? / <i>CRY</i>	1	\$ 8.00	6.32
29	BONNET ANTI-THEFT GUARD COVER ? X <i>nn</i>	1	\$ 17.00	
30	REAR LID LOCK ACTUATOR ? / <i>CRY (camera)</i>	1	\$ 1,468.00	1174.40
31	REAR BUNGS NE X <i>nn</i>	4	\$ 14.00	
32	REAR PACKING ADHESIVE / <i>ne</i>	1	\$ 21.00	16.72
33	AUDI EMBLEM / <i>ne</i>	1	\$ 144.00	114.80
34	"Q5" EMBLEM / <i>ne</i>	1	\$ 104.00	82.80
35	"QUATTRO" EMBLEM / <i>ne</i>	1	\$ 104.00	82.80
36	REAR WINDSCREEN / <i>ne</i> (<i>photo</i>)	1	\$ 1,274.00	1019.20
37	PRIMER / <i>ne</i>	1	\$ 22.00	17.36
38	REAR SPOILER - LH / RH / <i>ne</i>	2	\$ 520.00	415.20
39	TAILGATE TRIM STRIP / <i>ne</i>	1	\$ 330.00	263.60
40	TAILGATE SPOILER FIXING PARTS / <i>ne</i>	1	\$ 36.00	28.24
SUB TOTAL SPARE PARTS		:	\$ 14,558.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNA 6558 Y

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
41	TAILGATE SPOILER FOAM STRIPS / AC	1	\$ 36.00	28.24
42	REAR END PANEL ? / DD	1	\$ 632.00	505.20
43	REAR LOCK CARRIER REINFORCEMENT ? X nn	1	\$ 269.00	
44	REAR SILENCER HEAT SHIELD ? X nn	1	\$ 159.00	
45	REAR WHEEL ARCH COVER - LH / RH - AC (PH)	2	\$ 1,230.00	984
46	REAR NO PLATE - CUT	S/N	\$ 60.00	60 180
47	ARYLIC SEALANT ? / ACC	S/N	\$ 180.00	
48	CAVITY WAX ? / ACC	S/N	\$ 140.00	140
49	STONE CHIP ? / ACC	S/N	\$ 180.00	180
50	METAL FILLER POWDER ? / ACC	S/N	\$ 280.00	280
51	REAR WINDSCREEN SEALANT - AC	S/N	\$ 200.00	200
52	SUNDRIES ? / ACC	\$	400.00	62.88
TOTAL SPARE PARTS		:	\$ 42,585.00	
TOTAL LABOUR CHARGES		:	\$ 12,812.00	
GRAND TOTAL		:	\$ 55,397.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

Steve (LKK)
16/3/22, 11-30

90-14 AL

Excell-?

P/P

My BIL

6 days + 6 days = 12 days

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg



Supplementary Estimate-1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 / Fax: 6256 4315

Estimate No.

Date

Service Advisor

Pages

Regn No

Model No

PA/OD/0199/2022/JT

29-Mar-22

CHANG

1 of 1

SNA 6558 Y

AUDI Q5 S LINE 2.0 TFSI

Quantity	Description	Unit Price	Amount
Parts			
1	REAR LID BOWDEN CABLE / TA	\$ 43.00	33.84
GRAND TOTAL		\$ 43.00	

For Premium Automobiles



Authorised Signature

Steve (LKK)
29/3/22