

SM AUTOMOTIVE

Block C, 1 Kaki Bukit Avenue 6 #01-43 Singapore 417883

Email: SM_AUTOMOTIVE@HOTMAIL.COM

Tel: (65) 6747 9241

Fax: (65) 6741 7276

RCB No.: 53231488C

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

Accident date : 13/03/2022

Estimated repair cost for vehicle no: SKL6345Y TOYOTA VIOS E GRADE AUTO

CHASSIS: MR2BT9F3201065506 (2013)

16/03/2022

S/N	Qty	Items	U/price	Amount	
1	1	REAR BUMPER <i>Dented</i>	\$547.90	\$547.90	✓
2	2	REAR BUMPER REFLECTOR <i>Cracked</i>	\$87.60	\$175.20	✓
3	2	REAR BUMPER SIDE RETAINER <i>new</i>	\$74.60	\$149.20	✓
4	2	REAR BUMPER BRACKET <i>new</i>	\$65.30	\$130.60	✓
5	1	REAR BOOTLID <i>Cracked</i>	\$849.30	\$849.30	✓
6	1	REAR BOOTLID LOCK <i>Dented</i>	\$156.40	\$156.40	✓
7	1	REAR BOOTLID OUTER MOULDING <i>new</i>	\$188.30	\$188.30	✓
8	1	REAR BOOTLID EMBLEM LOGO <i>new</i>	\$94.80	\$94.80	✓
9	1	REAR BOOTLID EMBLEM VIOS <i>new</i>	\$84.60	\$84.60	✓
10	1	REAR BOOTLID EMBLEM E <i>new</i>	\$74.60	\$74.60	✓
11	1	REAR WEATHER STRIPE <i>new</i>	\$175.10	\$175.10	✓
12	1	REAR END PANEL <i>Dented</i>	\$455.60	\$455.60	✓
13	1	REAR END PANEL TOP GARNISH <i>Dented</i>	\$195.70	\$195.70	✓
14	2	REAR TAILLAMP <i>with Cracked</i>	\$357.00	\$714.60	357
15	2	REAR TAILLAMP LOWER BRACKET <i>new</i>	\$63.10	\$126.20	✓
16	2	REAR TAILLAMP INNER PANEL <i>new</i>	\$140.70	\$281.40	✓

TOTAL : \$4,399.50

LESS 25 % \$1,099.88

SUB-TOTAL : \$3,299.63

Supplementary
① *Rear Bumper reinforcement*
Dented

3140330

2355622

\$3140-30

-25%

\$2355.22

S/N	Qty	ITEMS / SPECIAL NETT	U/price	Amount
1	1	REAR BUMPER CLIPS <i>new</i>	\$80.00	\$80.00 30
2	1	REAR END PANEL TOP GARNISH <i>Clips new</i>	\$40.00	\$40.00 20
3	2	REAR TAILLAMP CLIPS <i>new</i>	\$12.00	\$24.00 10
4	1	REAR END PANEL SEALANT <i>new</i>	\$80.00	\$80.00 60
5	1	REAR BUMPER REVERSE SENSOR <i>Damaged</i>	\$280.00	\$280.00 200
6	1	REAR REVERSE CAMERA <i>new</i>	\$380.00	\$380.00 4

340

TOTAL: \$884.00

TOTAL PARTS: \$4,183.63

Labour charges

- 1 LABOUR FOR PANEL BEATING
- 2 LABOUR FOR SPRAYPAINTING
- 3 WIRING CHECK
- 4 TO APPLY TUFF COATING/RUST PROOF ACCIDENT AREAS
- 5 LABOUR FOR REMOVE & TRANSFER ALL REAR BOOTLID FITTING
- 6 To remove upholstery.
- 7 To remove reverse sensor

\$1,000.00 *800*
 \$1,000.00 *900*
 \$80.00 *30*
 \$300.00 *80*
 \$200.00 *80*

Subtotal :- \$2,580.00

Total:- \$6,763.63

Adrian L
 H/s 17/03/22.
 06 Days
 Supplementary: 281.85
 Total: 4997.07
 H/s: AK

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SM AUTOMOTIVE

Block C, 1 Kaki Bukit Avenue 6 #01-43 Singapore 417883

Email: SM_AUTOMOTIVE@HOTMAIL.COM

Tel: (65) 6747 9241 Fax: (65) 6741 7276

RCB No: 53231488C GST Reg No : 53231488C

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

Accident date : 13/03/2022

Estimated repair cost for vehicle no: SKL6345Y TOYOTA VIOS E GRADE AUTO

CHASSIS: MR2BT9F3201065506 (2013)

S/N	Qty	Items	U/price	Amount
1	1	REAR BUMPER REINFORCEMENT <i>Dented</i>	\$375.80	\$375.80

TOTAL : \$375.80

LESS 25 % \$93.95

SUB-TOTAL : \$281.85