


ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
Estimated Cost: \_\_\_\_\_  
OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
To Inspect Vehicle No: SMB 1477L  
at Workshop m/s SMRT  
of 60, Woodlands Ind Pk E4  
Insured: \_\_\_\_\_  
Policy No. \_\_\_\_\_  
Claims No. MT/1163478-002  
Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
(Client's Record)  
Make of Veh: \_\_\_\_\_

(Policy Condition)  
Remark: The veh had commenced its  
repair at the time of inspection.



Bal. or Market Value: \_\_\_\_\_  
IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No  
GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
Est. Repairs: 3 days Res.: Yes or No  
Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: SMB 1477L Yr Regn: 2014 / SEP  
Type: M.Car / M.Cycle / Bds / Van / Lorry / Taxi / Prime Mover /  
Truck / Trailer or \_\_\_\_\_  
Make: MAN NL320 F(A22) 11L A c.c. 10518  
Colour: MULTI A/C: Insured / Std / NI / NA  
Sp. Reading: 596250 T/Radio: Insured / Std / NI / NA  
Eng/No: \_\_\_\_\_  
C/No: WMAA 22224E7002203  
Gen. Cond: Good / Fair / Poor / Burnt  
Steering: In order / Jammed / Leaked / Burnt or \_\_\_\_\_  
Brake: In order / Jammed / Leaked / Burnt or \_\_\_\_\_  
Modi: NI / S/Rim / STD A/Rim or \_\_\_\_\_  
Tyre Size: F: 275/70R22.5  
R: \_\_\_\_\_  
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or FRUEN  
Front Rear  
R/Bal. 8 mm R/Bal. 8/8 mm  
L/Bal. 8 mm L/Bal. 8/8 mm  
D.O.A. 28/02/22 D.O.I. 16/03/22  
Survey held at SMRT  
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or  
REAR N/S  
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
04/04/22	Rasul finalised LS \$2300, 3 days. (Red \$4001 40, 64%)

Date/Time, File Pass to? ☐ : Preli. Report

1) 27/04 Typist ☐ : Final Report

Date/Time, File Return to?

2) \_\_\_\_\_

Rep. Format: TP

Lump Sum / ~~TP~~ (\$) 2300

Days Of Repair: 3

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_)  
☐ : Interview (\$ \_\_\_\_\_)  
☐ : Tech. Invs (\$ \_\_\_\_\_)  
☐ : Weekend (\$ \_\_\_\_\_)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL



## SMRT Accident Vehicle Repair Estimates

<b>SMRT Automotive Services Pte Ltd</b>
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672


Date Generated : 16/03/2022

User ID : JeongCH

### Section A - Accident Details

Registration Number	SMB1477L
Case Reference Number	BUS/02/22/7024
Registration Date	9/11/2014
Company Type	SMRT Buses Ltd
Make	MAN
Model	MAN NL320F(A22)
Name of Driver	Tan Hui Hong
Type of Accident	Head to Rear
Accident Date and Time	2/28/2022 12:20 PM
Accident Reported Date and Time	2/28/2022 2:45 PM
Is Surveyor Required?	Yes
Surveyed by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	
Special Instruction to ARC, if any	SMB1477L - Rear bumper dented and scratched and rear engine hatch scratched SBJ5115T (TP) - INSURED WITH NTUC
Prepared Date and Time	3/16/2022 10:09 AM
Chassis Number	WMAA22ZZ4E7002203
Mileage	
Work Shop	
Repair Completion Date and Time	

### Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$0.00	\$0.00
Total Spray Cost	\$0.00	\$0.00
Total Spare Part Cost	\$963.06	\$0.00
Total Other Cost	\$0.00	\$0.00
<b>TOTAL COST</b>	<b>\$963.06</b>	<b>\$0.00</b>
<b>Lump Sum Total</b>	<b>\$3,350.00</b>	<b>\$0.00</b>
Number of Repair Days	4.0	3 days
Prepared / Adjusted By	Kok Khoon Goh	
ARC / Surveyor Sign Off Date	16/03/2022 10:15 AM	
Signature		x
Remarks		

### Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	



**SMRT Accident Vehicle Repair Estimates**

<b>SMRT Automotive Services Pte Ltd</b>
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 16/03/2022

User ID : JeongCH

**Section D - Details of Repair Estimates**

Part 1 - Labour Works		
Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.	\$1,325.00	795
<b>Total Labour</b>	<b>\$1,325.00</b>	

Part 2 - Spray Painting & Panel Beating Related Works		
Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	\$1,048.00	878
<b>Total Spray Painting &amp; Panel Beating</b>	<b>\$1,048.00</b>	

Part 3 - Other Costs - Accident and Accident Repair Related Expense		
Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
<b>Total Other Costs</b>		

Part 4 - Spare Parts / Material Usage									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
			STICKER 60KM/H	1.00	\$5.00	0.00	\$5.00	Replace	re /
			STICKER SMRT	1.00	\$75.00	0.00	\$75.00	Replace	re /
010060	Body	F01001-CW271	COVER:REAR TAIL LAMP,LH,FOR MAN A22 BUS	1.00	\$974.70	100.00	\$0.00	Repair	R
011408	Body		BUMPER:REAR,CENTRE,MAN A22 'C' SERIES	1.00	\$1,625.00	100.00	\$0.00	Repair	R
010372	Body	4001F09-ACCE5021	PANEL,REFLECTOR:REAR,LH,FOR MAN BUS	1.00	\$107.00	10.00	\$96.30	Replace	cm /
010298			STOP LAMP LED	1.00	\$1,141.70	10.00	\$1,027.53	Replace	cm /
<b>Total</b>					<b>\$3,928.40</b>		<b>\$1,203.83</b>		

Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
<b>Total</b>									

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
  - To display damaged part(s) during resurvey
  - Parts prices are subject to confirmation
  - Third party survey is on a "Without Prejudice" basis
  - No illegal modification(s) is allowed
  - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Resue  
Up 90010068  
3 days  
H/S  
16/03/22 @ 1445  
Repair after repair