

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: SMB 1477L
at Workshop m/s SMRT
of 60, Woodlands Ind Pk E4
Insured: _____
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)
Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____
IDAC Accident Rpt: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: _____ days Res.: Yes or No
Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SMB 1477L Yr Regn: 2014 / SEP
Type: M.Car / M.Cycle / Bds / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or

Make: MAN NL320 F(A22) 11L A c.c. 10518
Colour: MULTI A/C: Insured / Std / NI / NA
Sp. Reading: 596250 T/Radio: Insured / Std / NI / NA

Eng/No: _____
C/No: WMAA 22224E7002203
Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or
Brake: In order / Jammed / Leaked / Burnt or
Modi: NI / S/Rim / STD A/Rim or

Tyre Size: F: 275/70R22.5
R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or FRANKEN

Front		Rear	
R/Bal. <u>8</u>	mm	R/Bal. <u>8/8</u>	mm
L/Bal. <u>8</u>	mm	L/Bal. <u>8/8</u>	mm
D.O.A. <u>28/02/22</u>		D.O.I. <u>16/03/22</u>	

Survey held at SMRT
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
REAR N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction

Date/Time, File Pass to? ☐ : Preli. Report
☐ : Final Report

Date/Time, File Return to?

2)

Rep. Format: _____

Lump Sum / L.B.H. (\$) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)
☐ : Interview (\$ _____)
☐ : Tech. Invs (\$ _____)
☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

TOTAL

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672


Date Generated : 16/03/2022

User ID : JeongCH

Section A - Accident Details

Registration Number	SMB1477L
Case Reference Number	BUS/02/22/7024
Registration Date	9/11/2014
Company Type	SMRT Buses Ltd
Make	MAN
Model	MAN NL320F(A22)
Name of Driver	Tan Hui Hong
Type of Accident	Head to Rear
Accident Date and Time	2/28/2022 12:20 PM
Accident Reported Date and Time	2/28/2022 2:45 PM
Is Surveyor Required?	Yes
Surveyed by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	
Special Instruction to ARC, if any	SMB1477L - Rear bumper dented and scratched and rear engine hatch scratched SBJ5115T (TP) - INSURED WITH NTUC
Prepared Date and Time	3/16/2022 10:09 AM
Chassis Number	WMAA22ZZ4E7002203
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$0.00	\$0.00
Total Spray Cost	\$0.00	\$0.00
Total Spare Part Cost	\$963.06	\$0.00
Total Other Cost	\$0.00	\$0.00
TOTAL COST	\$963.06	\$0.00
Lump Sum Total	\$3,350.00	\$0.00
Number of Repair Days	4.0	3 days
Prepared / Adjusted By	Kok Khoon Goh	
ARC / Surveyor Sign Off Date	16/03/2022 10:15 AM	
Signature		X
Remarks		

Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 16/03/2022

User ID : JeongCH

Section D - Details of Repair Estimates

Part 1 - Labour Works		
Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.	\$1,325.00	795
Total Labour	\$1,325.00	

Part 2 - Spray Painting & Panel Beating Related Works		
Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	\$1,048.00	878
Total Spray Painting & Panel Beating	\$1,048.00	

Part 3 - Other Costs - Accident and Accident Repair Related Expense		
Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Other Costs		

Part 4 - Spare Parts / Material Usage									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
			STICKER 60KM/H	1.00	\$5.00	0.00	\$5.00	Replace	re /
			STICKER SMRT	1.00	\$75.00	0.00	\$75.00	Replace	re /
010060	Body	F01001-CW271	COVER:REAR TAIL LAMP,LH,FOR MAN A22 BUS	1.00	\$974.70	100.00	\$0.00	Repair	R
011408	Body		BUMPER:REAR,CENTRE,MAN A22 'C' SERIES	1.00	\$1,625.00	100.00	\$0.00	Repair	R
010372	Body	4001F09-ACCE5021	PANEL,REFLECTOR:REAR,LH,FOR MAN BUS	1.00	\$107.00	10.00	\$96.30	Replace	cm /
010298			STOP LAMP LED	1.00	\$1,141.70	10.00	\$1,027.53	Replace	cm /
Total					\$3,928.40		\$1,203.83		

Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Resue
Up 90010068
3 days
H/S
16/03/22 @ 1445
Revy after repair