

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 17 Mar 2022)

Parts: 143 MERCEDES-BENZ CLA180 1.6 AMG (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Accord Auto Services Pte Ltd/SLZ1234G/17/03/2022 10:06

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT BUMPER / <i>BR</i>	0.00	0.00	*1,050.00 F
2	1		*FRONT BUMPER RH SIDE RETAINER / <i>BR</i>	0.00	0.00	*25.00 F
3	1		*FRONT RH BUMPER SENSOR / <i>Shard</i>	0.00	0.00	*120.00 F
4	1		*FRONT BUMPER CENTER GARNISH (RH) - <i>CUT</i>	0.00	0.00	*135.00 F
5	1		*FRONT BUMPER TOW COVER X	0.00	0.00	*45.00 F
6	1		*FRONT BUMPER RH INNER BRACKET <i>1 - Missing</i>	0.00	0.00	*165.00 F
7	1		*FRONT BUMPER TOP EMBLEM / <i>MC</i>	0.00	0.00	*55.00 F
8	1		*FRONT BUMPER SENSOR SEAL (SET) / <i>MC</i>	0.00	0.00	*36.00 F
9	1		*FRONT RH FENDER / <i>BR</i>	0.00	0.00	*400.00 F
10	1		*FRONT RH FENDER SHIELD / <i>TN</i>	0.00	0.00	*115.00 F
11	1		*FRONT RH FENDER EMBLEM / <i>MC</i>	0.00	0.00	*80.00 F
12	1		*FRONT RH HEADLAMP / <i>BR</i>	0.00	0.00	*1,700.00 F
13	1		*FRONT RH HEADLAMP LOWER BRACKET <i>?</i>	0.00	0.00	*70.00 F
14	1		*FRONT RH ABSORBER / <i>BT</i>	0.00	0.00	*400.00 F
15	1		*FRONT RH ABSORBER MOUNTING / <i>BT</i>	0.00	0.00	*190.00 F
16	1		*FRONT RH LOWER ARM / <i>BT</i>	0.00	0.00	*280.00 F
17	1		*FRONT RH LINKAGE / <i>BT</i>	0.00	0.00	*36.00 F
18	1		*FRONT STABILIZER BAR & BUSH <i>1 - BT</i>	0.00	0.00	*200.00 F
19	1		*FRONT RH DRIVE SHAFT(*N/S) <i>1 - BT</i>	0.00	0.00	*1,350.00 F
20	1		*FRONT RH TIE ROD <i>1 - BT</i>	0.00	0.00	*73.00 F
21	1		*FRONT RH TIE ROD END <i>2 - BT</i>	0.00	0.00	*65.00 F
22	1		*FRONT RH KNUCKLE WITH WHEEL BEARING / <i>BT</i>	0.00	0.00	*680.00 F
23	1		*FRONT RH DRIVE SHAFT INNER COVER <i>1 - TN</i>	0.00	0.00	*60.00 F
24	1		*FRONT BUMPER UNDER COVER <i>1 - BR</i>	0.00	0.00	*210.00 F
25	2		*RIM / <i>CUT</i>	0.00	0.00	*1,800.00 F

F=Franchise part.

Sub Total (\$\$)	9,340.00
+ Margin on L,N Items 10.00% (\$\$)	934.00
Total Parts (\$\$)	10,274.00

Accord Auto Services Pte Ltd/SLZ1234G/17/03/2022 10:06. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	FRONT BUMPER CLIPS <i>✓ NK</i>	<i>30</i> 40.00
2	1	RH FRONT & REAR FENDER SHIELD CLIPS <i>✓ NK</i>	<i>30</i> 75.00
3	2	TYRE CONTINENTAL RUN FLAT <i>TN (80% of 260)</i>	570.00
Sub Total (\$\$)			685.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	Spray Painting to All Affected Areas (Including Side Skirt & Front RH Door)	New	<i>800</i> 1,000.00 <i>✓</i>
2	Labour Remove / Refix Accident Damages parts to knock , jack, cut weld and realign accident affected area	New	<i>500</i> 1,200.00
3	Check Wiring System & Light	New	<i>80</i> 80.00 <i>✓</i>
4	To Check & Adjust Wheel Aligment	New	80.00 <i>✓</i>
5	To Remove & Replace Tyre & Rim (Including Tyre Balancing)	New	<i>60</i> 80.00 <i>✓</i>
6	To Remove / Replace Undercarriage	New	200.00 <i>✓</i>
7	Computer Diagnostic Reseting Headlamp , Sensor, Undercarriage & etc... After Repair	New	<i>150</i> 350.00
Gross Labour Cost (\$\$)			2,990.00

Accord Auto Services Pte Ltd/SLZ1234G/17/03/2022 10:06. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Supp Part
 1) Engine Under Cover *496* *✓* BR
 2) RH Side Skirt *5700* *✓* BR

Steve (LKK)
17/3/22, 3.30pm

OD- NK M
EXCESS- ?
L/S
My AL sy
6 dys

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 30 Mar 2022)

Parts: 143 MERCEDES-BENZ CLA180 1.6 AMG (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Accord Auto Services Pte Ltd/SLZ1234G/30/03/2022 16:42

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*ENGINE UNDER COVER(CENTER) BR	0.00	0.00	*96.00 F ✓
2	1		*RH SIDE SKIRT BR	0.00	0.00	*700.00 F ✓
Sub Total (S\$)						796.00
+ Margin on L,N Items 10.00% (S\$)						79.60
Total Parts (S\$)						875.60

F=Franchise part.

Accord Auto Services Pte Ltd/SLZ1234G/30/03/2022 16:42. Not valid without Reference section.
Generated using Merimen e-Claims IEAS