



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD

300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV No. AC2203838

INV Date 20/06/2022

Reference CC4/LPC22002487/Kga3q2

Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. SMN 8604C
Insured Veh. GBB 5795Y
Claim No. 21/22/22/VC00/025556
Policy No. Z/21/VC00/111133
Accident Date 16/03/2022
Inspection Date 23/03/2022

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CC4/LPC22002487/Kga3q2 Date: 20/06/2022 Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBB 5795Y	Veh. Inspected	SMN 8604C	
Policy No.	Z/21/VC00/111133	Coverage (\$)	0.00	
Claim No.	21/22/22/VC00/025556	Excess (\$)	0.00	
Assign From	ONG LI LI	Assign Date	17/03/2022	
2. Vehicle Particulars & Condition				
Make & Model	HONDA FREED (A)	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	GB71085177	Colour	METALLIC GREY	
Odometer	256567 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/65 R15	KAPSEN	7 mm	
L/H Front Tyre	185/65 R15	KAPSEN	7 mm	
R/H Rear Tyre	185/65 R15	RASSURER	2 mm	
L/H Rear Tyre	185/65 R15	RASSURER	2 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	16/03/2022	Inspection Date	23/03/2022	
Survey held at	HUI YANG MOTOR PTE LTD BLOCK 176 SIN MING DRIVE #04-02 SIN MING AUTOCARE SINGAPORE 575721			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMN 8604C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR TAILGATE	BENT	1,207.90	1,207.90
1	REAR TAILGATE 'H' LOGO	NECESSARY	68.20	68.20
1	REAR TAILGATE 'FEREED' EMBLEM	NECESSARY	58.00	58.00
1	REAR TAILGATE WINDSCREEN MOULDING	NECESSARY	181.80	121.00
1	REAR TAILGATE OUTER CHROME	MTG CRACKED	385.50	321.70
1	REAR TAILGATE INNER GARNISH	MTG CRACKED	265.30	265.30
1	REAR TAILGATE INNER LOCK	DENTED	287.50	187.50
1	REAR TAILGATE INNER RUBBER	SERVICEABLE	195.50	-
1	REAR TAILGATE INNER HANDLE	SERVICEABLE	47.50	-
2	REAR TAILLAMP LOWER BRACKET @\$85.50	SERVICEABLE	171.00	-
1	REAR BUMPER	BUCKLED	991.20	828.90
2	REAR BUMPER SIDE RETAINER @\$181.25	SERVICEABLE	362.50	-
1	REAR BUMPER TOWING COVER	SERVICEABLE	58.50	-
2	REAR BUMPER CENTRE BEAM @\$180.50	SERVICEABLE	361.00	-
1	REAR END PANEL	TO REPAIR SEE LABOUR	623.70	-
1	REAR END PANEL INNER GARNISH	MTG CRACKED	100.90	100.90
	LESS 20% DISCOUNT		-1,073.20	-631.88
			4,292.80	2,527.52
<u>SPECIAL NETT ITEMS</u>				
1	SET REAR PARKING SENSOR (SN)	SHORTED	280.00	200.00
1	SET REAR NUMBER PLATE & CASING (SN)	SERVICEABLE	50.00	-
1	SEALANT (SN)	NECESSARY	80.00	40.00
			410.00	240.00
<u>LABOUR</u>				
	REMOVE & REFIX REAR WINDSCREEN GLASS .		120.00	120.00
	TUFFKOTE.		80.00	30.00
	WIRING.		100.00	20.00
	SPRAY PAINTING.		1,000.00	600.00

Report Ref No. CC4/LPC22002487/Kga3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	LABOUR CHARGES.INCLUSIVE OF THE REPAIR OF REAR END PANEL .		1,000.00	500.00
			2,300.00	1,270.00
GRAND TOTAL			7,002.80	4,037.52
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,200.00

Report Ref No. CC4/LPC22002487/Kga3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMN 8604C

INSPECTION






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd


51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMN 8604C

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMN 8604C

RE-INSPECTION

