

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E
BEDOK NORTH AVE 4,
#01-2008/10/12 SINGAPORE 489977
TEL : 6441 5655 FAX : 6441 5355/6243 8121
R.O.C No : 200104141D GST Reg. No. 20-0104141-D

TO : 96652076

GANGA PARAMESH D/O ARIKRISHNASAMY
BLK 533 BUKIT PANJANG RING ROAD
13-801
SINGAPORE 670533
TEL : FAX :
PH : 96652076
ATTN :

ESTIMATE BILL

Number : EB00005910
Date : 17/03/2022
Case No : AD00012515
Vehicle No : SKV6491E
Chassis : SJNFEAJ11U1468649
Year of Mfr : 2015
Policy No :
Model : NISSAN QASHQAI 1.2
DIG-T CVT ABS 2WD

Term:

Sn	DESCRIPTION	QTY	U PRICE	DISC	AMOUNT
1	FRONT WINDSCREEN GLASS <i>320</i>	1.0	1,375.60	10	1,238.04
2	FRONT WINDSCREEN GLASS MOULDING <i>ner</i>	1.0	142.50	10	128.25
3	ROOF PANEL <i>Body 20/300</i>	1.0	2,393.55	10	2,154.20
4	ROOF LINING <i>waged</i>	1.0	1,982.55	10	1,784.30
5	ROOF BRACKET <i>R</i>	4.0		10	
6	ROOF SIDE MOULDING LH <i>ner</i>	1.0	226.40	10	203.76
7	ROOF SIDE MOULDING RH <i>ner</i>	1.0	226.40	10	203.76
8	FRONT DOOR LH <i>20/300</i>	1.0	1,166.20	10	1,049.58
9	FRONT DOOR RUBBER LH <i>11</i>	1.0	153.10	10	137.79
10	FRONT DOOR STICKER LH <i>ner</i>	1.0	39.00	10	35.10
11	FRONT DOOR OUTER TOP CHROME MOULDING LH <i>Body</i>	1.0	200.10	10	180.09
12	FRONT DOOR OUTER BOTTOM CHROME MOULDING LH <i>Body</i>	1.0	76.20	10	68.58
13	FRONT DOOR TRIMBOARD LH	1.0	1,460.50	10	1,314.45
14	FRONT DOOR HINGE BOTTOM LH <i>ner</i>	1.0	58.90	10	53.01
15	FRONT DOOR HINGE TOP LH <i>ner</i>	1.0	58.90	10	53.01
16	FRONT DOOR CHECKER LH <i>ner</i>	1.0	48.20	10	43.38
17	FRONT DOOR PILLAR LH <i>Body 20</i>	1.0	1,469.00	10	1,322.10
18	FRONT DOOR PILLAR RUBBER LH <i>De</i>	1.0	214.90	10	193.41
19	WING MIRROR LH <i>320</i>	1.0	582.10	10	523.89
20	WING MIRROR COVER LH <i>320</i>	1.0	112.50	10	101.25
21	WING MIRROR SIGNAL LAMP LH <i>320</i>	1.0	68.50	10	
22	FRONT DOOR GLASS CHAMBER RUBBER LH <i>Tw1</i>	1.0	192.60	10	173.34
23	FRONT DOOR OUTER HANDLER LH (BIG) <i>cut</i>	1.0	173.40	10	156.06
24	FRONT DOOR OUTER HANDLER LH (SMALL) <i>cut</i>	1.0	35.00	10	31.50
25	FRONT DOOR REGULATOR GEAR WITH MOTOR LH <i>11</i>	1.0	563.60	10	507.24
26	FRONT DOOR PROTECTOR LH <i>cut</i>	1.0	342.60	10	308.34
27	FRONT DOOR CENTER PILLAR LH <i>R</i>	1.0		10	
28	FRONT DOOR LOCK LH <i>Body 20</i>	1.0	172.30	10	155.07
29	REAR DOOR LH <i>20/300</i>	1.0	1,166.20	10	1,049.58
30	REAR DOOR TOP CHROME LH <i>Body</i>	1.0	200.10	10	180.09
31	REAR DOOR BOTTOM CHROME LH <i>Tw1</i>	1.0	76.20	10	68.58
32	REAR DOOR STICKER LH <i>ner</i>	1.0	39.00	10	35.10
33	REAR DOOR OUTER HANDLER LH (BIG) <i>cut</i>	1.0	173.40	10	156.06
34	REAR DOOR OUTER HANDLER LH (SMALL) <i>cut</i>	1.0	35.00	10	31.50

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E
BEDOK NORTH AVE 4,
#01-2008/10/12 SINGAPORE 489977
TEL : 6441 5655 FAX : 6441 5355/6243 8121
R.O.C No : 200104141D GST Reg. No. 20-0104141-D

TO : 96652076

GANGA PARAMESH D/O ARIKRISHNASAMY
BLK 533 BUKIT PANJANG RING ROAD
13-801
SINGAPORE 670533
TEL : FAX :
PH : 96652076
ATTN :

ESTIMATE BILL

Number : EB00005910
Date : 17/03/2022
Case No : AD00012515
Vehicle No : SKV6491E
Chassis : SJNFEAJ11U1468649
Year of Mfr : 2015
Policy No :
Model : NISSAN QASHQAI 1.2
DIG-T CVT ABS 2WD

Term:

Sn	DESCRIPTION	QTY	U PRICE	DISC	AMOUNT
35	REAR DOOR PROTECTOR LH <i>cut</i>	1.0	280.40	10	252.36
36	REAR FENDER LH <i>as</i>	1.0	1,230.90	10	1,107.81
37	REAR FENDER PROTECTOR LH <i>great</i>	1.0	540.50	10	486.45
38	TAILAMP PANEL LH <i>R</i>	1.0	361.90	10	325.71
39	DASHBOARD	1.0	1,637.90	10	1,474.11
40	BONNET <i>Surf/Buc</i>	1.0	1,061.30	10	955.17
41	BONNET HINGE LH <i>tw</i>	1.0	59.80	10	53.82
42	BONNET HINGE RH <i>tw</i>	1.0	59.80	10	53.82
43	FRONT FENDER RH <i>as/surf</i>	1.0	753.50	10	678.15
44	FRONT FENDER LH <i>as/surf</i>	1.0	753.50	10	678.15
45	FRONT FENDER PROTECTOR LH <i>great</i>	1.0	540.50	10	486.45
46	FRONT FENDER PROTECTOR RH <i>great</i>	1.0	540.50	10	486.45
47	FRONT FENDER SHIELD LH <i>tw</i>	1.0	128.30	10	115.47
48	FRONT FENDER SHIELD RH <i>tw</i>	1.0	128.30	10	115.47
49	SUPPORT PANEL <i>R</i>	1.0	588.10	10	529.29
50	SUPPORT PANEL INNER SIDE GARNISH LH <i>11</i>	1.0	90.20	10	81.18
51	FRONT GRILLE <i>11</i>	1.0	525.00	10	472.50
52	HEADLAMP WITH LOWER BRACKET LH <i>cro</i>	1.0	612.20	10	550.98
53	FRONT BUMPER <i>7.5</i>	1.0	682.90	10	614.61
54	FRONT BUMPER RETAINER RH <i>Surf</i>	1.0	24.30	10	21.87
55	FRONT BUMPER RETAINER LH <i>Surf</i>	1.0	24.30	10	21.87
56	FRONT BUMPER BRACKET RH <i>11</i>	1.0	193.70	10	174.33
57	FRONT BUMPER BRACKET LH <i>11</i>	1.0	193.70	10	174.33
58	FRONT BUMPER REINFORCEMENT <i>11</i>	1.0	755.90	10	680.31
59	FRONT BUMPER SPONGE <i>11</i>	1.0	240.90	10	216.81
60	HEADLAMP RH	1.0	612.20	10	550.98
61	ENGINE LOWER DUST COVER	1.0	308.80	10	277.92
62	FRONT LOWER ARM LH	1.0	249.40	10	224.46
63	FRONT LOWER ARM RH <i>Surf</i>	1.0	249.40	10	224.46
64	FRONT ABSORBER MOUNTING RH	1.0	104.00	10	93.60
65	FRONT ABSORBER MOUNTING LH	1.0	104.00	10	93.60
66	FRONT STABILIZER BAR LINK LH	1.0	36.60	10	32.94
67	FRONT STABILIZER BAR LINK RH <i>Surf</i>	1.0	36.60	10	32.94
68	FRONT BUMPER LOWER GARNISH <i>11</i>	1.0		10	

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

20191-50

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E
BEDOK NORTH AVE 4,
#01-2008/10/12 SINGAPORE 489977
TEL : 6441 5655 FAX : 6441 5355/6243 8121
R.O.C No : 200104141D GST Reg. No. 20-0104141-D

TO : 96652076

GANGA PARAMESH D/O ARIKRISHNASAMY
BLK 533 BUKIT PANJANG RING ROAD
13-801
SINGAPORE 670533
TEL : FAX :
PH : 96652076
ATTN :

ESTIMATE BILL

Number : EB00005910
Date : 17/03/2022
Case No : AD00012515
Vehicle No : SKV6491E
Chassis : SJNFEAJ11U1468649
Year of Mfr : 2015
Policy No :
Model : NISSAN QASHQAI 1.2
DIG-T CVT ABS 2WD

Term:

Sn	DESCRIPTION	QTY	U PRICE	SDR DISC	AMOUNT
Nett Price - Parts Sub Total					25,978.78
69	FRONT DOOR GLASS LH <i>shot</i>	1.0	800.00	0	800.00
70	REAR DOOR GLASS LH <i>cro</i>	1.0	800.00	0	800.00
71	REAR FENDER QUARTER GLASS WITH CHROME LH <i>nn</i>	1.0	400.00	0	400.00
72	REAR RIM LH <i>cu</i>	1.0	1,231.90	0	1,231.90
73	FRONT RIM LH <i>cu</i>	1.0	1,231.90	0	1,231.90
74	FRONT RIM RH <i>one</i>	1.0	1,231.90	0	1,231.90
75	REAR WHEEL BEARING LH	1.0	346.60	0	346.60
76	FRONT BUMPER SENSOR <i>nn</i>	1.0	280.00	0	280.00
77	RADIATOR <i>nn</i>	1.0	716.10	0	716.10
78	AIR CON CONDENSER <i>nn</i>	1.0	696.90	0	696.90
79	RADIATOR COWLING, FAN AND MOTOR <i>nn</i>	1.0	635.20	0	635.20
80	FRONT TYRE RH	1.0	380.00	0	380.00
81	FRONT KNUCKLE ARM LH	1.0	557.00	0	557.00
82	FRONT KNUCKLE ARM RH <i>nn</i>	1.0	557.00	0	557.00
83	FRONT SHOCK ABSORBER RH <i>nn</i>	1.0	560.30	0	560.30
84	FRONT SHOCK ABSORBER LH	1.0	560.30	0	560.30
85	FRONT ABSORBER STOPPER RH <i>nn</i>	1.0	46.30	0	46.30
86	FRONT ABSORBER STOPPER LH <i>nn</i>	1.0	46.30	0	46.30
87	FRONT WHEEL BEARING LH	1.0	287.50	0	287.50
88	FRONT WHEEL BEARING RH <i>nn</i>	1.0	287.50	0	287.50
89	ENGINE CROSSMEMBER	1.0	612.80	0	612.80
90	FRONT DRIVE SHAFT RH	1.0	1,058.20	0	1,058.20
91	FRONT DRIVE SHAFT LH	1.0	1,058.20	0	1,058.20
92	STEERING RACK & PINION	1.0	1,470.80	0	1,470.80
93	FRONT NUMBER PLATE <i>nn</i>	1.0	30.00	0	30.00
94	FRONT NUMBER PLATE HOLDER <i>nn</i>	1.0	30.00	0	30.00
95	WINDSCREEN SEALANT <i>nn</i>	2.0	24.00	0	48.00
96	FRONT DOOR RH - REPAIR <i>nn</i>	1.0			
97	FRONT SEAT LH - REPAIR <i>nn</i>	1.0			
Special Nett Price - Parts Sub Total					15,960.70
Parts Total					41,939.48
98	LABOUR TO REMOVE & REFIT NECESSARY PARTS	1.0	4,500.00	0	4,500.00

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE

* N = Item not subjected to GST

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E
BEDOK NORTH AVE 4,
#01-2008/10/12 SINGAPORE 489977
TEL : 6441 5655 FAX : 6441 5355/6243 8121
R.O.C No : 200104141D GST Reg. No. 20-0104141-D

TO : 96652076

GANGA PARAMESH D/O ARIKRISHNASAMY
BLK 533 BUKIT PANJANG RING ROAD
13-801
SINGAPORE 670533
TEL : FAX :
PH : 96652076
ATTN :

ESTIMATE BILL

Number : EB00005910
Date : 17/03/2022
Case No : AD00012515
Vehicle No : SKV6491E
Chassis : SJNFEAJ11U1468649
Year of Mfr : 2015
Policy No :
Model : NISSAN QASHQAI 1.2
DIG-T CVT ABS 2WD

Term:

Sn	DESCRIPTION	QTY	U PRICE	SDR DISC	AMOUNT
99	SPRAY PAINT ON THE AFFECTED AREAS	1.0	2,800.00	0	2,800.00
100	ANTI-RUST COATING	1.0	800.00	0	800.00
101	WIRING	1.0	120.00	0	120.00
102	TO REMOVE & REFIT WINDSCREEN	1.0	180.00	0	180.00
103	TO REMOVE & REFIT CUSHION & UPHOSTERY	1.0	500.00	0	500.00
104	TO REMOVE & REFIT UNDERCARRIAGE	1.0	800.00	0	800.00
105	TO REMOVE & REFIT DASHBOARD	1.0	600.00	0	600.00
106	TO REMOVE & REFIT ROOF	1.0	500.00	0	500.00
107	FOUR WHEEL ALIGNMENT	1.0	180.00	0	180.00
Labour 1 Sub Total					10,980.00
LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:					
SINGAPORE DOLLARS : FIFTY-SIX THOUSAND SIX HUNDRED TWENTY-THREE AND CENTS EIGHTY-FOUR ONLY			Less Excess		0.00
			SUBTOTAL		52,919.48
			GST 7.00%		3,704.36
			TOTAL		56,623.84

Date of accident : 12/03/2022 03:00 PM. Place : YUK TONG AVENUE

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

28887-15

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE