

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT					
	NTUC INCOME IN:	SURANCE CO-OPERATIVE LTD	Ref:	CS/INC22002500/Rvy3m4	
	73 BRAS BASAH F #05-01 NTUC TRA 189556	ROAD DE UNION HOUSESINGAPORE	Date	: 07/06/2022	
	ATTN: CHRYLLIS	QUAH	Code	e: INC	
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SLE 5590L	Veh. Inspected	SMJ 8540Z	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	MT/1164249-002	Excess (\$)	0.00	
	Assign From	THERESA VIMALA	Assign Date	16/03/2022	
2.	2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA NOAH HYBRID 7-S 1.8X	c.c	1797	
	Engine No.	HIDDEN	Year of Reg.	2019	
	Chassis No.	ZWR800362975	Colour	WHITE	
	Odometer	225770 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	FAIR			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	195/65 R15	WEST LAKE	6 mm	
	L/H Front Tyre	195/65 R15	WEST LAKE	6 mm	
	R/H Rear Tyre	195/65 R15	WEST LAKE	6 mm	
	L/H Rear Tyre	195/65 R15	WEST LAKE	6 mm	
4. Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION.				
	DAMAGES SEE DI	ETAILS.			
5.	General Information				
	Accident Date	04/03/2022	Inspect Date / Time	17/03/2022 (05:05 PM)	
	Survey held at	MY CAR CONSULTANT PTE LT	D		
		60 JALAN LAM HUAT #05-21 CARROS CENTRE SINGAPORE 737869			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days				