



MY CAR CONSULTANT PTE LTD

Reg no.: 2016058782

Address: 60 JALAN LAM HUAT, CARROS CENTRE #05-68 S737896

HP: 98888885

3396.71

96.00

1630.00

4516.71

Estimation

Date:

16/3/2022

Vehicle:

SMJ8540Z

Make / Model:

TOYOTA NOAH

INSURANCE

NTUC

@1710

Resy before print

Rasul
Hp 96010068

4 days

P/P

17/03/22

No.	Description	Unit	Unit Price	Amount
Parts Replacement:				
1	FRONT BUMPER <i>scu</i>	1	\$ 1,985.00	\$ 1,985.00
2	FRONT BUMPER BRACKET LH <i>X n</i>	1	\$ 144.00	\$ 144.00
3	FRONT BUMPER SIDE RETAINER LH <i>2 X n</i>	1	\$ 112.00	\$ 112.00
4	FRONT BUMPER SIDE COVER LH <i>X n</i>	1	\$ 159.00	\$ 159.00
5	FRONT GRILLE <i>X n</i>	1	\$ 788.00	\$ 788.00
6	HEADLAMP LH <i>2 cm</i>	1	\$ 3,985.00	\$ 3,985.00
7	HEADLAMP GARNISH LH <i>X n</i>	1	\$ 112.00	\$ 112.00
8	FRONT HEADLAMP LOWER BRACKET <i>X n</i>	1	\$ 122.00	\$ 122.00
9	FRONT FENDER LH <i>repair x R</i>	1	\$ 896.00	\$ 896.00
10	FRONT FENDER COWLING LH <i>cut</i>	1	\$ 211.00	\$ 211.00
11	FRONT FENDER EMBLEM HYBRID LH <i>u</i>	1	\$ 68.00	\$ 68.00
12	FRONT FENDER QUARTER GLASS MOULDING LH <i>X n</i>	1	\$ 65.00	\$ 65.00
13	SIDE SKIRTING LH <i>repair x</i>	1	\$ 898.00	\$ 898.00
14	FRONT DOOR LH <i>repair x</i>	1	\$ 1,598.00	\$ 1,598.00
15	FRONT DOOR HINGES LH <i>X n</i>	2	\$ 112.00	\$ 224.00
TOTAL PART				\$ 11,367.00
LIST DOWN			25%	\$ 2,841.75
AFTER LIST DOWN				\$ 8,525.25
S/N				
1	FRONT BUMPER CLIPS <i>u</i>	1	\$ 80.00	\$ 80.00
2	FRONT FENDER COWLING CLIPS <i>u</i>	1	\$ 50.00	\$ 50.00
3	SIDE SKIRTING CLIPS SET <i>u</i>	1	\$ 50.00	\$ 50.00
4	FRONT WHEEL SPORTS RIM LH <i>X n</i>	1	\$ 800.00	\$ 800.00
TOTAL SPECIAL NETT				\$ 130.00
Labour to:				
1	RESET TROUBLE CODE <i>X n</i>	1	\$ 300.00	\$ 300.00
2	TO CHECK ELECTRICAL WIRING	1	\$ 200.00	\$ 200.00
3	CONDUCT WHEEL ALIGNMENT <i>x n</i>	1	\$ 120.00	\$ 120.00
4	REMOVE AND REFIT FRONT UNDERCARRIAGE LH <i>X n</i>	1	\$ 300.00	\$ 300.00
5	REALIGN HEADLAMP <i>X n</i>	1	\$ 80.00	\$ 80.00
6	PANEL BEATING ON AFFECTED AREA	1	\$ 800.00	\$ 800.00
7	SPRAY ON AFFECTED AREA	1	\$ 800.00	\$ 800.00
				\$ 2,600.00
Parts Replacement Amount				\$ 8,655.25
Total Amount for Labour				\$ 2,600.00
Total Amount				\$ 11,255.25

Acknowledged by Repairer

Signature:

Date:

1288.20

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

3001.75

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

4528.95

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

25%

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

3396.71

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

30

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

90

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

1030

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X