

KIM CHWEE AUTO PTE LTD

PAGE 1 OF 3

1 Kaki Bukit Ave 6 #01-48 Autobay**Singapore 417883****Tel No: 67452063 / 67467158 Fax No: 67458520****Tax Reg No: 199802379-R**

Estimate : 22875

Date : 16.03.2022

Vehicle Num : SKT 8988L

Make/Model : MERCEDEZ BENZ R300

Chassis/Engine no :

Accident Date : 15.03.2022

Claim No : 0322-22875

Reference :

Policy No :

Qty	Particular	Amount S\$
<u>List Item :</u>		
1 pc	Front bumper logo	\$ 46.00
1 pc	Front bumper	\$ 2,450.00
1 pc	Front bumper air grille	\$ 182.00
1 pc	Front fog lamp cover RH	\$ 56.00
2 pc	Front bumper corner sensor seal RH @ 7.00	\$ 14.00
2 pc	Front bumper corner parking sensor RH @ 235.00	\$ 470.00
1 pc	Front bumper side retainer RH	\$ 15.00
1 pc	Front bumper top seal	\$ 84.00
1 pc	Front bumper sponge	\$ 155.00
1 pc	Head lamp assy RH	\$ 3,640.00
1 pc	Front fender RH	\$ 1,425.00
1 pc	Front fender inner shield RH no1	\$ 119.00
1 pc	Front fender inner shield RH no2	\$ 189.00
1 pc	Rocker panel garnish (side skirt) RH	\$ 609.00
10 pc	Rocket panel clip @ 5.20	\$ 52.00
1 pc	Front door glass RH	\$ 630.00
1 pc	Front door RH	\$ 2,520.00
1 pc	Front door rubber RH	\$ 416.00
1 pc	Front door frame top seal RH	\$ 97.00
1 pc	Front door bottom seal RH	\$ 23.00
1 pc	Front door glass moulding RH (outer)	\$ 195.00
1 pc	Front door glass channel RH	\$ 145.00
1 pc	Front door wing mirror assy RH	\$ 2,485.00
1 pc	Front door wing mirror glass RH	\$ 585.00
1 pc	Front door wing mirror cover RH	\$ 225.00
1 pc	Front door top chrome moulding	\$ 97.00
1 pc	Front door outer handle RH	\$ 375.00
1 pc	Front door protector RH	\$ 256.00
1 pc	Front door inner lock RH	\$ 1,425.00
1 pc	Front door board RH	\$ 985.00
1 pc	Front door rubber RH	\$ 315.00
1 pc	Rear door rubber seal (behind front door)	\$ 71.50
1 pc	Rear door glass channel RH	\$ 145.00
1 pc	Rear door glass outer moulding	\$ 195.00
1 pc	Rear door frame top chrome moulding RH	\$ 375.00
1 pc	Rear door quarter glass rubber RH	\$ 115.00
1 pc	Rear door quarter glass pillar RH	\$ 75.00
1 pc	Rear door outer handle RH	\$ 375.00
		\$ 21,631.50

KIM CHWEE AUTO PTE LTD

PAGE 2 OF 3

1 Kaki Bukit Ave 6 #01-48 Autobay**Singapore 417883****Tel No: 67452063 / 67467158 Fax No: 67458520****Tax Reg No: 199802379-R**

Estimate : 22875

Date : 16.03.2022

Vehicle Num : SKT 8988L

Make/Model : MERCEDEZ BENZ R300

Chassis/Engine no :

Accident Date : 15.03.2022

Claim No : 0322-22875

Reference :

Policy No :

Qty	Particular	Amount S\$
		\$ 21,631.50
<u>List Item :</u>		
1 pc	Rear door rubber RH	\$ 315.00
1 pc	Rear door protector RH	\$ 256.00
1 pc	Rear bumper	\$ 2,550.00
1 pc	Rear bumper diffuser	\$ 465.00
1 pc	Rear bumper side retainer	\$ 48.00
1 pc	Rear bumper reflector RH	\$ 23.00
1 pc	Rear bumper reversing sensor RH	\$ 235.00
1 pc	Rear fender RH	\$ 8,136.00
1 pc	Rear fender quarter glass assy RH	\$ 665.00
1 pc	Front lower arm RH	\$ 685.00
1 pc	Front shock absorber RH	\$ 2,548.00
1 pc	Front knuckle arm RH	\$ 780.00
1 pc	Front top arm RH	\$ 395.00
1 pc	Front wheel bearing with hub	\$ 525.00
1 pc	Rear lower arm RH	\$ 645.00
1 pc	Rear knuckle arm RH	\$ 695.00
1 pc	Rear wheel bearing with hub RH	\$ 525.00
1 pc	Rear shock absorber RH	\$ 2,548.00
1 pc	Rear control arm RH	\$ 685.00
1 pc	Rear top arm RH	\$ 395.00
List Item Total :		\$ 44,750.50
Discount 10 % :		\$ 4,475.05
		\$ 40,275.45

Special Nett Item :

2 pc	Tyre @ 750.00	\$ 1,500.00
	Apply front door glass solar film	\$ 180.00
1 set	Rear fender quarter glass sealant	\$ 80.00
1 pc	Front sport rim RH	\$ 1,800.00
1 pc	Rear sport rim RH	\$ 1,800.00
Special Nett Item :		\$ 5,360.00

KIM CHWEE AUTO PTE LTD

PAGE 3 OF 3

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax Reg No: 199802379-R

Estimate : 22875

Date : 16.03.2022

Vehicle Num : SKT 8988L

Make/Model : MERCEDEZ BENZ R300

Chassis/Engine no :

Accident Date : 15.03.2022

Claim No : 0322-22875

Reference :

Policy No :

Qty	Particular	Amount S\$
<u>Labour Charge :</u>		
	To check wiring & diagnostic fault core	\$ 200.00
	Remove & refix rear fender quarter glass	\$ 150.00
	Remove & refix cushion seat	\$ 250.00
	Labour charge to remove & refix & renew parts cut & welding etc	\$ 2,200.00
	Remove & refix & renew front & rear under carriage, suspension etc	\$ 1,200.00
	Check 4 wheel alignment	\$ 150.00
	To respray painting	\$ 2,200.00
	Labour Charge Total :	\$ 6,350.00

E & O . E

Total Amount : \$ 51,985.45

KIM CHWEE AUTO PTE LTD