

Your Ref : SNM22D201844/C01/TANKW

Date: 31st May 2022

Our Ref : CS/CTI22002512/Ety3e2

M/s China Taiping Insurance (S) Pte Ltd

3 Anson Road #16-00

Springleaf Tower

Singapore 079909

(The Motor Claims Department)

Dear Sir/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE XD 9902H
ACCIDENT ON 16/03/2022**

Instruction was received to inspect the vehicle Reg. No. XD 9902H. The inspection was conducted on 18/03/2022 at the premises of M/s Goldbell Engineering Pte Ltd, 10 Tuas Ave 18, Singapore 638894.

The following information was recorded: -

Registration Number	: XD 9902H
Make & Model	: Iveco Stralis AT440S46T/P (Auto) Euro V 60T
Year of Registration	: 2014
Engine Capacity	: 7790 cc
Body Colour	: White
Chassis Number	: WJMM1VTH4DC264296
Speedometer Reading	: Not Available

The vehicle sustained damages at the front portion. The Estimated repair cost of such vehicle is S\$45,000.00 (Sin Dollars: Forty-Five Thousand only.) (Details see photographs enclosed).

In view of this repair work, we are of the opinion that it would be **uneconomical** to proceed with the repairs and recommend it's to be written off as **"Total Loss"**.

(a) If the vehicle to be "Total Loss"

Market Value

S\$ 40,000.00(est)

Less: LTA Reimbursement Value (RV)

(S\$ 6,562.00)

S\$ 33,438.00

Less: Excess

(S\$ 3,000.00)

Nett Liability

S\$ 30,438.00

(b) If the vehicle to be "Repair"

Repair Cost

S\$ 45,000.00

Less: Excess

(S\$ 3,000.00)

Nett Liability

S\$ 42,000.00

(a) – (b) =

(S\$ 11,562.00)

=====

The amount of estimated saving of S\$11,562.00 if the vehicle to be written off as **"Total Loss"** instead of to be repair.

Vehicle Inspected By:



CHEN TSUE YEE
Automotive Assessor



K.K.LAU
MSc(Eng M), B Eng(Hons), Peng(UK),
MASME(USA), B Bus(Aust), MBA(UK),
IEng(UK), MIIE(mech), MinstAEA, MFIEA,
MIRTE, MIMI, MSAE, MCIARD, AM, NIJAAR(USA),
AM CATARI(CAN), M.MATA(USA), M.MdATA(USA),
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.