

Team AutoPro Pte Ltd 160 Sin Ming Dr, #02-12 Sin Ming AutoCity Singapore 575722

Tel: 8269-9999 Email: estimate.tap@gmail.com / teamautopl@gmail.com

SJE :

Date of Survey :

Date of ReSurvey:

Contacts :

After-Paint:

Vehicle Nos : SLF 3820 G

Model : Toyota Wish

Year : 2008

Chassis No : JTDER12W403000651

*** AGREED Cost Of Repair and Repair Day/s with SJE ***

Amount:

Working Day:

2008

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$
1	Tailgate	1	\$ 1,210.15	\$ ✓1,210.15
2	Tailgate logo	1	\$ 114.20	\$ 47.90 114.20
3	Tailgate inner trim board	1	\$ 585.20	\$ 251.50 585.20
4	Tailgate weatherstrip	1	\$ 214.60	\$ ✓214.60
5	Tailgate inner lock	1	\$ 401.50	\$ ✓401.50
6	Tailgate inner lock sticker	1	\$ 62.30	\$ 62.30
7	Tailgate outer chrome garnish	1	\$ 363.90	\$ ✓363.90
8	Tailgate windscreen moulding	1	\$ 241.00	\$ 230.00 241.00
9	Rear bumper	1	\$ 827.60	\$ 570.80 827.60
10	Rear bumper reflector	2	\$ 151.80	\$ 303.60
11	Rear bumper support bracket	2	\$ 137.40	\$ 274.80
12	Rear end panel	1	\$ 748.60	\$ 748.60
13	Rear end panel top garnish	1	\$ 321.20	\$ 121.00 321.20
14	Rear floor panel	1	\$ 828.30	\$ 828.30
15	Rear tool tray garnish	1	\$ 388.70	\$ 388.70
16	Rear tool tray board	1	\$ 482.60	\$ 482.60
17	Rear Spare tyre bracket	1	\$ 385.20	\$ 385.20
18	Rear fender inner trim board	2	\$ 694.60	\$ 1,389.20
19	Taillamp	2	\$ 471.80 658.30	\$ 943.60 1,316.60

Parts Sub Total : \$4354.95 10,459.25

Discount : \$1088.74 2,614.81

PARTS TOTAL : \$ 7,844.44

3266.21

DDV ✓

NEC ✓

BR ✓

TN ✓

JM ✓

NDX

BR ✓

NEC ✓

BR ✓

NDX

NSX

DDX R

BR ✓

NDX

BR ✓

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$	
1	Sundries	1	\$ 80.00	\$ 80.00	NNX
2	Tailgate sealant	1	\$ 100.00	\$ 30.00 100.00	} NEC ✓
3	Tailgate inner trim board clips	1	\$ 50.00	\$ 30.00 50.00	
4	Tailgate windscreen sealant	1	\$ 120.00	\$ 60.00 120.00	
5	Tailgate windscreen inner seal	1	\$ 60.00	\$ 60.00	NNX
6	Tailgate windscreen primer & cleaner	1	\$ 80.00	\$ 80.00	NNX
7	Tailgate outer chrome garnish clips	1	\$ 50.00	\$ 20.00 50.00	} NEC ✓
8	Rear bumper clips	1	\$ 50.00	\$ 30.00 50.00	
9	Rear bumper lower lip	1	\$ 750.00	\$ 750.00	NDX
10	Rear bumper side retainer	2	\$ 114.40	\$ 228.80	NECV
11	Rear bumper reverse sensor	2	\$ 250.00	\$ 200.00 500.00	SCV
12	Rear end panel sealant	1	\$ 100.00	\$ 100.00	NNX
13	Rear end panel top garnish clips	1	\$ 50.00	\$ 30.00 50.00	NECV
14	Rear floor panel sealant	1	\$ 100.00	\$ 100.00	NNX
15	Taillamp clips	2	\$ 50.00	\$ 100.00	NNX
16	Taillamp seal	2	\$ 60.00	\$ 40.00 120.00	NECV
17	Rear number plate w/casing	1	\$ 80.00	\$ 80.00	} ND ✓
18	Rear reverse camera	1	\$ 480.00	\$ 480.00	
SPECIAL NETT TOTAL :				\$ 440.00 3,098.80	

Nos.	LABOUR	S\$	
1	R&R tailgate componnet	\$ 80.00 150.00	} NNX
2	R&R tailgate windscreen	\$ 120.00 250.00	
3	R&R rear bumper reverse sensor	\$ 60.00 100.00	
4	Check wiring	\$ 100.00	
5	Upholstery	\$ 300.00	} NNX
6	Panel beating	\$ 1000.00 1,600.00	
7	Rust proofing	\$ 200.00	
8	Spray painting	\$ 800.00 1,600.00	
LABOUR TOTAL :		\$ 2060.00 4,300.00	

Survey + Resurvey
18/3/2022
Ramin M
15 Hrs

Lamp sum repair
Repair days 7

PARTS TOTAL : \$ 7,844.44
SPECIAL NETT TOTAL : \$ 3,098.80
LABOUR TOTAL : \$ 4,300.00

GRAND TOTAL : \$ 15,243.24

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

LS 4600/2

Tamin M

15/4/2022

PARTS 3266.21
SN 440.00
Labour 2060.00
5766.21
@ 200% 1153.24
4612.97