

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CC4/ ASM22002522/Ueo3

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

STB3141C

at Workshop m/s

focus

of

Insured:

SHC 8732H

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

85500

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

3

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

4606

Vehicle: IN / OUT

Date:

Person Contacted:

LTA 82974

Veh No:

STB3141C

Yr Regn:

08/01/08

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Corolla Axio

c.c

1496

Colour

Silver

A/C:

Insured / Std / NI / NA

Sp. Reading

278525

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

NTE 1416061457

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil S/Rim / STD A/Rim or

Tyre Size:

F:

195/60R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Firestone

Front

6

mm

Rear

6

mm

R/Bal.

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

12/3/22

D.O.I.

21/3/22

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S fit.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

counted 30-11-2022 & 1 further.

net 82526

24/3/22 L/S \$1500 in formal m/w way

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

) \$ + RS \$ SI

☐

: Interview (\$

) Photos

☐

: Tech. Invs (\$

) Others

☐

: Weekend (\$

)

Report Format :

Lump Sum / I.B.I: (\$

)

TOTAL

FOCUS AUTO PTE LTD

NO. 1 KAKI BUKIT AVENUE 6 #02-48/50
 AUTOBAY @ KAKI BUKIT SINGAPORE 417883

TEL: 6886 9097 FAX: 6844 4625 Email: claims@focusauto.com.sg

*Asker***AXA INSURANCE PTE LTD**

9 North Buona Vista Drive
 #18-01/06
 Tower 1
 The Metropolis
 Singapore 138588

Not Approved
21/3/22
2/5 @ 1500
3 days
Whisper Attorney

Estimate No : E22030071
 Date : 17/03/2022
 Veh Reg No : **SJB 3141 C**
 Make / Model : **TOYOTA COROLLA AXIO 1.5X A**
 Chassis No. : NZE1416061457
 Engine No. : 1NZC843443
 Reg. Date : 08/01/2008

ATTN : Motor Claim Department
 Your Ref No. : **SHC 8732 H**
 Claim Type : **THIRD PARTY**
 Accident Date : 12/03/2022

Estimate Repair Cost to Vehicle No : SJB 3141 C

	Quantity	Unit	Price	Amount
<u>LIST PRICE</u>			<u>SS</u>	<u>SS</u>
1 Front Fender - LH <i>Boddy</i>	1	PCS	589.60	589.60 ✓
2 Front Fender Dust Cover - LH <i>su</i>	1	PCS	102.20	102.20 X
3 Front Fender Dust Cover Clip - LH <i>17</i>	6	PCS	5.50	33.00 X
4 Front Door - LH <i>20/247</i>	1	PCS	986.40	986.40 ✓
5 Front Door Rubber - LH <i>17</i>	1	PCS	289.40	289.40 X
6 Front Door Hinge Lower - LH <i>su</i>	1	PCS	56.20	56.20 X
TOTAL A :				2,056.80
DISCOUNT 25% :				514.20
SUB TOTAL :				1,542.60

LABOUR CHARGES

	<u>SS</u>	<u>SS</u>
1 Panel Beating	<i>280</i>	550.00
2 To Remove & Refix Door Accessory	<i>60</i>	80.00
3 To Spray Painting	<i>400</i>	620.00
TOTAL B :		1,250.00
GRAND TOTAL :		2,792.60

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:

FOR FOCUS AUTO PTE LTD

Jenny Koh
Claims Executive
HP: 8139 9800
 AUTHORISE SIGNATURE

P-1576
252
P-1182
L 740
1922
1530