

ASS. REC. BY: Pasul

REF: CC4/GRB 2200 2523/Rga3

389K

**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD  TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: YQ 4802R

at Workshop m/s ARK OTO

of IO AMK Autopoint #104-01

Insured: 111

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 87K

IDAC Accident Rport: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: YQ 4802R Yr Regn: 2021 / NOV

Type: M.Car / M.Cycle / Bus / Van /  Lorry / Taxi / Prime Mover /

Truck / Trailer or \_\_\_\_\_

Make: TOYOTA DYNA 150SMT c.c. 275K

Colour: GREY A/C: Insured / Std / NI / NA

Sp. Reading: 23890 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: JHHA GV 46XOK001136

Gen. Cond: Good /  Fair / Poor / Burnt

Steering:  Inorder / Jammed / Leaked / Burnt or

Brake:  Inorder / Jammed / Leaked / Burnt or

Modi:  NIP / S/Rim / STD A/Rim or

Tyre Size: F: 175/75R15

R: 145/80R13

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or \_\_\_\_\_

Front R/Bal. 7 mm

Rear R/Bal. 8/5 mm

L/Bal. 7 mm

L/Bal. 8/5 mm

D.O.A. 12/03/22

D.O.I. 18/03/22

Survey held at ART OTO

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Frt

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>REPAIR LIMIT - 55K</u>

Date/Time, File Pass to?  : Preli. Report

: Final Report

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

1) Date/Time, File Return to?

2) \_\_\_\_\_

Report Format: \_\_\_\_\_

Lump Sum / I.B.F. (\$) \_\_\_\_\_

Add Fee:  : Site Insp (\$ \_\_\_\_\_)

: Interview (\$ \_\_\_\_\_)

: Tech. Invs (\$ \_\_\_\_\_)

: Weekend (\$ \_\_\_\_\_)

Survey Fee:	_____
Transportation:	_____
S + RS. SI	_____
Photos	_____
Others	_____
TOTAL	_____

To surveyor

# ARK OTO

Blk 10 Ang Mo Kio Industrial Park 2A AMK Autopoint #04-01  
Singapore 568047 HP 91004390/HP 91254449 Fax 64841482

EMAIL : arkotoamk@gmail.com

M/s	India International Insurance Pte Ltd	DATE	18.03.2022
	64 Cecil Street #04,05 IOB Building	CAR NO	YQ 4802 R
	Singapore 049711	MAKE	Toyota Dyna

ESTIMATE COST OF REPAIR FOR THE ABOVE MENTIONED VEHICLE.  
YOUR INSURED : SND 1072 Z

Pc	Pcs	JHHAGV46X0K001136	UNIT PRICE	AMOUNT
1	DC	Front right side air cleaner box <i>cm</i>		\$689.90
1	DC	Front right side air cleaner box holder <i>X</i>		\$283.90
1	DC	Front right side fender cowling <i>su</i>		\$169.90
1	DC	Front right side fender cowling mudflap <i>X</i>		\$69.90
1	pc	Front right side corner bracket frame (triangle) <i>repair</i>		\$115.39
1	pc	Diesel tank <i>repair 51</i>		\$1,189.90
1	pc	Diesel tank bracket holder <i>X</i>		\$299.60
1	pc	Right side protector bar <i>bt</i>		\$456.90
2	pcs	Right side protector bar corner garnish <i>su</i>	\$56.90	\$113.80
		To spray anti-rust coating on new & affected panels.		\$200.00 <i>X</i>
		To straighten, repair, realign on affected area and replace the above damaged parts.		\$900.00
		To respray painting on affected area.		\$600.00
		To dismantle & replace diesel tank.		\$300.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

*Repair*  
*HP 910010068100*  
*3 days*  
*4/8*  
*18/03/22 @ 1550*  
*Resy after repair*

Susan Lim  
**ARK OTO.**

> Back to OneMotoring

### Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Company
Owner ID:	389K
Vehicle No.:	YQ4802R
Vehicle to be Exported:	No
Intended Deregistration Date:	20 Mar 2022
Vehicle Make:	TOYOTA
Vehicle Model:	DYNA 150 5MT
Primary Colour:	Silver
Manufacturing Year:	2021
Engine No.:	1GD8807307
Chassis No.:	JHHAGV46XDK001136
Maximum Power Output:	-
Open Market Value:	\$31,609.00
Original Registration Date:	08 Nov 2021
First Registration Date:	08 Nov 2021
Transfer Count:	0
Actual ARF Paid:	\$1,581.00
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
COE Expiry Date:	07 Nov 2031
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$32,971.00
COE Rebate Amount:	\$31,758.00
Total Rebate Amount:	\$31,758.00

The information contained herein is correct as at 20 Mar 2022

OK

# Toyota Dyna 150 2.8M

Overview

Financial

Accessories

Similar

Research

Photos

Map



EZY-1 PTE LTD | EZY-1 LEASING | EZY-1 SERVICES

<b>Price</b>	<b>\$87,800</b>	<b>Lifespan</b>	29-Nov-2041
<b>Depreciation</b>	\$9,050 /yr View models with similar depre	<b>Reg Date</b>	30-Nov-2021 (9yrs 8mths 9days COE left)
<b>Mileage</b>	N.A.	<b>Manufactured</b>	2021
<b>Road Tax</b>	N.A.	<b>Transmission</b>	Manual
<b>Dereg Value</b>	\$31,938 as of today (change)	<b>Fuel Type</b>	Diesel
<b>COE</b>	\$32,921	<b>OMV</b>	\$31,609
<b>Engine Cap</b>	2,755 cc	<b>ARF</b>	\$1,581
<b>Curb Weight</b>	1,780 kg	<b>No. of Owners</b>	1