

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/HLA22002526/KVY3N2**Date:** 12/05/2022REFERENCE

Handling Insurer:	HL Assurance Pte Ltd	Policy No:	MP313640
Claimant Vehicle No :	SLL20L	Insured Vehicle No :	SLE5309J
Date of Loss:	16/03/2022	Nature of Claim:	TP
		Claim No:	MPC03232/JG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLL20L		
Make & Model:	MERCEDES-BENZ AMG A45 S, 2.0 4MATIC PLUS HATCHBACK (A)	Engine No:	17898060013638
Reg. Date:	28/04/2017 (Man. Year: 2017)	Chassis No:	WMX1904802A013563
Colour:	Metallic Pearl White	Odometer:	22229 km
Engine Capacity:	3982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	275/35ZR19	Rear Tyre Size:	325/30ZR20
Front Left Side:	Pirelli 8 mm	Rear Left Side:	Pirelli 8 mm
Front Right Side:	Pirelli 8 mm	Rear Right Side:	Pirelli 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	26,613.85	17,594.04	9,019.81	33.89
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,720.00	610.00	1,110.00	64.53
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	28,333.85	18,204.04	10,129.81	35.75
Approved Total (Overridden) (S\$)		14,550.00		
(S\$)	28,333.85	14,550.00	13,783.85	48.65
+ GST 7.00/7.00% (S\$)	1,983.37	1,018.50	964.87	48.65
Nett Amount (S\$)	30,317.22	15,568.50	14,748.72	48.65

INSPECTION

Date of Assignment:	18/03/2022	
Date Inspected:	18/03/2022 Inspected At:	Optima Werkz Pte Ltd (HQ) 10 Ang Mo Kio Industrial Park 2A, #01-05 AMK Autopoint Singapore 568047
Estimated Period of Repair:	4.0 days	

Adjuster: KENNETH KONG**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 12 May 2022)

Parts: 143 MERCEDES-BENZ AMG A45 S 2.0 4MATIC PLUS HATCHBACK (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLL20L)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR KNUCKLE RH	Bent	2,138.00 FL	*1,786.56 FL
2	1		*REAR WHEEL BEARING RH	Necessary	562.50 FL	*409.87 FL
3	1		*MOUNTING CONSOLE RH	Bent	405.00 FL	*206.20 FL
4	1		*REAR UPPER ARM RH	Distorted	1,080.00 FL	*820.49 FL
5	1		*REAR LOWER ARM RH	Bent	1,935.00 FL	*1,679.17 FL
6	1		*REAR CONTROL TRAIL ARM RH	Distorted	482.00 FL	*482.00 FL
7	1		*REAR STEERING GEAR RH	Jammed	8,325.00 FL	*6,086.51 FL
8	1		*MOUNTING RH	Cracked	675.00 FL	*528.23 FL
9	1		*REAR DRIVE SHAFT RH	Repair	4,050.00 FL	*- FL
10	1		*REAR ABSORBER RH	Bent	5,412.00 FL	*5,325.55 FL
11	1		*REAR SPORT RIM RH	Dented	4,162.00 FL	*2,224.35 FL
12	1		*REAR BUMPER (NPA)	Repair	0.00 FL	*- FL
13	1		*FRONT FENDER INNER SHIELD CLIPS RH	Not Necessary	40.00 FS	*- FS
14	1		*FRONT DOOR INNER TRIM BOARD CLIPS RH	Not Necessary	50.00 FS	*- FS
15	1		*REAR DOOR INNER TRIM BOARD CLIPS RH	Not Necessary	50.00 FS	*- FS
16	1		*REAR WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
17	1		*REAR BUMPER CLIPS	Not Necessary	50.00 FS	*- FS
18	1		*REAR FENDER INNER SHIELD CLIPS RH	Not Necessary	40.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	29,536.50	19,548.93
- List Item Discount on L Items 10.00/10.00% (\$)	2,922.65	1,954.89
Total Parts (\$)	26,613.85	17,594.04

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REMOVE,REPLACE,REFIX,REPAIR & READJUST ACCIDENT AREA	New	400.00	0.00
2	LABOUR CHARGES TO REMOVE & REPLACE REAR UNDERCARRIAGE	New	450.00	250.00
3	LABOUR CHARGES TO SUPPLY PAINT & FURNISHING MATERIALS	New	400.00	280.00
4	TO WHEEL ALIGNMENT & BALANCING	New	120.00	80.00
5	TO TUFF KOTE & UNDERSEAL MATERIALS	New	150.00	0.00
6	TO CHECK WIRING & ELECTRICAL SYSTEM & ETC	New	200.00	0.00
Gross Labour Cost (S\$)			1,720.00	610.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >