



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
BLUWEL AUTOMOTIVE SERVICE PTE LTD BLK 1 KAKI BUKIT AVE 6 #01-28/53/55/56 (MAIN OFFICE)SINGAPORE 417883		Ref: CS/TP22002528/Uty3e2 Date: 28/03/2022 Code: TP149	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	Veh. Inspected	SMF 4774M	
Policy No.	Coverage (\$)	0.00	
Claim No.	Excess (\$)	0.00	
Assign From	Assign Date	18/03/2022	
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model	VOLKSWAGEN GOLF (A)	c.c	1395
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	WVWZZZAUZJW140555	Colour	WHITE
Odometer	29245 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre	225/45 R17	PIRELLI	7 mm
L/H Front Tyre	225/45 R17	PIRELLI	7 mm
R/H Rear Tyre	225/45 R17	PIRELLI	7 mm
L/H Rear Tyre	225/45 R17	PIRELLI	7 mm
<b>4. Description of Damages</b>			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>			
Accident Date	15/03/2022	Inspection Date	18/03/2022
Survey held at	BLUWEL AUTOMOTIVE SERVICE PL BLK 1 KAKI BUKIT AVE 6 #01-28/53/55/56 (MAIN OFFICE) SINGAPORE 417883		
<b>5a. Remarks</b>			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	