

HD Perfect Autowork Pte Ltd

Company Reg No: 202136904Z

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778

E-mail: hdperfectautowork@gmail.com



HD PERFECT
AUTOWORK PTE LTD

DATE : 21.02.2022

TO : AXA MOTOR CLAIMS DEPTS
VEHICLE NO : SLB5485Z
MODEL : HONDA VEZEL
DATE OF ACCIDENT : 16.03.2022
TIME OF ACCIDENT : 10:35HRS

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	TAILGATE	1	\$ 1,420.00	\$ 1,420.00
2	TAILGATE NUMBER PLATE LAMP	2	\$ 85.00	\$ 170.00
3	TAILGATE OUTER SWITCH BUTTON	1	\$ 187.00	\$ 187.00
4	TAILGATE LOCK CONNECTOR	1	\$ 379.00	\$ 379.00
5	TAILGATE LOGO	1	\$ 65.00	\$ 65.00
6	TAILGATE EMBLEM 'VEZEL'	1	\$ 68.00	\$ 68.00
7	TAILGATE OUTER GARNISH	1	\$ 220.00	\$ 220.00
8	TAILGATE SIDE LAMP	2	\$ 240.00	\$ 480.00
9	TAILGATE INNER HOLDER	1	\$ 52.00	\$ 52.00
10	TAILGATE STOPPER	2	\$ 19.00	\$ 38.00
11	TAILGATE TOP LOCK	1	\$ 180.00	\$ 180.00
12	TAILGATE LOWER LOCK	1	\$ 24.70	\$ 24.70
13	TAILGATE INNER TRIM	1	\$ 398.60	\$ 398.60
14	TAILGATE WEATHER STRIP	1	\$ 168.40	\$ 168.40
15	TAILGATE WINDSCREEN MOULDING (SET)	1	\$ 164.00	\$ 164.00
16	TAIL LAMP	2	\$ 475.00	\$ 950.00
17	REAR BUMPER	1	\$ 865.50	\$ 865.50
18	REAR BUMPER REFLECTOR	2	\$ 151.10	\$ 302.20
19	REAR BUMPER SIDE	2	\$ 230.00	\$ 460.00
20	REAR BUMPER SIDE RETAINER	2	\$ 57.00	\$ 114.00
21	REAR FENDER INNER TRIM	2	\$ 399.10	\$ 798.20
22	REAR FENDER COWLING	2	\$ 150.20	\$ 300.40
23	REAR FENDER ARCED GARNISH	2	\$ 184.70	\$ 369.40
24	BUZZER	1	\$ 109.00	\$ 109.00
25	REAR END PANEL	1	\$ 530.00	\$ 530.00
26	REAR END PANEL TOP GARNISH	1	\$ 146.30	\$ 146.30

TO : **AXA** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SLB5485Z**
 MODEL : HONDA VEZEL
 DATE OF ACCIDENT : 16.03.2022
 TIME OF ACCIDENT : 10:35HRS

27	REAR FLOOR PANEL BOTTOM GARNISH	1	\$ 269.00	\$ 269.00
28	REAR FLOOR PANEL TOP BOARD	1	\$ 300.40	\$ 300.40
29	REAR STORAGE BOX	1	\$ 495.00	\$ 495.00

TOTAL PRICE \$ 10,024.10
 LESS 20% \$ 2,004.82
SUB TOTAL PRICE \$ 8,019.28

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR NUMBER PLATE	1	\$ 80.00	\$ 80.00
2	REAR BUMPER CLIPS (SET)	1	\$ 80.00	\$ 80.00
3	REAR BUMPER DIFFUSER	1	\$ 800.00	\$ 800.00
4	TAIL LAMP CLIP (SET)	1	\$ 60.00	\$ 60.00
5	TAILGATE OUTER GARNISH CLIP (SET)	1	\$ 60.00	\$ 60.00
6	TAILGATE INNER TRIM CLIP (SET)	1	\$ 80.00	\$ 80.00
7	TAILGATE WINDSCREEN SEALANT	1	\$ 80.00	\$ 80.00
8	TAILGATE WINDSCREEN INNER SEAL	1	\$ 60.00	\$ 60.00
9	REAR FENDER INNER TRIM CLIP (SET)	1	\$ 80.00	\$ 80.00
10	REAR FENDER COWLING CLIP (SET)	1	\$ 80.00	\$ 80.00
11	REAR FENDER ARCED GARNISH CLIP (SET)	1	\$ 80.00	\$ 80.00
12	REAR END PANEL TOP GARNISH CLIP (SET)	1	\$ 60.00	\$ 60.00
13	REAR END PANEL INSULATION SEAL	1	\$ 150.00	\$ 150.00
14	REAR FLOOR PANEL BOTTOM GARNISH CLIP (SET)	1	\$ 80.00	\$ 80.00
15	REVERSE CAMERA	1	\$ 550.00	\$ 550.00
16	REVERSE SENSOR (SET)	1	\$ 220.00	\$ 220.00

TOTAL \$ 2,600.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 1,800.00	
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,600.00	
3	TUFF COAT	\$ 250.00	
4	REMOVE AND REFIX CUSHION SEAT/ UPHOLSTRY AND ROOF LINNING TO FACILITATE REPAIR	\$ 350.00	

TO : **AXA** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SLB5485Z**
 MODEL : **HONDA VEZEL**
 DATE OF ACCIDENT : 16.03.2022
 TIME OF ACCIDENT : 10:35HRS

5	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	\$ 80.00	
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	
7	REMOVE AND REFIX VIDEO RECORDER AND DISTANCE SETTING	\$ 80.00	
8	CONDUCT WATER LEAKAGE TEST	\$ 100.00	
9	REMOVE AND REFIX TAILGATE WINDSCREEN	\$ 120.00	
10	TRANSFER TAILGATE MECHANISM	\$ 80.00	
11	REMOVE AND REFIX REAR EXHAUST PIPE	\$ 180.00	
12	MANAGEMENT/CONTROL UNITS,RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	

TOTAL \$ 4,900.00

TOTAL PARTS COST : \$ 10,619.28
 TOTAL LABOUR COST : \$ 4,900.00
 TOTAL REPAIR COST : \$ 15,519.28

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.
 PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
 IRENE
 HP : 8297 9787