

# HD Perfect Autowork Pte Ltd

Company Reg No: 202136904Z



8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit  
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778

E-mail: hdperfectautowork@gmail.com

HD PERFECT  
AUTOWORK PTE LTD

*Xiao Chen.*

DATE : 21.02.2022

TO : **AXA** MOTOR CLAIMS DEPTS  
VEHICLE NO : **SLB5485Z**  
MODEL : **HONDA VEZEL**  
DATE OF ACCIDENT : 16.03.2022  
TIME OF ACCIDENT : 10:35HRS

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

### CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	TAILGATE <i>Distorted</i>	1	\$ 1,420.00	\$ 1,420.00 <i>1100</i>
2	TAILGATE NUMBER PLATE LAMP <i>new</i>	2	\$ 85.00	\$ 170.00 <i>+</i>
3	TAILGATE OUTER SWITCH BUTTON <i>new</i>	1	\$ 187.00	\$ 187.00 <i>+</i>
4	TAILGATE LOCK CONNECTOR <i>new</i>	1	\$ 379.00	\$ 379.00 <i>+</i>
5	TAILGATE LOGO <i>new</i>	1	\$ 65.00	\$ 65.00 <i>+</i>
6	TAILGATE EMBLEM 'VEZEL' <i>new</i>	1	\$ 68.00	\$ 68.00 <i>+</i>
7	TAILGATE OUTER GARNISH <i>new</i>	1	\$ 220.00	\$ 220.00 <i>+</i>
8	TAILGATE SIDE LAMP <i>RH cut</i>	2	\$ 240.00	\$ 480.00 <i>240</i>
9	TAILGATE INNER HOLDER <i>for</i>	1	\$ 52.00	\$ 52.00 <i>+</i>
10	TAILGATE STOPPER <i>for</i>	2	\$ 19.00	\$ 38.00 <i>+</i>
11	TAILGATE TOP LOCK <i>Damaged</i>	1	\$ 180.00	\$ 180.00 <i>-</i>
12	TAILGATE LOWER LOCK <i>new</i>	1	\$ 24.70	\$ 24.70 <i>+</i>
13	TAILGATE INNER TRIM <i>could</i>	1	\$ 398.60	\$ 398.60 <i>298</i>
14	TAILGATE WEATHER STRIP <i>lt</i>	1	\$ 168.40	\$ 168.40 <i>-</i>
15	TAILGATE WINDSCREEN MOULDING (SET) <i>new</i>	1	\$ 164.00	\$ 164.00 <i>-</i>
16	TAIL LAMP <i>RH cut</i>	2	\$ 475.00	\$ 950.00 <i>475</i>
17	REAR BUMPER <i>Deland</i>	1	\$ 865.50	\$ 865.50 <i>765</i>
18	REAR BUMPER REFLECTOR <i>RH could</i>	2	\$ 151.10	\$ 302.20 <i>151.10</i>
19	REAR BUMPER SIDE <i>Ryir</i>	2	\$ 230.00	\$ 460.00 <i>+</i>
20	REAR BUMPER SIDE RETAINER <i>new</i>	2	\$ 57.00	\$ 114.00 <i>-</i>
21	REAR FENDER INNER TRIM <i>RH could</i>	2	\$ 399.10	\$ 798.20 <i>399.10</i>
22	REAR FENDER COWLING <i>new</i>	2	\$ 150.20	\$ 300.40 <i>+</i>
23	REAR FENDER ARCED GARNISH <i>new</i>	2	\$ 184.70	\$ 369.40 <i>+</i>
24	BUZZER <i>new</i>	1	\$ 109.00	\$ 109.00 <i>+</i>
25	REAR END PANEL <i>Dented</i>	1	\$ 530.00	\$ 530.00 <i>+</i>
26	REAR END PANEL TOP GARNISH <i>Deland</i>	1	\$ 146.30	\$ 146.30 <i>+</i>

TO : AXA MOTOR CLAIMS DEPTS  
 VEHICLE NO : SLB5485Z  
 MODEL : HONDA VEZEL  
 DATE OF ACCIDENT : 16.03.2022  
 TIME OF ACCIDENT : 10:35HRS

27	REAR FLOOR PANEL BOTTOM GARNISH <i>MT</i>	1	\$ 269.00	\$ 269.00	<i>+</i>
28	REAR FLOOR PANEL TOP BOARD <i>Delud</i>	1	\$ 300.40	\$ 300.40	<i>✓</i>
29	REAR STORAGE BOX <i>could</i>	1	\$ 495.00	\$ 495.00	<i>-285</i>

*5384.30*  
*4307.44*

TOTAL PRICE \$ 10,024.10  
 LESS 20% \$ 2,004.82  
 SUB TOTAL PRICE \$ 8,019.28

**SPECIAL NETT ITEMS**

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	REAR NUMBER PLATE <i>MT</i>	1	\$ 80.00	\$ 80.00	<i>+</i>
2	REAR BUMPER CLIPS (SET) <i>MT</i>	1	\$ 80.00	\$ 80.00	<i>30</i>
3	REAR BUMPER DIFFUSER <i>MT</i>	1	\$ 800.00	\$ 800.00	<i>+</i>
4	TAIL LAMP CLIP (SET) <i>MT</i>	1	\$ 60.00	\$ 60.00	<i>+</i>
5	TAILGATE OUTER GARNISH CLIP (SET) <i>MT</i>	1	\$ 60.00	\$ 60.00	<i>+</i>
6	TAILGATE INNER TRIM CLIP (SET) <i>MT</i>	1	\$ 80.00	\$ 80.00	<i>30</i>
7	TAILGATE WINDSCREEN SEALANT <i>Green</i>	1	\$ 80.00	\$ 80.00	<i>30</i>
8	TAILGATE WINDSCREEN INNER SEAL	1	\$ 60.00	\$ 60.00	<i>30</i>
9	REAR FENDER INNER TRIM CLIP (SET) <i>MT</i>	1	\$ 80.00	\$ 80.00	<i>30</i>
10	REAR FENDER COWLING CLIP (SET) <i>MT</i>	1	\$ 80.00	\$ 80.00	<i>+</i>
11	REAR FENDER ARCED GARNISH CLIP (SET) <i>MT</i>	1	\$ 80.00	\$ 80.00	<i>+</i>
12	REAR END PANEL TOP GARNISH CLIP (SET) <i>MT</i>	1	\$ 60.00	\$ 60.00	<i>10</i>
13	REAR END PANEL INSULATION SEAL <i>MT</i>	1	\$ 150.00	\$ 150.00	<i>60</i>
14	REAR FLOOR PANEL BOTTOM GARNISH CLIP (SET) <i>MT</i>	1	\$ 80.00	\$ 80.00	<i>+</i>
15	REVERSE CAMERA <i>MT</i>	1	\$ 550.00	\$ 550.00	<i>+</i>
16	REVERSE SENSOR (SET) <i>Dangd</i>	1	\$ 220.00	\$ 220.00	<i>200</i>

*420* TOTAL \$ 2,600.00

**CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)**

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 1,800.00	<i>800</i>
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,600.00	<i>800</i>
3	TUFF COAT	\$ 250.00	<i>60</i>
4	REMOVE AND REFIX CUSHION SEAT/UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR	\$ 350.00	<i>60</i>

TO : **AXA** MOTOR CLAIMS DEPTS  
 VEHICLE NO : **SLB5485Z**  
 MODEL : **HONDA VEZEL**  
 DATE OF ACCIDENT : 16.03.2022  
 TIME OF ACCIDENT : 10:35HRS

5	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	\$ 80.00	50
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	50
7	REMOVE AND REFIX VIDEO RECORDER AND DISTANCE SETTING	\$ 80.00	50
8	CONDUCT WATER LEAKAGE TEST	\$ 100.00	x
9	REMOVE AND REFIX TAILGATE WINDSCREEN	\$ 120.00	✓
10	TRANSFER TAILGATE MECHANISM	\$ 80.00	✓
11	REMOVE AND REFIX REAR EXHAUST PIPE	\$ 180.00	80
12	MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	x

2150

**TOTAL \$ 4,900.00**

TOTAL PARTS COST : \$ 10,619.28  
 TOTAL LABOUR COST : \$ 4,900.00  
 TOTAL REPAIR COST : \$ 15,519.28

**NB:** THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

**PARTS PRICES ARE SUBJECT TO CHANGES.**

YOURS FAITHFULLY,

**IRENE**

SERVICE ADVISOR  
 IRENE  
 HP : 8297 9787

Admin Lj  
 H/S 18/03/22.  
 06 Days

total: 6877.44.  
 H/S: 5.5K.

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date: