

2 Kaki Bukit Ave 2, #02-19/22 AutoHub @ Kaki Bukit, Singapore 417921

Email: ryderautoworkshop@gmail.com

Tel: 67418277 Fax: 67468277

TP 1st Cap

Venn.

ESTIMATE OF REPAIR

Veh# : SGW7449P

Model: HONDA CIVIC 1.8L A
28/7/2007

Accident Date : 17/3/2022

Location : JURONG EAST

3P: SBS3397L (FIRST CAP)

S/Nos.	Qty	Description	List \$	S/Nett \$	Nett \$
1	1 pc	Rear bumper <i>Dehnd</i>	765.60	638	-
2	10 pcs	Rear bumper clips <i>new</i>	-	30.00	-
3	1 pc	Rear bumper body kit <i>Ry</i>	-	800.00	x
4	2 pcs	Rear bumper o/s & n/s retainer <i>new</i>	89.60	46.	-
5	2 pcs	Rear bumper o/s & n/s screw <i>new</i>	-	40.00	-
6	1 pc	Rear reverse sensor <i>Dehd</i>	-	220.00	2w
7	1 pc	Rear end panel <i>Ry</i>	360.60	x.	-
8	1 pc	Rear end panel inner trim <i>Dehd.</i>	70.80	✓	-
9	4 pcs	Rear end panel inner trim clips <i>new</i>	-	16.00	✓
10	2 pcs	Rear o/s & n/s tail-lamp <i>Lit at, Rlt chld.</i>	642.88	570.	-
11	2 pcs	Rear o/s & n/s tail-lamp panel <i>Ry</i>	360.00	x.	-
12	2 pcs	Rear boot o/s & n/s lamp <i>chld.</i>	495.04	410.	-
13	1 pc	Rear boot cover <i>Dehd.</i>	792.84	✓	-
14	1 pc	Rear boot cover weatherstrip <i>new</i>	137.60	-	-
15	1 pc	Rear boot cover emblem <i>new</i>	76.90	45.	-
16	1 pc	Rear boot cover lock (Upper) <i>new</i>	205.00	125	-
17	2 pcs	Rear boot cover o/s & n/s hinges <i>new</i>	97.20	x.	-
Sub-Total:			4,094.06	1,106.00	0.00
			20%	0%	0%
After Less %:			3,275.25	1106.00	0.00
Labour					
1		To dismantle, cutting, welding rear portion damaged parts. <i>SN: 246</i>	1,000.00	503	
2		To putty and spray painting.	800.00	600	
3		To check wiring.	80.00	30	
4		To re-seal anti-rust. <i>1170</i>	80.00	40	
Sub-Total:			1,960.00		
Total:			6,341.25		
After Less 20%			5,073.00		

Chan San Choon
Director
DipEng, AAE MIMI, MSAE(Aust)



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

24 hr accident call

Acknowledged by Repairer
Signature:
Date:

Total: 3524.11
L/S: 900 (Nett Value)
04 Days

