

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/ICS22002534/AQY3N2**Date:** 27/05/2022REFERENCE

Handling Insurer: ECICS Limited Policy No:

Claimant Vehicle No : SLB5485Z **Insured Vehicle No :** GBL1330D

Date of Loss: 16/03/2022 Nature of Claim: TP Claim No: DQAM2200005H

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLB5485Z**

Make & Model: HONDA VEZEL, 1.5 (A) Engine No: L15B4028124

Reg. Date: 13/04/2016 (Man. Year: 2015) Chassis No: RU11108123

Colour: White Odometer: 199942 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60R16 Rear Tyre Size: 215/60R16

Front Left Side: Habilead 6 mm Rear Left Side: Habilead 6 mm

Front Right Side: Habilead 6 mm Rear Right Side: Habilead 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,671.20	3,135.36	5,535.84	63.84
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,400.00	980.00	4,420.00	81.85
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,071.20	4,115.36	9,955.84	70.75
Approved Total (Overridden) (S\$)		3,300.00		
Nett Amount (S\$)	14,071.20	3,300.00	10,771.20	76.55

INSPECTION

Date of Assignment: 18/03/2022

Date Inspected: 18/03/2022 Inspected At: HD Perfect Autowork Pte Ltd (HQ)
8 Kaki Bukit Ave 4, #08-09 Premier @ Kaki Bukit
Singapore 415875

Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 27 May 2022)
Parts:	M1-SUV	HONDA VEZEL 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLB5485Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,085.00 FL	*785.00 FL
2	1		*FRONT BUMPER LOWER LIP	Not Necessary	381.00 FL	*- FL
3	1		*FRONT BUMPER SIDE RETAINER	O/s Damaged	46.00 FL	*23.00 FL
4	1		*HEADLAMP RH (LED)	Cracked	1,859.40 FL	*1,859.40 FL
5	1		*HEADLAMP LOWER BRACKET	Not Necessary	59.00 FL	*- FL
6	1		*FRONT FENDER RH	Dented	748.80 FL	*748.80 FL
7	1		*FRONT FENDER INNER GARNISH RH	Not Necessary	85.00 FL	*- FL
8	1		*FRONT FENDER ARCD GARNISH RH	Deformed	195.00 FL	*195.00 FL
9	1		*FRONT FENDER INNER COWLING RH	Torn	170.50 FL	*170.50 FL
10	1		*FRONT ABS SENSOR	Not Necessary	180.00 FL	*- FL
11	1		*FRONT SHOCK ABSORBER RH	Not Necessary	586.50 FL	*- FL
12	1		*FRONT LOWER ARM RH	Not Necessary	474.70 FL	*- FL
13	1		*FRONT KNUCKLE ARM RH	Not Necessary	461.70 FL	*- FL
14	1		*FRONT KNUCKLE ARM INNER BEARING RH	Not Necessary	262.00 FL	*- FL
15	1		*FRONT WHEEL HUP RH	Not Necessary	379.40 FL	*- FL
16	1		*FRONT LINKAGE RH	Not Necessary	65.00 FL	*- FL
17	1		*FRONT STEERING RACK & PINION	Not Necessary	1,750.00 FL	*- FL
18	1		*FRONT NUMBER PLATE	Not Necessary	80.00 FS	*- FS
19	1		*FRONT BUMPER CLIP (SET)	Necessary	60.00 FS	*30.00 FS
20	1		*FRONT WIPER PANEL GARNISH CLIP (SET)	Necessary	30.00 FS	*20.00 FS
21	1		*FRONT SUPPORT PANEL TOP GARNISH CLIP (SET)	Not Necessary	30.00 FS	*- FS
22	1		*FRONT FENDER INNER COWLING CLIP RH (SET)	Necessary	50.00 FS	*30.00 FS
23	1		*FRONT FENDER ARCED GARNISH CLIP LH (SET)	Necessary	50.00 FS	*30.00 FS
24	1		*FRONT WHEEL TYRE RH	Not Necessary	450.00 FS	*- FS
25	1		*FRONT WHEEL RIM RH	Not Necessary	850.00 FS	*- FS
26	1		*BRAKE OIL	Not Necessary	40.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	10,429.00	3,891.70
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,757.80	756.34
Total Parts (\$\$)	8,671.20	3,135.36

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING, REMOVING AND REPLACING PARTS	New	1,600.00	500.00
2	SPRAY PAINTING TO AFFECTED AREA	New	1,600.00	450.00
3	WIRING CHECK	New	120.00	30.00
4	REFOCUS HEADLAMP BEAM	New	80.00	0.00
5	REMOVE & REFIX CUSHION SEAT/UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR	New	350.00	0.00
6	REMOVE AND REFIX FRONT UNDERCARRIAGE	New	650.00	0.00
7	REMOVE AND REFIX POWER STEERING RACK AND PINION	New	350.00	0.00
8	FOUR WHEEL ALIGNMENT	New	120.00	0.00
9	RESET ABS LIGHT	New	350.00	0.00
10	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	New	180.00	0.00
Gross Labour Cost (\$)			5,400.00	980.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >