


HD Perfect Autowork Pte Ltd

Company Reg No: 202136904Z

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778

E-mail: hdperfectautowork@gmail.com



HD PERFECT
AUTOWORK PTE LTD

DATE : 16.03.22

TO : **ECICS** MOTOR CLAIMS DEPTS
VEHICLE NO : **SLQ8630Y**
MODEL : **HONDA VEZEL**
DATE OF ACCIDENT : 16.03.22
TIME OF ACCIDENT : 09:45HRS

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BUMPER	1	\$ 1,085.00	\$ 1,085.00
2	FRONT BUMPER LOWER LIP	1	\$ 381.00	\$ 381.00
3	FRONT BUMPER SIDE RETAINER	2	\$ 23.00	\$ 46.00
4	HEADLAMP RH (LED)	1	\$ 1,859.40	\$ 1,859.40
5	HEADLAMP LOWER BRACKET	1	\$ 59.00	\$ 59.00
6	FRONT FENDER RH	1	\$ 748.80	\$ 748.80
7	FRONT FENDER INNER GARNISH RH	1	\$ 85.00	\$ 85.00
8	FRONT FENDER ARCD GARNISH RH	1	\$ 195.00	\$ 195.00
9	FRONT FENDER INNER COWLING RH	1	\$ 170.50	\$ 170.50
10	FRONT ABS SENSOR	1	\$ 180.00	\$ 180.00
11	FRONT SHOCK ABSORBER RH	1	\$ 586.50	\$ 586.50
12	FRONT LOWER ARM RH	1	\$ 474.70	\$ 474.70
13	FRONT KNUCKLE ARM RH	1	\$ 461.70	\$ 461.70
14	FRONT KNUCKLE ARM INNER BEARING RH	1	\$ 262.00	\$ 262.00
15	FRONT WHEEL HUP RH	1	\$ 379.40	\$ 379.40
16	FRONT LINKAGE RH	1	\$ 65.00	\$ 65.00
17	FRONT STEERING RACK & PINION	1	\$ 1,750.00	\$ 1,750.00

TOTAL PRICE \$ 8,789.00
LESS 20% \$ 1,757.80
SUB TOTAL PRICE \$ 7,031.20

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	FRONT NUMBER PLATE	1	\$ 80.00	\$ 80.00
2	FRONT BUMPER CLIP (SET)	1	\$ 60.00	\$ 60.00
3	FRONT WIPER PANEL GARNISH CLIP (SET)	1	\$ 30.00	\$ 30.00
4	FRONT SUPPORT PANEL TOP GARNISH CLIP (SET)	1	\$ 30.00	\$ 30.00
5	FRONT FENDER INNER COWLING CLIP RH (SE	1	\$ 50.00	\$ 50.00

TO : **ECICS** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SLQ8630Y**
 MODEL : **HONDA VEZEL**
 DATE OF ACCIDENT : 16.03.22
 TIME OF ACCIDENT : 09:45HRS

6	FRONT FENDER ARCED GARNISH CLIP LH (SET)	1	\$ 50.00	\$ 50.00
7	FRONT WHEEL TYRE RH	1	\$ 450.00	\$ 450.00
8	FRONT WHEEL RIM RH	1	\$ 850.00	\$ 850.00
9	BRAKE OIL	1	\$ 40.00	\$ 40.00

TOTAL \$ 1,640.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$ 1,600.00	
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,600.00	
3	WIRING CHECK	\$ 120.00	
4	REFOCUS HEADLAMP BEAM	\$ 80.00	
5	REMOVE & REFIX CUSHION SEAT/UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR	\$ 350.00	
6	REMOVE AND REFIX FRONT UNDERCARRIAGE	\$ 650.00	
7	REMOVE AND REFIX POWER STEERING RACK AND PINION	\$ 350.00	
8	FOUR WHEEL ALIGNMENT	\$ 120.00	
9	RESET ABS LIGHT	\$ 350.00	
10	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	

TOTAL \$ 5,400.00

TOTAL PARTS COST : \$ 8,671.20
 TOTAL LABOUR COST : \$ 5,400.00
 TOTAL REPAIR COST : \$ 14,071.20

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR

IRENE

HP : 8297 9787