



Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

(199806235M)

Vehicle No. SGD7175D TOYOTA WISH 1.8 A

Page No. 1

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(\$)	SURVEYOR'S ADJUSTMENT
PARTS (LIST ITEMS)				
1	Rear windscreen / OR		1219.00	
1	Boot lid / OO		1719.00	1208 /
1	Boot lid lock / BT		579.00	228 /
1	Boot lid trim board / CR4		790.00	680 /
1	Boot lid logo badge / NK		231.00	70 /
1	Boot lid outer center chrome / OR		471.00	383 /
1	Boot lid emblem "drive" / NK		62.00	
1	Boot lid top spoiler brake lamp / OR		579.00	233 /
2	Boot lid both hinge LH/RH @\$231 X NN		462.00	
1	Boot lid weatherstrip / CR4		371.00	300 /
1	Tail lamp rh / OR		579.00	472 /
1	Rear bumper / OO		481.00	
2	Rear bumper side retainer LH/RH @\$231 OR (RH) 110		462.00	110 /
2	Rear bumper side reflector LH/RH @\$231 (RH) / OR 124		382.00	124 /
1	End panel / OO		790.00	690 /
2	End panel side bracket metal LH/RH @2*\$171 (RH) / OO 88		342.00	88 /
1	End panel top garnish / CR4		402.00	230 /
2	Rear Car plate lamp LH/RH @2*\$122 ? X NN		244.00	
Part Items Total:			10165.00	
			-25% -2541.25	
			7623.75	
SPECIAL NETT ITEMS				
1	Rear boot lid lock switch ? X NN		180.00	
1	Boot lid top spoiler / OR		1200.00	600 /
3	Rear windscreen moulding @Qty:3*\$60 / NK 40		180.00	120 /
1	Rear bumper clips / NK		30 / 35.00	
1	Rear carplate / CR4		35.00	
1	Rear reverse sensor / OR		200.00	
1	End panel sealant / NK		30 / 60.00	
1	Rear windscreen sealant / NK		40 / 60.00	
1	Rear windscreen solar film / NK		100 / 200.00	

6470
-25%
4852.50

1	Rear bumper lower chrome stripe	✓	Mc	70	✓	100.00
1	Boot lid emblem "chinese word"	✓	Mc	50	✓	100.00
1	Boot lid emblem "blue"	✓	Mc	50	✓	100.00
				SN Items Total:	2450.00	
				Total Parts	10073.75	

1325



Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 5(608581)

Email: motor@wahhong.sg

(199806235M)

Vehicle No. SGD7175D TOYOTA WISH 1.8 A

Page No. 2

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (\$)	SURVEYOR'S ADJUSTMENT
1	LABOUR To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas and replace the damaged parts and components	1200.00	900
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	1000.00	800
3	To remove/refix/replace wiring system at accident damaged area and check for all electrical proper function	60.00	30
4	To perform anti-rust treatment on affected areas	60.00	30
5	To remove and refit/replace rear compartment fitting, trimmings, garnish and etc	100.00	50
6	To remove and replace rear windscreen	150.00	120
7	To remove and replace rear reverse sensor	100.00	30
Labour Total :		2670.00	
TOTAL (PARTS & LABOUR):		12743.75	

1960

Steve (CLKK)
18/3/22, 12.30pm

ML PL = 8137.50
L/S L/S-6510
= 6500
AL
S Lp

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: