

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

HUA KWEE RENOVATION
BLK 115A YISHUN RING ROAD #10-831
SINGAPORE 761115

Contact : 96236641

TP China
Denise

TAX INVOICE

Repair Code : CLM15461

Date in : 12/02/2022

Vehicle Num. : GX5822C

Model : TOYOTA DYNA 3.0 M

Chassis/Eng# : LY2300009836/5L5433892

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
LH SIDE GATE <i>Dented</i>	1	1409.20	✓ 1,409.20
LH SIDE GATE HINGES <i>new</i>	6	57.70	✗ 346.20
LH SIDE GATE OPENER HANDLE <i>Dented.</i>	1	139.00	✓ 139.00
REAR LH RUBBER STOPPER <i>new</i>	1	43.10	✗ 43.10
REAR LH RUBBER STOPPER BRACKET <i>new</i>	1	98.60	✗ 98.60
REAR LH TAILLAMP <i>Cracked.</i>	1	251.30	✓ 251.30
REAR LH TAILLAMP BRACKET <i>new</i>	1	61.80	✗ 61.80
REAR TAILGATE <i>Dented</i>	1	1116.70	✓ 1,116.70
REAR TAILGATE 'TOYOTA' STICKER <i>new</i>	1	238.90	✓ 238.90
REAR TAILGATE HINGES <i>new</i>	4	57.70	✗ 230.80
Subtotal before discount			3,935.60
Percentage discount 25%			983.90
Sub-total 1			2,951.70
ALUMINIUM SWING DOOR REPAIT KIT - SET <i>new</i>	1	200.00	✓ 200.00
CANOPY SILICON <i>new</i>	1	100.00	✓ 100.00
REAR ALUMINIUM SWING DOOR CANVAS <i>new</i>	1	500.00	✗ 500.00
REAR LH ALUMINIUM DOOR <i>Dented.</i>	1	1800.00	✓ 1,800.00
REAR LH ALUMINIUM SWING DOOR <i>Ryis</i>	1	1300.00	✗ 1,300.00

*** This is a computer-generated document which requires no signature. ***

2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@i51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

HUA KWEE RENOVATION
BLK 115A YISHUN RING ROAD #10-831
SINGAPORE 761115

Contact : 96236641

TAX INVOICE

Repair Code : CLM15461

Date in : 12/02/2022

Vehicle Num. : GX5822C

Model : TOYOTA DYNA 3.0 M

Chassis/Eng# : LY2300009836/5L5433892

REAR LH SWING DOOR PILLAR	1	600.00	400.00	600.00
REAR TAILGATE '4FAX' STICKER	1	25.00	10.00	25.00
REAR TAILGATE '70KM/H' STICKER	1	25.00	10.00	25.00
REAR TAILGATE 'LTA SIGN' STICKER	1	180.00	100.00	180.00
Subtotal before discount				4,730.00

Percentage discount 0%

Sub-total 2

Parts-total

LABOUR

To remove, re-install electrical wiring harness, check lighting. (to FR)

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

To provide labour, workmanship to charge the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

Labour Total

Parts & Labour Total

*** This is a computer-generated document which requires no signature.***

page 2

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Li
1/5 22/03/22

05 Days.

Total: 5126.32

L/S: A. LK ✓