

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlmmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : DALJIT SINGH S/O HARBHAJAN SINGH
351 HOUGANG AVE 7
#08-741
SINGAPORE 530351
TEL: 81265993
ATTN:

Your Ref No: SKN7346C
Claim Type: Third Party → C.N.R.
Accident Date: 17/03/2022
TP Veh Reg No: GBE139J

Estimate No: MC1902541
18 Mar 2022
LKK Auto Consultants hence notify
the Repairer of the following:
• To resurvey before/after repair SKN7346C
• To display damaged part(s) during resurvey
• Prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company
Acknowledged by Repairer
Signature:
Date:

Estimate Repair Cost to Vehicle No. SKN7346C

Description	Quantity	List Price S\$	Amount S\$
SPARE PARTS			
1 REAR BUMPER ?	1 PC	1,231.50	
2 REAR BUMPER SIDE RETAINER RH ?	1 PC	41.00	
3 REAR BUMPER SPLASH SHIELD RH ?	1 PC	53.90	
4 REAR BUMPER CLIPS ?	6 PC	30.00	
5 REAR FENDER RH / BUC	1 PC	1,312.50	
6 REAR FENDER MUDGUARD RH ?	1 PC	188.40	
7 REAR FENDER MUDGUARD CLIPS ?	8 PC	40.00	
8 REAR AIR VENT RH X MN	1 PC	74.90	
9 REAR WINDSCREEN MLDG / BCL	1 PC	117.10	
10 REAR WHEEL BEARING + HUB RH X IVN	1 PC	480.40	
		3,569.70	
	Less 20%	713.94	2,855.76
Special Nett			
11 INNER SEAL	1 PC	20.00	
12 WINDSCREEN SEALANT / BCL	1 PC	40.00	
13 SPORT RIM RHR - CHECK PRICE X MN	1 PC	0.00	
		60.00	60.00
LABOUR			
14 TO CHECK AND RE-ADJUST WHEEL ALIGNMENT.	1 PC	80.00	60
15 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR WINDSCREEN.	1 PC	120.00	120
16 TO REMOVE AND REINSTALL CUSHIONS, SEATS, BACKREST, INNER TRIM, GARNISH, ROOF LINING OR UPHOLSTERY TO FACILITATE REPAIRS.	1 PC	180.00	60
17 TO DISMANTLE, REPLACE AND REINSTALL UNDERCARRIAGE.	1 PC	120.00	X MN
18 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR BUMPER SENSORS.	1 PC	60.00	40
19 TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS.	1 PC	60.00	1
20 TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD REAR FENDER RH. TO KNOCK & REPAIR REAR FENDER INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	800.00	600
21 TO SPRAY REAR BUMPER, REAR FENDER RH, REAR FENDER INNER RH.	1 PC	700.00	400
		2,120.00	2,120.00

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST.M9-0009639-E RCB NO.06470300B

SURVEYOR COPY

M/S : DALJIT SINGH S/O HARBHAJAN SINGH
351 HOUGANG AVE 7
#08-741
SINGAPORE 530351
TEL: 81265993
ATTN:

Estimate No: **MC1902541**
Date: 18 Mar 2022
Policy No: P10308602R02
Veh Reg No: **SKN7346C**
Make/Model: MAZDA 6 4-DOOR
SEDAN 2.0L

Your Ref No: SKN7346C
Claim Type: Third Party
Accident Date: 17/03/2022
TP Veh Reg No: GBE139J

Estimate Repair Cost to Vehicle No :SKN7346C

Description	Quantity	List Price S\$	Amount S\$
Total			S\$ 5,035.76
Add GST @ 7%			352.50
Total Amount Payable			S\$ 5,388.26

TOTAL: SINGAPORE DOLLAR FIVE THOUSAND THREE HUNDRED EIGHTY EIGHT AND CENTS TWENTY SIX ONLY

Please arrange this vehicle to be surveyed soonest possible.
Thank You

For AH LIM MOTOR COMPANY

Zila
Motor Company

AUTHORISED SIGNATURE

5 Days.

Complete repair

After repair photos.

Caro @ car.

8288 082

Caro @ car @ 14 Auto.com

28/4/22.