

来發 ( 明 記 ) 摩 哆 有 限 公 司  
LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267  
GST No: M2-0128609-3  
UEN: 199407592C

SUPPLEMENTARY

ESTIMATE

EST. No ..... EST0029013  
Lonpac Insurance Bhd  
300 Beach Road  
#17-04/07 The Concourse  
Singapore 199555

Page ..... 1 of 1  
Your ref. .... Z21VP05029195  
Job No. .... 72535  
Our ref ..... 22.03.19  
Payment .....  
Date ..... 28/3/2022

Attn .....

Vehicle No .... SLN 9294T  
Vehicle Model : BMW 530i  
Accident on ... 13/3/2022

| Quantity            | Unit | Description                          | Unit price | Disc. pct. | Amount |
|---------------------|------|--------------------------------------|------------|------------|--------|
| SUPPLEMENTARY ITEM: |      |                                      |            |            |        |
| 1.00                | Pc   | Rear door weatherstrip LH <b>nec</b> | 145.00     |            | 145.00 |
| 1.00                |      | 15% of parts supplied:               | 21.75      |            | 21.75  |

Sub-Total 166.75  
GST 7.00% 11.67  
Total S\$ 178.42

本公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给于快速与准确的测量方式和大铁修理。  
除外，还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

# 來發 (明記) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267  
GST No: M2-0128609-3  
UEN: 199407592C

## ESTIMATE

EST. No .....: EST0029013  
Lonpac Insurance Bhd  
300 Beach Road  
#17-04/07 The Concourse  
Singapore 199555

Page .....: 1 of 2  
Your ref. ....: Z21VP05029195  
Job No. ....: 72535  
Our ref .....: 22.03.19  
Payment .....  
Date .....: 18/3/2022

Attn .....

Vehicle No ....: SLN 9294T  
Vehicle Model : BMW 530i  
Accident on ...: 13/3/2022

*Not Authorized*  
*Recovery B4 p.m*  
*Ex @ 500* *7 days*

| Quantity                                     | Unit | Description                                                                         | Unit price | Disc. pct. | Amount                      |
|----------------------------------------------|------|-------------------------------------------------------------------------------------|------------|------------|-----------------------------|
| Supply of Parts:                             |      |                                                                                     |            |            |                             |
| 1.00                                         | Pc   | Rear door LH                                                                        | 1,180.00   |            | <i>Ry</i> 1,180.00 ✓        |
| 1.00                                         | Pc   | Rear fender LH                                                                      | 1,700.00   |            | <i>Ry</i> 1,700.00 ✓        |
| 1.00                                         | Pc   | Side skirt LH                                                                       | 410.00     |            | <i>Det 1/12/11</i> 410.00 ✓ |
| 1.00                                         | Pc   | Side skirt rear retainer LH                                                         | 26.00      |            | <i>M</i> 26.00 ✓            |
| 1.00                                         | Pc   | Rear fender inner shield LH                                                         | 155.00     |            | <i>CMT</i> 155.00 ✓         |
| Total amount of parts supplied - S\$3,471.00 |      |                                                                                     |            |            |                             |
| 1.00                                         |      | 15% of parts supplied:                                                              | 520.65     |            | 520.65                      |
| Labour & Misc:                               |      |                                                                                     |            |            |                             |
| 1.00                                         |      | To check/clear fault codes                                                          | 120.00     |            | 120.00 <i>100d</i>          |
| 1.00                                         |      | To remove & refix rear cushion assy                                                 | 80.00      |            | 80.00 ✓                     |
| 1.00                                         |      | To cut + weld, to knock dents on inner reinforce rocker panel LH and renew of parts | 800.00     |            | 800.00 <i>700d</i>          |



本公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给于快速与准确的测量方式和大铁修理。除外，还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

来發 ( 明 記 ) 摩 哆 有 限 公 司  
LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267  
GST No: M2-0128609-3  
UEN: 199407592C

ESTIMATE

EST. No .....: EST0029013  
Lonpac Insurance Bhd  
300 Beach Road  
#17-04/07 The Concourse  
Singapore 199555

Page .....: 2 of 2  
Your ref. ....: Z21VP05029195  
Job No. ....: 72535  
Our ref .....: 22.03.19  
Payment .....  
Date .....: 18/3/2022

Attn .....

Vehicle No ....: SLN 9294T  
Vehicle Model : BMW 530i  
Accident on ...: 13/3/2022

| Quantity | Unit | Description                                                            | Unit price | Disc. pct. | Amount               |
|----------|------|------------------------------------------------------------------------|------------|------------|----------------------|
| 1.00     |      | To spray paint (including blending front door LH + roof side panel LH) | 1,000.00   |            | 1,000.00 <i>pool</i> |

Sub-Total 5,991.65  
GST 7.00% 419.42  
Total S\$ 6,411.07

本公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给于快速与准确的测量方式和大铁修理。除外，还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."