



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CS3/LPC21011548/Vvy3e2-1 Date: 17/05/2022 Code: LPC2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SLK 4844E	Veh. Inspected	SMD 8219J	
Policy No.	Z21VP05028250	Coverage (\$)	0.00	
Claim No.	21/21/21/VP05/025140	Excess (\$)	0.00	
Assign From	GERALD POH	Assign Date	18/03/2022	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	TOYOTA ESTIMA 2.4G A SR	c.c	2362	
Engine No.	HIDDEN	Year of Reg.	2008	
Chassis No.	ACR500073731	Colour	SILVER	
Odometer	133407 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	215/55Z R17	APLUS	5 mm	
L/H Front Tyre	215/55Z R17	APLUS	5 mm	
R/H Rear Tyre	215/55Z R17	APLUS	5 mm	
L/H Rear Tyre	215/55Z R17	APLUS	5 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	10/11/2021	Inspection Date	12/11/2021	
Survey held at	8, Kaki Bukit Avenue 4 @ Premier, #04-20			
Repairer	A-TEC AUTOMOTIVE PTE LTD			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	