



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555		Ref: CS3/LPC22001235/Eqy3e2-1 Date: 11/04/2022 Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	GBD 9704Z	Veh. Inspected	GBF 6427H
Policy No.		Coverage (\$)	0.00
Claim No.	21/22/22/VC00/025441	Excess (\$)	0.00
Assign From	GERALD POH	Assign Date	18/03/2022
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA HIACE	c.c	2982
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JTFHT02P900213962	Colour	SILVER
Odometer	106509 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195 R15C	GOODYEAR	4 mm
L/H Front Tyre	195 R15C	GOODYEAR	4 mm
R/H Rear Tyre	195 R15C	GOODYEAR	4 mm
L/H Rear Tyre	195 R15C	GOODYEAR	4 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	08/02/2022	Inspection Date	10/02/2022
Survey held at	V-TECH AUTO SERVICE No.1 SOON LEE STREET #06-04/05/06/07 PIONEER CENTRE SINGAPORE 627605		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	