

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III22002550/VPA3Q2**Date:** 20/06/2022**REFERENCE**

Handling Insurer: India International Insurance Pte Ltd Policy No: D19MFL0005549_02

Claimant Vehicle No : SMN4355Y **Insured Vehicle No :** GBH7274P

Date of Loss: 17/03/2022 Nature of Claim: TP Claim No: MFL2022D0001273

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMN4355Y**

Make & Model: HONDA CIVIC, 1.6 VTI CVT (A) Engine No: R16B25510827

Reg. Date: 08/08/2019 (Man. Year: 2019) Chassis No: MRHFC5650KT000762

Colour: Black Odometer: 1597 km

Engine Capacity: 1597 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/55Z R16 Rear Tyre Size: 215/55Z R16

Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm

Front Right Side: Dunlop 6 mm Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,807.92	1,585.92	222.00	12.28
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,500.00	830.00	670.00	44.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	3,307.92	2,415.92	892.00	26.97
+ GST 7.00/7.00% (S\$)	231.55	169.11	62.44	26.97
Nett Amount (S\$)	3,539.47	2,585.03	954.44	26.97
+ Car Rental (5.0 x S\$100.00/day + 7.00% GST) (S\$)		535.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		3,127.48		

INSPECTION

Date of Assignment: 18/03/2022

Date Inspected: 21/03/2022 Inspected At:

Kan Fook Sing Motor Workshop (Defu)

No. 61 Defu Lane 12

Singapore 539147

Estimated Period of Repair: 4.0 days

Adjuster: Thevan Thomas Karthikesavan**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 24 May 2022)
Parts:	143	HONDA CIVIC 1.6 VTI CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMN4355Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT COVER	Dented	550.90 FL	*550.90 FL
2	1		*REAR BOOT CIVIC EMBLEM	Necessary	13.40 FL	*13.40 FL
3	1		*REAR BOOT IVTEC EMBLEM	Necessary	12.50 FL	*12.50 FL
4	1		*REAR END PANEL	Repair	277.50 FL	*- FL
5	1		*REAR BUMPER	Cut	617.20 FL	*617.20 FL
6	1		*REAR BUMPER LOWER	Cut	148.50 FL	*148.50 FL
7	1		*REAR BUMPER LOWER CHROME	Cut	115.00 FL	*115.00 FL
8	1		*REAR BUMPER REINFORCEMENT	Dented	188.00 FL	*188.00 FL
9	1		*REAR BUMPER SENSOR	Cut	155.40 FL	*155.40 FL
10	1		*REAR BUMPER TOW COVER	Cut	10.70 FL	*10.70 FL
11	10		*REAR BUMPER CLIP	Necessary	35.00 FL	*35.00 FL
12	1		*REAR BOOT GARNISH	Cut	135.80 FL	*135.80 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	2,259.90	1,982.40
- List Item Discount on L Items 20.00/20.00% (\$\$)	451.98	396.48
Total Parts (\$\$)	1,807.92	1,585.92

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING SYSTEM	New	30.00	30.00
2	TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS	New	720.00	400.00
3	SPRAYPAINTING CHARGES	New	750.00	400.00
Gross Labour Cost (\$)			1,500.00	830.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >