

Vehicle Damage Assessment Report for [SMN4355Y]

Estimate Created: 21/03/2022 02:04 by LKK_admin-a
(LKK_Auto_Consultants_Pte_Ltd)

Owned: 31/05/2022 07:45 by LKK_cs-a (LKK_Auto_Consultants_Pte_Ltd)

General Information

Insurance Company		Claim Number
Claim Type	TP	
Workshop	LKK_Auto_Consultants_Pte_Ltd	Reference Number

Vehicle Information

Brand	Honda	Model	Civic
Engine Type			
License Plate Number	SMN4355Y	VIN (or Chassis #)	

Vehicle Condition

Damaged Diagram	Odometer	0.00 Km
	Tyres Condition	
	Front Left	mm
	Front Right	mm
	Rear Left	mm
	Rear Right	mm

Comments

- Final review together with LKK: Concluded the cost of repair at \$2415.92 (Part by part) with 4 days for repair.

Insurlogic 1 (31/05/2022 07:43)

Parts

Description	Number/Type	Qty	Cost	Markup/Disc.%	Sum
REAR BOOT COVER		1	550.90	-20.00 %	440.72
REAR BOOT CIVIC EMBLEM		1	13.40	-20.00 %	10.72
REAR BOOT IVTEC EMBLEM		1	12.50	-20.00 %	10.00
REAR BUMPER		1	617.20	-20.00 %	493.76
REAR BUMPER LOWER		1	148.50	-20.00 %	118.80
REAR BUMPER LOWER CHROME		1	115.00	-20.00 %	92.00
REAR BUMPER REINFORCEMENT		1	188.00	-20.00 %	150.40
REAR BUMPER SENSOR		1	155.40	-20.00 %	124.32
REAR BUMPER TOW COVER		1	10.70	-20.00 %	8.56
REAR BUMPER CLIPS		1	35.00	-20.00 %	28.00
REAR BOOT GARNISH		1	135.80	-20.00 %	108.64

Parts Subtotal 1,585.92

LaborReplace/RnR

Description	Type	Cost	Markup/Disc %	Price
CHECK WIRE	RnR	30.00	0.00 %	30.00
REPLACE REAR BOOTLID AND ATTACHMENT	RnR	200.00	0.00 %	200.00
REPLACE REAR BUMPER WITH ATTACHMENT	RnR	200.00	0.00 %	200.00

Paint

Description	Paint Type	Cost	Markup/Disc %	Price
REAR BOOTLID	Full spray	200.00	0.00 %	200.00
REAR BUMPER	Full spray	200.00	0.00 %	200.00

Labor Rate S\$ 50 / Hour

General Labor Subtotal 430.00

Paint Labor Subtotal 400.00

Labor Subtotal 830.00

Summary

Repair Cost 2,415.92

Discount(0 %)	(0.00)
	2,415.92
Excess	(0.00)
GST(0.00 %)	0.00
Grand Subtotal	2,415.92