



簡福星摩多工廠

KAN FOOK SING MOTOR WORKSHOP

Headquater: 61 Defu Lane 12 Singapore 539147

Tel: (65) 6747 9560, 6473 5344 Fax: (65) 6748 1006, 6281 8428

E-mail: ryan@kanfs.net/ patricia@kanfs.net

Branch: 1 Kaki Bukit Avenue 6 #01-108 Singapore 417883

Tel: (65) 6481 5150 Fax: (65) 6481 8683

INDIA INTERNATIONAL INSURANCE PTE LTD
64 CECIL STREET
#04-05 IOB BUILDING
SINGAPORE 049711

DATE : 18-03-2022

VEHICLE NO. : SMN4355Y
ACCIDENT DATE : 17-03-2022 18:40
THIRD PARTY REF. : GBH7274P

ATTN: MOTOR CLAIMS DEPT.

ESTIMATE COST OF REPAIR TO VEHICLE SMN4355Y HONDA CIVIC 1.6 VTI CVT

QTY PARTS DESCRIPTION

1	1	REAR BOOT COVER
2	1	REAR BOOT CIVIC EMBLEM
3	1	REAR BOOT IVTEC EMBLEM
4	1	REAR END PANEL
5	1	REAR BUMPER
6	1	REAR BUMPER LOWER
7	1	REAR BUMPER LOWER CHROME
8	1	REAR BUMPER REINFORCEMENT
9	1	REAR BUMPER SENSOR
10	1	REAR BUMPER TOW COVER
11	10	REAR BUMPER CLIP@\$3.50

AMOUNT (SG\$)

550.90	/DT
13.40	/NIC
12.50	/172C
277.50	/1. KR
617.20	/Cut
148.50	/Cut
115.00	/Cut
188.00	/1. DT
155.40	/Cut
10.70	/Cut
35.00	/nec

2,124.10 1846-6

LESS 20 %

424.82

TOTAL (A)

1,699.28 1477.2

LABOUR CHARGES

1	1	TO CHECK WIRING SYSTEM
2	1	TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS
3	1	SPRAYPAINTING CHARGES

30.00 /

720.00 400

750.00 400



簡福星摩多工廠

KAN FOOK SING MOTOR WORKSHOP

Headquater: 61 Defu Lane 12 Singapore 539147

Tel: (65) 6747 9560, 6473 5344 Fax: (65) 6748 1006, 6281 8428

E-mail: ryan@kanfs.net/ patricia@kanfs.net

Branch: 1 Kaki Bukit Avenue 6 #01-108 Singapore 417883

Tel: (65) 6481 5150 Fax: (65) 6481 8683

VEHICLE NO. : SMN4355Y
ACCIDENT DATE : 17-03-2022 18:40
THIRD PARTY REF. : GBH7274P

QTY PARTS DESCRIPTION

TOTAL (D)

AMOUNT (SG\$)

1,500.00

ESTIMATE TOTAL

3,199.28

2554.28

Thuan @ Chhau to - Com

822 35769

21/3/22 1530

4 days wp

P/P

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



簡福星摩多工廠

KAN FOOK SING MOTOR WORKSHOP

Headquater: 61 Defu Lane 12 Singapore 539147
Tel: (65) 6747 9560, 6473 5344 Fax: (65) 6748 1006, 6281 8428
E-mail: ryan@kanfs.net/ patricia@kanfs.net
Branch: 1 Kaki Bukit Avenue 6 #01-108 Singapore 417883
Tel: (65) 6481 5150 Fax: (65) 6481 8683

INDIA INTERNATIONAL INSURANCE PTE LTD
64 CECIL STREET
#04-05 IOB BUILDING
SINGAPORE 049711

DATE : 23-03-2022

VEHICLE NO. : SMN4355Y
ACCIDENT DATE : 17-03-2022 18:40
THIRD PARTY REF. : GBH7274P

(N: MOTOR CLAIMS DEPT.

SUPPLEMENTARY COST OF REPAIR TO VEHICLE SMN4355Y HONDA CIVIC 1.6 VTI CVT

QTY	PARTS DESCRIPTION	AMOUNT (SG\$)
1	REAR BOOT GARNISH ✓ Cut	135.80
		135.80
	LESS 20 %	27.16
	TOTAL (A)	108.64
	SUPPLEMENTARY TOTAL	108.64

Parts : 1982.41

- 20%

= 1585.92

L abour: 830

1585.92 + 830

= 2415.92

F : 2415.92

DR: 4