

TPA16

Ceilia.

GBA7288L 2007 Nov

Toyota Dyna 2982 cc

JTFAT357703001499.

Rear Number Plate	Bent	30(SN) ✓
Rear Number Plate Panel.	Bent	127.30 ✓
Rear Number Plate Lamp	xrp nr	69.50 ✗
Taillamp x 02.	lit	$258.2 \times 2 = 516.40$ ✓
Taillamp Panel x 02	Rip	$119.3 \times 2 = 238.60$ ✗
Tailgate	Dented	1289.40 216.20 ✓
Tailgate Hinge x 04	2 pieces Bent	$108.1 \times 4 = 432.40$ ✗
Tailgate Side Lock x 02	xrp nr	$220.7 \times 2 = 441.40$ ✗
Tailgate Stopper x 02	cut	$30 \times 2 = 60$ ✗
Tailgate Slopper Bracket x 02	Bent	$153.8 \times 2 = 307.60$ ✓
Tailgate Inner Aluminium Panel	xrp nr	680(SN) ✗
Tailgate Inner Aluminium Panel Rivets.	nr	50(SN) ✓
Tailgate lower Panel.	Dented	495.40 ✓

GBA 7288L

Toyota Sticker

Dyna Sticker

70km/h Sticker

13 Pax Sticker

NEC

176.50

65

10(SN)

10(SN)

3536.90

2652.67

S.N: 280

Rear Step Panel

Bent

Repd

Spare Tyre Lock Regulator

~~250(SN)~~ 180(SN)

283.10

Panel Beating

Spray Painting

Wiring

To spray full coat

~~900~~ 700

~~800~~ 600

~~50~~ 30 1380

~~150~~ 50

Total: 4312.67

4/s: 3 HK

04 Days

3 HK

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: