

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SJN1198P
Accident Date : 14-Mar-2022

Our Ref : 022045 (AIG) / CHAN

ONG KOK KIANG
BLK 690D CHOA CHU KANG CRESCENT
#22-76
Singapore 684690

No. : 06554

Date : 16-Mar-2022

PAGE : 1

*Not withash
11/12/2022 @ 2050h
Penny Ate Peim
4 days*

ESTIMATED COST OF REPAIR FOR LEXUS IS250 SGT168L

1 pc Front o/s fender *1063*
1 pc Front bumper fascia *752.80*
1 pc Front o/s bumper side retainer

Bu 1,063.70
Bu 752.80
Di 148.90

1,965.40

Less 10% : 196.54

1,768.86

To putty and spray replaced parts

500.00 *4401*

To remove, cut-out damaged parts,
panel beating, welding, align,
refix and to renew above parts

400.00 *3801*

Total : S\$ 2,668.86

Singapore Dollars Two Thousand Six Hundred and
Sixty Eight and Cents Eighty Six Only

**LKK Auto Consultants hence notify
the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: