

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD5247G***Not Authorized*  
*11/11/2018*

AAD2203-

Vehicle No.:

Chassis No.:

Co UEN:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

**17 MAR 2022****SHD5247G**

JTDKB3FU603076688

200303878K

TOYOTA

PRIUS

16/03/2022

**SLG3272H/ ALG-**

15/11/2018

| PART  |                                            | LIST |                |
|-------|--------------------------------------------|------|----------------|
| 1     | COVER, REAR BUMPER                         | \$   | Bu 442.60 ✓    |
| 1     | COVER, REAR BUMPER, LOWER                  | \$   | Sm 15.40 X     |
| 1     | GUARD, REAR BUMPER, CENTER                 | \$   | Bu/Sm 576.30 ✓ |
| 1     | REINFORCEMENT SUB-ASSY, REAR BUMPER        | \$   | R 332.70 X     |
| 1     | FILLER, REAR BUMPER EXTENSION, RH          | \$   | mg Bu 123.70 ✓ |
| 1     | COVER, BACK DOOR TRIM                      | \$   | Sm 24.90 X     |
| 1     | PANEL SUB-ASSY, BODY LOWER BACK            | \$   | R 650.30 X     |
| 1     | LENS AND BODY, REAR LAMP, RH               | \$   | Sm 502.00 X    |
| 1     | LENS & BODY, REAR COMBINATION LAMP, RH     | \$   | cm 451.80 ✓    |
| 1     | COVER SUB-ASSY, QUARTER PILLAR, RH         | \$   | Sm 207.30 X    |
| 1     | PANEL SUB-ASSY, QUARTER, RH                | \$   | R 871.50 X     |
| 1     | PANEL SUB-ASSY, BACK DOOR                  | \$   | R 1,147.80 X   |
| 1     | GARNISH SUB-ASSY, BACK DOOR, OUTSIDE       | \$   | R 925.60 X     |
| 1     | HINGE ASSY, BACK DOOR, LH                  | \$   | R 61.00 X      |
| 1     | HINGE ASSY, BACK DOOR, RH                  | \$   | R 61.00 X      |
| 1     | PLATE, LUGGAGE COMPARTMENT DOOR NAME, NO.2 | \$   | Sm 54.60 ✓     |
| 1     | PLATE, BACK DOOR NAME, NO.1                | \$   | Sm 54.60 ✓     |
| 1     | ORNAMENT SUB-ASSY, BACK DOOR               | \$   | Sm 47.90 ✓     |
| 1     | PANEL SUB-ASSY, REAR DOOR, RH              | \$   | R 1,294.90 X   |
| 1     | HANDLE ASSY, REAR DOOR OUTSIDE, RH         | \$   | R 97.40 X      |
| TOTAL |                                            | \$   | 6,551.00       |
| 25%   |                                            | \$   | 1,637.75       |
|       |                                            | \$   | 4,913.25       |

**Special Nett**

SET PARKING AID

\$ Sm 700.00 X

1 REAR BUMPER CLIP

\$ Sm 65.00 ✓

**Trans-cab Auto Services Pte Ltd**

AAD2203-

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD5247G

|                                  |           |    |               |   |
|----------------------------------|-----------|----|---------------|---|
| 1 REAR TAIL LAMP CLIP            | \$        | nn | 65.00         | X |
| 1 END PANEL INNER TRIM CLIP      | \$        | nn | 60.00         | X |
| 1 CLIP(FOR REAR DOOR TRIM BOARD) | \$        | nn | 65.00         | X |
| 2 WINDSCREEN SEALANT             | \$        | nn | 150.00        | X |
| 1 WINDSCREEN MOULDING            | \$        | nn | 200.00        | X |
| 1 WINDSCREEN INNER SPONGE SEAL   | \$        | nn | 130.00        | X |
| <b>TOTAL</b>                     | <b>\$</b> |    | <b>735.00</b> |   |

**TOTAL PARTS \$ 8,543.40****LABOUR**

|                                                                                                                           |           |    |                 |      |
|---------------------------------------------------------------------------------------------------------------------------|-----------|----|-----------------|------|
| To Rust-Proofing and apply undercoat Of The Affected Areas.                                                               | \$        | nn | 250.00          | X    |
| Putty And Spray Painting Of The Affected Portion.                                                                         | \$        |    | 1,800.00        | 4401 |
| To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.                           | \$        | nn | 380.00          | X    |
| To Check Electrical Lighting Concerned.                                                                                   | \$        |    | 170.00          | 201  |
| Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same | \$        |    | 3,000.00        | 3001 |
| To check steering geometry and computer wheel alignment                                                                   | \$        | nn | 220.00          | X    |
| To transfer of rear fender panel fittings, attachment and perform water seepage test.                                     | \$        | nn | 170.00          | X    |
| <b>TOTAL</b>                                                                                                              | <b>\$</b> |    | <b>5,990.00</b> |      |

**Over All Total \$ 19,446.65****LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

**(PART-BY-PART) Repair Days**

20 Days

2 1/2 days