



Liu's Brother Auto Engineering Workshop

No. 1 Kaki Bukit Avenue 6 #01-01 AutoBay @ Kaki Bukit Singapore 417883

UEN No: 53291793J

liusbro@gmail.com

Tel: 67411730

ESTIMATE

Name: China Taiping Insurance (Singapore) Pte Ltd

Address Motor Claims Department

3 Anson Road #16-00

Springleaf Tower

Singapore 079909

Ref Date:

Ref No:

Vehicle No:

Model / Make:

18-03-2022

GBG9975S220310

GBG9975S

Mitsubishi Canter

FEA01BR2SDEB (CUB)

Item #	Damaged Area	Description	Unit Price	Qty	Estimation / Quotation	N / SN	Cost Of Repair
1	Front Rr	Door O/S 20/Bent	\$ 1,995.00	1	\$ 1,995.00	✓	1615-32
2	front	Signal Lamp O/S	\$ 324.30	1	\$ 324.30	✓	208-21
3		Head Lamp Side Panel O/S	\$ 976.00	1	\$ 976.00	X	
4		Bumper Side RM 319.82	\$ 441.70	1	\$ 441.70	✓	319.82
5		Bumper Side Clips 01 set	\$ 65.00	1	\$ 65.00	SN	X
6		"Corporate" Advertisement & Artwork			\$ 200.00	SN	180 s/n
7		Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc			\$ 500.00		350
8		To putty & spray painting & including touch up paint on accident affected areas			\$ 400.00		300
9		To apply Rust Proofing, reseal tuff-coating treatment on accident area			\$ 40.00		30

Total Parts & Labour of estimate for damaged vehicle

\$ 4,942.00

Total amount in Lumpsum Basis for repaired vehicle

SDL

not Authored
Liu
21/3/22
L/S \$2000/
3 days

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

MSIAO TOM



Liu's Bro Auto Engrg Wks

P-2223-38
258
P-1667-51
S.N-180
L-680
2527-51
202
2022