

Our Job Ref No : 305509354
Date : 26/03/22

COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969

FINALIZATION FORM

To : LKK

Fax :

Attn : THEVAN

Vehicle Reg No. : SHC1833X

17.03.2022

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-


1. The repair job shall bill to: TOKIO SMU6361D
2. The finalized amount shall be:
- (a) Spare Parts after List discount \$1,790.32
- (b) Labour Charges \$701.00
- Total for Part-By-Part Repair Cost \$2,491.32
- (c.) Lumpsum Repair (if applicable)
Total for Lumpsum repair cost after Less:
Final Lumpsum Repair cost

3. Estimated normal period for repairs: 3 working days.

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and
finalized amount

Signature : 

Name : CHIANG

Tel : 62148314

Fax : 65468156

Signature : 

Name : THEVAN

Date : 19/4/22

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid	-	N		
3. Survey Fees	-	-		
4. LTA Search Fee	\$7.49/\$2.00	YES		
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE

Date: 26.03.2022
Time: 09:49:19
Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305509354
REGN NO : SHC1833X
MILEAGE : 0000000000
MAKE : TOYOTA
MODEL : PRIUS HYBRID(G4A)
DATE OF REGN : 13.12.2019
DATE/TIME IN : 17.03.2022 20:30
ACCIDENT DATE : 17.03.2022

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0302-2712-G	COVER REAR BUMPER#	1	458.60	25.00	343.95
0002	04-01-0302-2713-G	GUARD REAR BUMPER CENTER	1	552.60	25.00	414.45
0003	04-01-0302-2267-G	BUMPER PIECE	10	22.00	25.00	16.50
0004	04-01-0302-1150-A	BUMPER PROTECTOR MAT	1	50.00		50.00
0005	09-01-0302-2005-A	REVERSE SENSOR ASSY	1	135.70		135.70
0006	04-01-0302-2716-G	LENS & BODY RR LH UPPER	1	557.90	25.00	418.42
0007	04-01-0302-2718-A	LENS & BODY RR COMB LH LO	1	548.40	25.00	411.30

SUB-TOTAL : 1,790.32

NATURE

0000 L	MERIMEM	11.00
0001 PB	PANEL BEATING SHC1833X	350.00
0002 SP	SPRAYPAINT CHARGE	250.00
0003 17-01	CHECK ALL LIGHTING	30.00

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 26.03.2022

Time: 09:49:19

Page: 2

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305509354
REGN NO : SHC1833X
MILEAGE : 0000000000
MAKE : TOYOTA
MODEL : PRIUS HYBRID
DATE OF REGN : 13.12.2019
DATE/TIME IN : 17.03.2022 20:3
ACCIDENT DATE : 17.03.2022

JOB / PARTS DESCRIPTION		QTY	IND	UNIT-PRICE	DISC%	AMOUNT
0004	20-22 REMOVE/REFIX REVERSE SENSOR			30.00		
0005	20-22 REMOVE/REFIX REVERSE SENSOR			30.00		
SUB-TOTAL :						701.00

TOTAL : 2,491.32


MVA NAME & SIGNATURE
DATE:

SURVEYOR NAME & SIGNATURE
DATE : AUTHORIZED : YES / NO

REPAIR DETAILS**Reference**

Part Source: MRM-SG

Version: 1.0 (Last Synchronised: 18 Mar 2022)

Parts: 144

TOYOTA PRIUS TAXI 1.8 (A) (Catalogue Merimen Singapore 1.0)

Labour: Repairer's

(Price-denominated Standard List)

Print Code: ComfortDelGro Engineering Pte Ltd/SHC1833X/18/03/2022 13:11

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER	25.00	0.00	*458.80 FL / 64
2	1		*REAR BUMPER RETAINER LH	25.00	0.00	NN *112.70 FL / nec 3
3	1		*REAR BUMPER UNDER COVER	25.00	0.00	*552.60 FL / 50
4	1		*REAR BUMPER REINFORCEMENT	25.00	0.00	NN *318.80 FL / 7
5	1		*REAR BUMPER TOW COVER	25.00	0.00	*82.70 FL X Sur
6	10		*REAR BUMPER CLIPS	25.00	0.00	*22.00 FL / 11 C
7	1		*TAIL LAMP UPPER LH	25.00	0.00	*567.90 FL / 109
8	1		*TAIL LAMP LOWER LH	25.00	0.00	(19) ✓ 548.40 FL X Sur
9	1		*REAR BUMPER MAT	0	0.00	*50.00 FS / 11 C
10	1		*REAR REVERSE SENSOR	0	0.00	*135.70 FS / 64
11	1		*REAR BUMPER REFLECTOR LH	25.00	0.00	*55.00 FL X Sur

F=Franchise part S=SpdNett L=ListItemDisc.

Sub Total (\$\$)

2,394.40

- List Item Discount on L Items (\$\$)

677.18

Total Parts (\$\$)

2,217.22

ComfortDelGro Engineering Pte Ltd/SHC1833X/18/03/2022 13:11. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	OD/TP Case (Insurer)	11.00
Sub Total (S\$)			11.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	PANEL BEATING	New	600.00 350
2	SPRAY PAINTING	New	300.00 250
3	CHECK LIGHTING & WIRING	New	60.00 30
4	REMOVE/REFIX REVERSE SENSOR	New	60.00 30
5	TUFF COATING	New	60.00 30
Gross Labour Cost (S\$)			1,080.00

ComfortDelGro Engineering Pte Ltd/SHC1833X/18/03/2022 13:11. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Thuan
82235769
21/3/22 1600
2dayswp
Plp before paint photo

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: