

rmb to close in view

25 KAKI BUKIT ROAD 4, #06-77
TEL: 63416453/54, FAX: 63416450

TO: TAI THIN SOO
383C BALESTIER ROAD
Singapore 329794

DATE: 24-Jun-22

VEH: GBC 4452 M

S/NO.	Description		amount	
1	left cabin top panel	damaged	\$650	✓
2	left headlight	broken	\$450	✓
3	left door	damaged	\$180	✓
4	left door handle	broken	\$80	✓
5	to dismantle, replace/cut, weld knock out dents to straighten areas affected by impacted as mentioned on the "parts Repair" column inclusive of replacement parts		\$1,500	800/-
6	Putty & spray painting to adjusted panels. Job allowance. panel / materials		\$800	600/- 700/-
7	apply rust proofing on adjusted panels		\$80	40/-
8	remove and rebuild labour		\$500	24
	total adds up			\$4,240

10%
on parts.

800/-

600 - 700

40 | -

五

\$4,240

Reciever Name: TAI THIN SOO

NRIC: S 2593289 G

Date: 24th JUNE 2022

1/5 2:2001-
5 days

mv : 4000

LIA : 1198

NV : 2802

22/03/2022

Hst Andu

1 km LKAD

Depi Unit + 2.8pc