



Polymath garage

Polymath Garage Pte Ltd
 10 Kaki Bukit Road 2 #01-21
 First East Centre, Singapore 417868
 24 Hour: +65 8228 9818
 Phone: +65 6871 8861 | Fax: +65 6871 8814
 Email: enquiry@polymathgarage.com.sg
 UEN: 201605123Z

ESTIMATED REPAIR CHECKLIST

Xiao Chen.

TO: MSIG.	VEHICLE REGISTRATION NO.: SLH3546M
ATTENTION : MOTOR INSURANCE CLAIM	VEHICLE MAKE/MODEL: VOLKSWAGEN / TIGUAN
CLAIM TYPE : 3RD PARTY CLAIM	CHASSIS NUMBER: WVGZZ5NZGW070920
ACCIDENT DATE/TIME :	CONTACT PERSON : SEBASTIAN (97527592)

PARTS	QTY	PER UNIT	PRICES	
1 REAR BUMPER <i>Deband</i>	1	\$ 1,145.60	\$ 1,145.60	✓
2 REAR BUMPER SIDE HOLDER <i>He ne</i>	2	\$ 38.10	\$ 76.20	X
3 REAR BUMPER REFLECTOR (RED) LH <i>found</i>	1	\$ 65.20	\$ 65.20	✓
4 REAR BUMPER REFLECTOR (WHITE) LH <i>found</i>	1	\$ 68.10	\$ 68.10	✓
5 REAR BUMPER REINFORCEMENT <i>new</i>	1	\$ 554.90	\$ 554.90	X
6 REAR BUMPER LOWER GARNISH <i>Deband</i>	1	\$ 459.50	\$ 459.50	✓
7 REVERSE SENSOR <i>1 piece done</i>	2	\$ 245.00	\$ 450.00	245
8 REVERSE SENSOR HOLDER <i>New</i>	4	\$ 18.00	\$ 72.00	✓
9 TAILLAMP LH <i>New</i>	1	\$ 485.20	\$ 485.20	X
10 TAILGATE <i>Deband</i>	1	\$ 1,674.60	\$ 1,674.60	✓
11 TAILGATE LOCK <i>New</i>	1	\$ 248.10	\$ 248.10	X
12 TAILGATE WEATHERSTRIP <i>New</i>	1	\$ 221.40	\$ 221.40	X
13 TAILGATE REFLECTOR LH <i>found</i>	1	\$ 385.20	\$ 385.20	✓
14 VOLKSWAGEN LOGO <i>found</i>	1	\$ 130.90	\$ 130.90	✓
15 TIGUAN EMBLEM <i>He ne</i>	1	\$ 104.20	\$ 104.20	✓
16 TSI EMBLEM <i>He ne</i>	1	\$ 62.20	\$ 62.20	✓
17 BLUEMOTION EMBLEM <i>He ne</i>	1	\$ 57.80	\$ 57.80	✓
18 REAR END PANEL <i>Ryir</i>	1	\$ 648.90	\$ 648.90	X
19 REAR END PANEL TOP GARNISH <i>new</i>	1	\$ 261.10	\$ 261.10	X
20 REAR EXHAUST PIPE <i>found</i>	1	\$ 869.40	\$ 869.40	X
21 REAR EXHAUST PIPE MOUNTING <i>found</i>	1	\$ 35.90	\$ 35.90	X
22 REAR EXHAUST PIPE GASKET <i>new</i>	1	\$ 48.20	\$ 48.20	X
SUBTOTAL :			\$ 8,124.60	
LESS 10% :			\$ 812.46	
PARTS TOTAL :			\$ 7,312.14	

4470.30

4023.27

SPECIAL NETT	QTY	PER UNIT	PRICES	
1 REAR NUMBER PLATE <i>found</i>	1	\$ 30.00	\$ 30.00	X
2 REAR NUMBER PLATE HOLDER <i>found</i>	1	\$ 30.00	\$ 30.00	X
3 REAR BUMPER CLIPS <i>new</i>	1 SET	\$ 50.00	\$ 50.00	✓
4 TAILGATE GLASS SEALANT <i>new</i>	1 SET	\$ 60.00	\$ 60.00	✓
5 REAR END PANEL TOP GARNISH CLIPS <i>found</i>	1 SET	\$ 20.00	\$ 20.00	X
6 REAR END PANEL SEALANT <i>found</i>	1 SET	\$ 60.00	\$ 60.00	X
S/N TOTAL :			\$ 250.00	

110



Polymath garage

Polymath Garage Pte Ltd

10 Kaki Bukit Road 2 #01-21

First East Centre, Singapore 417868

24 Hour: +65 8228 9818

Phone: +65 6871 8861 | Fax: +65 6871 8814

Email: enquiry@polymathgarage.com.sg

UEN: 201605123Z

LABOUR CHARGES	PRICES	ADJUSTMENT
1 PANEL BEATING	\$ 1,200.00	500
2 SPRAY PAINTING	\$ 1,200.00	600
3 WIRING	\$ 50.00	30
4 TO SPRAY TUFF COAT	\$ 150.00	40
5 TO REMOVE UPHOLSTERY	\$ 150.00	30
6 TO TRANSFER TAILGATE FITTINGS	\$ 150.00	80
7 TO REMOVE TAILGATE GLASS	\$ 180.00	120
8 TO REMOVE EXHAUST PIPE	\$ 150.00	X
LABOR TOTAL :		\$ 3,230.00

1400

ESTIMATE REPORT	
TOTAL PARTS COST:	\$ 7,562.14
TOTAL LABOUR COST:	\$ 3,230.00
TOTAL REPAIR COST:	\$ 10,792.14
PART BY PART / LUMP SUM:	_____
NO. OF REPAIR DAYS:	_____

SURVEYOR DETAILS	
SURVEYOR NAME:	_____
CONTACT:	_____
EMAIL:	_____
DATE :	_____
TIME :	_____

Total: 5533.27

L/S: A.H.K.

05 Days.