

**Note: This document has not been finalised.**

# **LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Fievel Foo Wen Yao

Date: 21 Apr 2022

## **Preliminary Advice**

Insured : FBG7785L  
Vehicle No  
TP Vehicle No : SLH3546M  
Make : VOLKSWAGEN TIGUAN  
Date of Inspection : 21/03/2022  
Inspection At : 10 KAKI BUKIT ROAD 2#03-01 FIRST EAST CENTRE S(417868)  
REPAIRER:POLYMATH GARAGE PTE LTD - KAKI BUKIT (HQ)

Accident Date : 14/03/2022  
Assignment Date : 21/03/2022  
Est. Duration of Repair : 5

## **Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	10,792.14
Revised Amount	:S\$	5,533.27
Check Items (Estimated)	:S\$	0.00
Total	:S\$	5,533.27
Lump Sum Repair	:S\$	4,400.00

## **Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$

COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

### **Remarks**

- ( ) The vehicle is economical for repair
  - ( ) The vehicle is not economical for repair
  - ( ) Part-by-Part repair
  - ( X ) Lump Sum repair
- ( X ) The above survey was conducted on a 'without prejudice' basis.  
Please note that the preliminary advice amount (Revised & Check Items)  
stated are subject to consistency check, part prices and labour cost.