

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Irene Tay Hui Ping

Date: 22 Mar 2022

Preliminary Advice

Vehicle No	: SNB6640L	Accident Date	: 14/03/2022
Make	: VOLKSWAGEN GOLF	Policy No.	: DMPCSNW00216502100
Assignment Date	: 21/03/2022	Excess	: S\$0.00
Date of Inspection	: 21/3/2022	Est. Duration of Repair	: 6
Inspection At	: AUTO INSURE PTE LTD		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	4,896.00
Revised Amount	:S\$	4,626.00
Check Items (Estimated)	:S\$	0.00
Total	:S\$	4,626.00
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	64,000.00
COE / PARF Rebate	:S\$	31,255.00
Salvage Value	:S\$	
Margin for Repair	:S\$	32,745.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Lump Sum Repair

Please note that the preliminary advise amount (Revised & Check items) stated are subject to consistency check, part prices and labour cost .