



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
UNITED OVERSEAS INSURANCE LTD 146 ROBINSON ROAD #02-01 UOI BUILDINGSINGAPORE 068909		Ref: CS/UOI22002574/Uqy3e2 Date: 12/07/2022 Code: UOI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	GBE 6691R	Veh. Inspected	SML 7877Z
Policy No.		Coverage (\$)	0.00
Claim No.	M11D14922204	Excess (\$)	0.00
Assign From	JOSEPHINE WONG	Assign Date	21/03/2022
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA SIENTA (A)	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	MHFZ28H3400064254	Colour	GREY
Odometer	45902 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195/50 R16	YOKOHAMA	7 mm
L/H Front Tyre	195/50 R16	YOKOHAMA	7 mm
R/H Rear Tyre	195/50 R16	YOKOHAMA	7 mm
L/H Rear Tyre	195/50 R16	YOKOHAMA	7 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	17/03/2022	Inspection Date	07/06/2022
Survey held at	BORNEO MOTORS (S) PTE LTD 17 UBI ROAD 4 SINGAPORE 408611		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	