



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no.: 6631 1188



TOYOTA

#1836-40

NOT Allowed
Mercedes
7/6/22
Height After repair
MP 80096608
3 days

ESTIMATE

Account Details	Account No.	Customer Details
United Overseas Insurance Ltd 146 Robinson Road #02-01 UOI Building Singapore cc	S1000019 / ICUOI1	Ms Lim Sau Peng Judy (Lin Xiaoping)
	Document No. 0	273D Punggol Place #12-888 Singapore 824273
	Document Date 18/03/2022	Mobile: 98393660

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2019	NSP170R	MWYQKT E3	04/06/2019	SML7877Z	0	21677	67/DS/SML7877Z

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
MHFZ28H3400064254	2NRX471068	60	Sam San Joi	--/--/----	0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY-AI SUNDRIES TP-DIRECT SETTLEMENT TP-GBE6691R ACC DATE:17/03/2022 DRIVE IN:17/03/2022 DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORISED ON:				30.00
2	S	BP-SUBLET TO RESET ECU AND REPROGRAMME				180.00
3	B	BP-LAB2 REPLACE REAR ACCIDENT DAMAGED PARTS STRAIGHTEN & ALIGN REAR ACCIDENT AFFECTED AREAS				1440.00
4	B	BP-RES2 RESPRAY JOB ON REAR ACCIDENT AFFECTED AREAS				1770.00
5	1	S52159-0U919 COVER, RR BUMPER, L/	1.00	335.20		335.20
6	2	S52151-0D010 EXTENSION, RR BUMPER	1.00	201.40		201.40
7	3	S67005-0D360 PANEL SUB-ASSY, BACK	1.00	1199.60		1199.60
8	4	T90975-02086 FRONT BONNET EMBLEM,	1.00	72.20		72.20
9	5	S75442-0D290 PLATE, BACK DOOR NAM	1.00	37.60		37.60
10	6	S75441-0D070 PLATE, BACK DOOR NAM	1.00	56.40		56.40

For & on behalf of Borneo Motors (Singapore) Pte Ltd	Customer's Signature	Charge Summary	Total 5,322.40
Please acknowledge receipt of vehicle		Parts 1,902.40	GST 7.00% 372.57
		Labour 3,240.00	Less 0.00
		Sublet 180.00	
		Lubrication/Fluid 0.00	
		Others 0.00	
Amount Due			5,694.97

Acknowledged by Repairer

Signature:

Date:

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no.: 6631 1188



TOYOTA

TAX INVOICE

Account Details	Account No.	Customer Details
United Overseas Insurance Ltd 146 Robinson Road #02-01 UOI Building Singapore cc	S1000019 / ICUOI1	Ms Lim Sau Peng Judy (Lin Xiaoping) 273D Punggol Place #12-888 Singapore 824273 Mobile: 98393660
	Document No. 39012710	
	Document Date 13/06/2022	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2019	NSP170R	MWYQKT E3	04/06/2019	SML7877Z	44213	21677	67/DS/SML7877Z

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
MHFZ28H3400064254	2NRX471068	60	Sam San Joi	18/03/2022 8.10	08/06/2022 14.03

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY-AI SUNDRIES TP-DIRECT SETTLEMENT TP-GBE6691R ACC DATE:17/03/2022 DRIVE IN:17/03/2022 DATE-IN:07/06/2022 DATE SURVEY:07/06/2022 NO OF REPAIR DAYS:3 DAYS BY:MARCUS(LKK)				30.00
2	B	BP-LAB2 REPLACE REAR ACCIDENT DAMAGED PARTS	*			720.00
3	B	STRAIGHTEN & ALIGN REAR ACCIDENT AFFECTED AREAS	*			885.00
4	1	BP-RES2 RESPRAY JOB ON REAR ACCIDENT AFFECTED AREAS S52151-0D010 EXTENSION, RR BUMPER	1.00	201.40		201.40

For & on behalf of Borneo Motors (Singapore) Pte Ltd	Customer's Signature	Charge Summary	Total	1,836.40
	Please acknowledge receipt of vehicle	Parts 201.40 Labour 1,635.00 Sublet 0.00 Lubrication/Fluid 0.00 Others 0.00	GST 7.00%	128.55
			Less	0.00
			Amount Due	1,964.95

Customer Copy