

ASS. REC. BY:

REF:

ASW/ 22 002574/K.

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: \$606

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 06 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SLV 9881 Yr Regn: 01, 18Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or A.Make: Honda Jazz c.c. 1318Colour: M. Grey A/C: Insured / Std / NI / NASp. Reading: 160786 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTM GK 3850 JX 205232Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModl: Nil / S/R/m / STD A/R/m orTyre Size: F: 185/60R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front: _____

R/Bal. 8 mmL/Bal. 8 mmD.O.A. 20/3/22Survey held at 10.40amDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

1 Got B1

Date/Time, File Pass to?

☐ : Prell. Report☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech Invs (\$ _____)☐ : Weekend (\$ _____)

) \$ + RS. \$ _____

) Fuel \$ _____

) Others \$ _____

TOTAL

Report Format :

Lump Sum / I.B.I: (\$ _____)

Blk 5038 #01-405 Ang Mo Kio Industrial Pk 2 Singapore 569541
H/p 91082728

Fax : 64816131

Neo Thiam Wei
Blk 854 Tampines St 82
#05-233
Singapore 520854

Not Authorized
C/Pay &
Heavy After Paint
6 days

Vehicle No : SLV 9681 S
Make : Honda Jazz
Year : 2018

Qty	Description	Unit Price	Amount
-----	-------------	------------	--------

Estimate Cost Of Repair

QTY	DESCRIPTION	UNIT PRICE	TOTAL PRICE	REMARKS
1 pc	Rear tail-gate assy		\$105.10	✓
1 pc	Rear tail-gate glass moulding		\$950.60	X
2 pcs	Rear tail-gate lamp		\$45.10	✓
1 pc	Rear tail-gate emblem " JAZZ "		\$229.70	X
1 pc	Rear tail-gate garnish		\$185.70	?
1 pc	Rear tail-gate inner lock sensor		\$195.10	?
1 pc	Rear tail-gate inner lock		\$152.60	?
1 pc	Rear tail-gate inner trim board		\$110.20	X
2 pcs	Rear no plate lamp		\$287.10	X
1 pc	Rear tail-gate wiper motor		\$410.20	✓
2 pcs	Rear fender inner trim board		\$384.60	✓
1 pc	Rear end panel		\$191.10	✓
1 pc	Rear end panel inner garnish		\$103.40	50% ✓
1 pc	Rear boot rubber		\$1,072.50	X
1 pc	Rear spare tyre panel		\$215.90	X
1 pc	Rear spare tyre panel top cover board		\$967.70	✓
2 pcs	Rear tail-lamp assy		\$791.30	✓
1 pc	Rear bumper		\$95.10	✓
1 pc	Rear bumper lower garnish (centre portion)		\$230.40	?
2 pcs	Rear bumper reflector garnish		\$90.20	✓
2 pcs	Rear bumper side retainer		\$75.10	?
2 pcs	Rear bumper sponge		\$95.60	?
1 pc	Rear antenna		\$92.10	?
1 pc	Rear buzzer		\$495.30	X
1 pc	Rear exhaust silencer		\$45.10	X
1 pc	Rear exhaust silencer heat shield		\$115.20	X
1 pc	Rear towing hook		\$1,151.60	200% ✓
1 pc	Rear reverse sensor		\$9,764.90	
			\$1,952.98	
			\$7,811.92	

✓ 1pc Rear tool sponge - \$135.70 cm ✓

SLV 9681 S

balance b/f \$7,811.92

S Nett

1 pc Rear reverse camera
1 pc Rear no plate
1 pc Rear windscreen sealant
20 pcs Rear bumper clip

Pm \$300.00 *X*
Det \$40.00 *✓*
Mr \$55.00 *4052*
\$2.50 *Mr* \$50.00 *✓*
\$445.00

Labour Charges

Remove/renew the above parts including knocking, welding & cutting.

\$1,200.00 *7*

To putty & spray paint rear accident affected portion.

\$1,200.00 *9001*

Check/reconnect wiring.

\$45.00 *201*

To spray anti rust on accident affected portion.

\$120.00 *7*

Remove/refit rear tail-gate wiper motor and lock mechanism and rear boot upholstery.

\$120.00 *601*

Remove/renew rear exhaust silencer

Mr \$120.00 *X*

Remove/refit rear windscreen to facilitate repair.

\$120.00 *✓*
\$11,181.92

**LKK Auto Consultants hence notify
the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	21/03/2022 17:41 (SGT)
Date of Accident	20/03/2022 14:00 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	CHOA CHU KANG WAY TOWARDS KJE JUNCTION
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLV9681S
-----------------------------	----------

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	NEO THIAM WEI
NRIC No	S1478958H
Email Address	philip.neo@hotmail.com
Mobile Phone No	(Phone) +65-90475784
Alternative Phone No	+65-90475784

VEHICLE PARTICULARS

Manufacturer	Honda
Model	Jazz
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private hire
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private hire
Transmission	Auto
CC	1318

INSURANCE COMPANY

Name of Insurance Company	FWD Singapore Pte. Ltd.
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	PNCV2021-00000014-01
Cover Note Number	-

DRIVER

Name of Driver	NEO THIAM WEI
NRIC No	S1478958H

IMPORTANT NOTICE

SKETCH PLAN

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [Form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and


(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan



Veh A: SLV 9681S
Veh B: SHC 1376Z