



CYCLE &amp; CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED  
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



Co Reg No : 1977014696

## ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name KCV17820/MEHENDALE SURJIT SHYAM Reg No/Reg Date SKB1284A*# / 30/06/201 Date In/Mileage 21/03/2022/ 0 Chassis No JMYSRCY1AGU006924 Engine No 4A92CP5609 Make/Model MIT/16MY LANCER EX 1.6 (F52) Colour/Trim U02 STERLING SILVER/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	21/03/2022/ 11:53	BLK	282 / Kevin Leong	21764

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE FRT BUMPER, FRT RH FENDER & AFFECTED AREA 450 X 1.5				675 1350.00
E PNT98000 PAINT WORK ON FRT BUMPER & FRT RH FENDER 350 X 2				700.00
M SUNDRY PERFORM RUST PREVENTION				40.00
A 54900099 CHECK CHASSIS & ELECTRICAL SYSTEM				30.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM BR				120.00
M SUNDRY TO SUPPLY FRT NUMBER PLATE WITH FRAME BR				50.00
M SUNDRY SUNDRIES				29 30.00
M HEADLAMP ASSY, RH - BR	1.00	851.00	23.00	655.27
M FACE, FR BUMPER - BR	1.00	1045.00	23.00	804.65
M GRILLE, FR BUMPER - BR	1.00	78.00	23.00	60.06
M COVER, HEADLAMP SUPT PANEL ? x NA	1.00	70.00	23.00	53.90
M BRACKET, FR BUMPER SIDE, RH ? x NA	1.00	17.00	23.00	13.09
M GRILLE, RADIATOR - BR	1.00	270.00	23.00	207.90
M REINFORCEMENT, FR BUMPER ? - PD	1.00	531.00	23.00	408.87
M FENDER, FR RH x R	1.00	622.00	23.00	478.94

Steve (LKK)  
21/3/22, 12:00pmOD-M AL  
EXC-1-?  
P/P17 BL M  
4 djsLKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Confirm &amp; accepted by

Acknowledged by Repairer

Authorized signatory and company stamp

7% GST on 5002.68 5,002.68 350.19

Nett 5,002.68

Total Payable 5,352.87

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.