

# AUTOMAX SURVEY

Blk 110 Bedok Reservoir Road , #07-280, Singapore 470110  
Mobile : 9855 6879      Email : automaxsurvey@gmail.com  
Registration No. 53110062J

Report Ref : TP21080072

Date: 22 FEB 2022

**JC Connections Pte Ltd**  
**c/o Hup Ley Huat Motor Spray Painting Services**  
**Blk 1, #01- 35**  
**Kaki Bukit Ave 6**  
**Singapore 489978**

## THIRD PARTY SURVEY ACCIDENT OCCURED ON 04 AUG 2021

Workshop Name and Address      Hup Ley Huat Motor Spray Painting Services  
Blk 1, #01- 35  
Kaki Bukit Ave 6  
Singapore 417883

As per your instruction dated      02 sept 2021      with regard to the above matter.  
We have carried out a physical inspection on the said      GBD2456K  
We enclosed herewith our report and findings as follows:

### 1. VEHICLE PARTICULARS

Registration No : GBD2456K	Engine No : 1KD2414175
Model : TOYOTA DYNA 150	Mileage : 140 271km
Year / Capacity : Aug 2014 / 2982 cc	Colour : Metallic Silver
Chassis No : KDY2318016275	

### 2. TYRES CONDITION

	<u>Size</u>	<u>Made</u>	<u>Balance</u>	<u>Rim</u>
FRONT O/S :	195/50/R15	Bridgestone	9.00 mm	Normal
REAR O/S :	155 R 12	Bridgestone	9.00 mm	Normal
FRONT N/S :	195/50/R15	Bridgestone	9.00 mm	Normal
REAR N/S :	155 R 12	Bridgestone	9.00 mm	Normal

# AUTOMAX SURVEY

Blk 110 Bedok Reservoir Road , #07-280, Singapore 470110

Mobile : 9855 6879

Email : automaxsurvey@gmail.com

Registration No. 53110062J

## 3. DESCRIPTION OF DAMAGES

At the time of inspection, we noted that the vehicle has sustained an impact damages on the Rear & side portion(s). For more detail of the damages, please see photograph attached.

4. Estimated normal period of repair : 05 working days to complete

5. In accordance to your instruction, we have Not Authorised repair to the vehicle and the survey done on a "Without Prejudice" basis. We hope that this report will be of assistance to you in dealing with the matter.

6. Should you discover any discrepancy in the report, please kindly notify us within 1 week, or the report will be treated as correct.

### Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicles and/or other accidents in other legal proceedings.

Vehicle Number : GBD2456K

**SPARE PARTS**

QTY	PARTS DESCRIPTION	CONDITION	Workshop Estimation (S\$)	Our Revised Estimation (S\$)
<u>List Items</u>				
1 pc	Tailboard with hinges	Bent/deformed	\$ 1,850.00	\$ 1,850.00
1 pc	Tailboard lock	Damaged	\$ 220.00	\$ 220.00
2 pcs	Tailboard rubber stopper	Warped/deformed	\$ 80.00	\$ 80.00
1 pc	Tailboard lower member	Bent/distorted	\$ 650.00	\$ 650.00
1 pc	Sticker 'TOYOTA'	Essential	\$ 120.00	\$ 120.00
1 pc	Sticker 'DYNA'	Essential	\$ 80.00	\$ 80.00
2 pcs	Rear number plate lamp	cracked	\$ 75.00	\$ 75.00
1 pc	Rear number plate panel	bent	\$ 100.00	\$ 100.00
1 pc	Taillamps	Base cracked	\$ 275.00	\$ 275.00
1 pc	Taillamp brackets	Dent/distorted	\$ 148.00	\$ 148.00
1pc	Exhaust silencer	Bent/distorted	\$ 547.50	\$ 547.50
1pc	Exhaust silencer rubber	Bent/deformed	\$ 35.00	\$ 35.00
Parts Sub-Total			\$ 4,180.50	\$ 4,180.50
Discount 25.00%			\$ 1,045.13	\$ 1,045.13
			\$ 3,135.38	\$ 3,135.38

Vehicle Number : GBD2456K

**SPARE PARTS**

QTY	PARTS DESCRIPTION	CONDITION	Workshop Estimation (S\$)	Our Revised Estimation (S\$)
<u>Special Nett Items</u>				
1pc	Sticker '70KM/H'	Essential	\$ 55.00	\$ 55.00
1pc	Sticker '13 PAX'	Essential	\$ 55.00	\$ 55.00
1 pc	Rear number plate	damaged	\$ 75.00	\$ 75.00
1 pc	Company logo sticker	necessary	\$ 220.00	\$ 220.00
1 set	Rectangle" reflector	necessary	\$ 100.00	\$ 100.00
1 set	Circle" reflector	necessary	\$ 60.00	\$ 60.00
Special Nett Sub-Total			\$ 565.00	\$ 565.00
Spare Parts Total			\$ 3,700.38	\$ 3,700.38

## LABOUR COST

S/No	JOB DESCRIPTIONS	Workshop Estimation (S\$)	Our Revised Estimation (S\$)
	Spare PartsTotal c/f	\$ 3,700.38	\$ 3,700.38
1	Labour charges to repair and panel beat the tailboard lower support, rear cargo deck and replace the above mentioned parts.	\$ 1,400.00	\$ 1,200.00
2	To check wiring functions & conduct water leakage test.	\$ 180.00	\$ 150.00
3	To putty, apply primer & spray-paint the affected areas.	\$ 1,400.00	\$ 1,200.00
4	To apply rust-proofing on repaired/replaced panels.	\$ 180.00	\$ 150.00
	Total	\$ 6,860.38	\$ 6,400.38

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a Lump Sum Repair of :

\$ 5,150.00

  
Fong Kok Heng  
Qualified Appraiser





KEY AUTO



KEY AUTO



OMAX SURVEY



















