



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### Affiliated to Federation Internationale Des Experts En Automobile

INDIA INTERNATIONAL INSURANCE PL

Ref: CS3/III22002592/Tqy3e2

64 CECIL STREET

Date: 13/05/2022

#05-02 IOB BUILDING SINGAPORE 049711

Code: III2

#### 1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SMK 8962J	Veh. Inspected	SKC 6846R
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	Bhuvaneswari	Assign Date	21/03/2022

#### 2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.	WDD2040452A591041	Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

#### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

#### 4. Description of Damages

--	--

#### 5. General Information

Accident Date	18/02/2022	Inspection Date	24/03/2022
Survey held at	18, SENANG CRESCENT		
Repairer	6 SPEED AUTOWERKZ PTE LTD		

#### 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
--