



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAJ@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0227/2022/JT
DATE : 24-Feb-22
WIP : 16755

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE SURVEY 24/3/22
YOUR INSURED VEH NO : SLC 352 B

AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120
Attn: Motor Claims Dept
Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MS CHAN SIEW LIAN ANGELINE
ADDRESS : 335E PASIR PANJANG ROAD
SINGAPORE 118665
TELEPHONE : HP +65 96348427
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 7210114447
VEHICLE NO : **SNC 1135 G**
MODEL CODE : AUDI A5 SB 2.0 TFSI
MODEL YEAR : 28/9/2021
ENGINE NO : DEM 034040
CHASSIS NO : WAUZZZF5XMA059848
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 20-Mar-22
PLACE OF ACCIDENT : COLD STORAGE CAR PARK



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAJ@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SNC 1135 G

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00 / nec	
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 800.00 XNW	
3	TO REMOVE AND RENEW AIRCON CONDENSER, CHARGE AIR COOLER AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT.	S/N \$ 1,700.00 XNW	
4	TO CARRY OUT PRESSURISE, VACUUM AND REGAS FOR R1234.	S/N \$ 1,200.00 XNW	
5	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET AND BOTH HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 4,800.00 550	500.00
6	TO RESPRAY FRONT BUMPER AND BONNET.	\$ 2,500.00 1000	1,100.00
7	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00 / nec	
TOTAL LABOUR CHARGES		: \$ 11,672.00	



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNC 1135 G

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
1	FRONT BUMPER	1	\$ 2,493.00	Xr
2	FRONT BUMPER SECURING STRIP	2	\$ 79.00	Xr
3	FRONT BUMPER GRILLE - CENTER	1	\$ 219.00	XSVc
4	FRONT BUMPER CLOSING ELEMENT - LOWER CENTER	1	\$ 293.00	XSVc
5	FRONT BUMPER SPOILER	1	\$ 599.00	XSVc
6	FRONT BUMPER CLOSING ELEMENT	1	\$ 293.00	XSVc
7	FRONT BUMPER AIR GUIDE GRILLE - LH / RH	2	\$ 302.00	XSVc
8	FRONT BUMPER TRIM - LH / RH	2	\$ 108.00	XSVc
9	FRONT BUMPER TRIM - CENTER	1	\$ 127.00	XSVc
10	RADIATOR GRILLE	1	\$ 1,881.00	Scr 1,504.80
11	RADIATOR GRILLE COVER CAP	1	\$ 141.00	XSVc
12	RADIATOR GRILLE BRACKET	1	\$ 19.00	X SVc
13	RADIATOR GRILLE SECURING PLATE	1	\$ 12.00	X SVc
14	FRONT CAMERA	1	\$ 1,261.00	XSVc
15	FRONT BUMPER FOAM FILLER PIECE	1	\$ 163.00	X SVc
16	FRONT BUMPER REINFORCEMENT BEAM	1	\$ 899.00	XSVc
17	FRONT BUMPER TOP COVER	1	\$ 143.00	XSVc
18	CAUTION STICKER	1	\$ 16.00	X SVc
19	AIR COND STICKER	1	\$ 9.00	X SVc
20	FRONT BUMPER GUIDE SECTION - LH / RH	2	\$ 82.00	XSVc
SUB TOTAL SPARE PARTS		:	\$ 9,139.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNC 1135 G

S/N	PARTS DESCRIPTION	QTY	S/NETT	DAMAGED PARTS & PRICES	
				S/NETT	REMARKS
21	FRONT BUMPER BRACKET - LH / RH	2	\$	508.00	XSVC
22	FRONT BUMPER LOCK CARRIER BRACKET	1	\$	154.00	XSVC
23	FRONT BUMPER SUPPORT - LH / RH	2	\$	64.00	XSVC
24	POP RIVET	4	\$	4.00	XSVC
25	FRONT PARKING AID SENSOR - INNER	2	\$	530.00	XSVC
26	FRONT PARKING AID SENSOR SEAL RING	4	\$	10.00	XSVC
27	FRONT BUMPER WIRING SET	1	\$	449.00	XSVC
28	HORN - LH / RH	2	\$	273.00	XSVC
29	HORN SUPPORT - LH / RH	2	\$	66.00	XSVC
30	BONNET	1	\$	3,491.00	XSVC
31	BONNET ATTACHMENT PARTS	1	\$	128.00	XSVC
32	BONNET IMPACT PROTECTION - CENTER / LH / RH	3	\$	93.00	XSVC
33	BONNET STRIKER - LH / RH	2	\$	112.00	XSVC
34	BONNET LOCK	2	\$	455.00	XSVC
35	BONNET BOWDEN CABLE - CENTER	1	\$	64.00	XSVC
36	BONNET RELEASE LEVER	1	\$	15.00	XSVC
37	BONNET BOWDEN CABLE - OUTER	1	\$	64.00	XSVC
38	BONNET RELEASE CABLE COVER	1	\$	11.00	XSVC
39	HEADLIGHT MATRIX BEAM - LH / RH	2	\$	16,344.00	XSVC
40	LIFT CYLINDER - LH / RH	2	\$	434.00	XSVC
SUB TOTAL SPARE PARTS		:	\$	23,269.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNC 1135 G

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
				\$ 1,504.80
41	LIFT CYLINDER BRACKET - LH / RH	2	\$ 34.00	} X Svc
42	LIFT CYLINDER CORRUGATED PIPE	1	\$ 107.00	
43	LOCK CARRIER	1	\$ 1,127.00	
44	LOCK CARRIER SUPPORT - LH / RH	2	\$ 85.00	} X svc
45	RADIATOR COOLANT	6	\$ 282.00	
46	A/C CONDENSER	1	\$ 683.00	
47	OUTSIDE TEMPERATURE SENSOR BRACKET	1	\$ 21.00	} X Svc
48	CHARGE AIR COOLER	1	\$ 654.00	
49	RADIATOR AIR GUIDE - LH / RH	2	\$ 72.00	
50	RADIATOR AIR GUIDE INNER - LH / RH	2	\$ 38.00	} X Svc
51	RADIATOR AIR GUIDE UPPER	1	\$ 19.00	
52	FRONT NO PLATE	S/N	\$ DT ✓ 60.00	\$ 60.00
53	SUNDRIES		\$ 350.00	NN
TOTAL SPARE PARTS			\$ 35,940.00	\$ 1,564.80
TOTAL LABOUR CHARGES			\$ 11,672.00	\$ 2,272.00
GRAND TOTAL			\$ 47,612.00	\$ 3,836.80

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



XX (001 8511) E. SINGAPORE 4198000
 TEL: 0668 0424 FAX: 0661 1181
 EMAIL: NORA@PREMIUMAUTOMOBILES.COM.SG CLAIMS@PREMIUMAUTOMOBILES.COM.SG

NAME {
 SURVEYED DATE {
 AUTHORIZED DATE {
 EXCESS COST {
 LIABILITY {
 REMARKS {

Thuan @ LKK Auto loan 821,587.69
 24/5/22 w/pk/ly 5
 P/P

PLEASE NOTE {

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE
 AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER
 LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF
 REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
 FOR INSPECTION OF VEHICLE, PLEASE REFER TO
 MS. NORAH KHALAI TEL: 0668 9028 / 0668 9911 FOR
 APPOINTMENT.

YOURS FAITHFULLY,
 PREMIUM AUTOMOBILES PTE LTD

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
 BODY REPAIR MANAGER

ALLAN WU
 CLAIMS CONSULTANT