



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2206378

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 13/10/2022
Reference CC3/CTI22002606/Vpa3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SHC 394C
Insured Veh. SKL 4858Y
Claim No. SNM22D201728/C02
Policy No. DMPCSNW00255452101
Accident Date 12/03/2022
Inspection Date 14/03/2022

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC3/CTI22002606/Vpa3q2	
			Date: 13/10/2022	
			Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKL 4858Y	Veh. Inspected	SHC 394C	
Policy No.	DMPCSNW00255452101	Coverage (\$)	0.00	
Claim No.	SNM22D201728/C02	Excess (\$)	0.00	
Assign From		Assign Date	14/03/2022	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA PRIUS BYBRID	c.c	1798	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	JTDKB3FU503080277	Colour	YELLOW	
Odometer	-	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	WEST LAKE	5 mm	
L/H Front Tyre	195/65 R15	WEST LAKE	5 mm	
R/H Rear Tyre	195/65 R15	WEST LAKE	5 mm	
L/H Rear Tyre	195/65 R15	WEST LAKE	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	12/03/2022	Inspection Date	14/03/2022	
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 394C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRT FENDER LH	DENTED	945.30	945.30
1	FRT FENDER HYBRID EMBLEM LH	NECESSARY	86.50	86.50
1	PANEL SUB ASSY FRT DOOR LH	TO REPAIR SEE LABOUR	1,264.00	-
1	PANEL SUB ASSY RR DOOR LH	DENTED	1,258.30	1,258.30
1	REAR FENDER LH	TO REPAIR SEE LABOUR	836.70	-
1	FRT BUMPER SIDE RETAINER LH	NOT NECESSARY	77.00	-
1	HEADLAMP PANEL LH	SERVICEABLE	241.10	-
1	HEADLAMP LH	SERVICEABLE	2,735.28	-
1	FRONT BUMPER COVER	CUT	499.90	499.90
1	FRONT BUMPER SIDE BRACKET LH	NECESSARY	82.30	82.30
10	FRONT BUMPER CLIPS	NECESSARY	22.00	22.00
	LESS 25% DISCOUNT		-2,012.10	-723.60
			6,036.28	2,170.70
<u>SPECIAL NETT ITEMS</u>				
1	REAR FENDER PETROL STICKER LH (SN)	NECESSARY	15.00	15.00
1	FRT DOOR CITYCAB LOGO (SN)	NECESSARY	75.00	75.00
1	RR DOOR CITYCAB & APP STICKER (SN)	NECESSARY	80.00	80.00
			170.00	170.00
<u>LABOUR</u>				
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF PANEL SUB ASSY FRT DOOR LH AND REAR FENDER LH.		1,100.00	1,100.00
	SPRAY PAINTING CHARGE.		1,050.00	1,050.00
	CHECK ALL LIGHTING & WIRING.		60.00	30.00
	TRANSFER OF FRT & RR DOOR.		240.00	60.00
	TUFF KOTE.		50.00	30.00
			2,500.00	2,270.00
GRAND TOTAL			8,706.28	4,610.70



RECOMMENDED COST OF REPAIRS			4,610.70
------------------------------------	--	--	-----------------

Report Ref No. CC3/CT122002606/Vpa3q2

THEVAN THOMAS KARTHIKESAVAN

Asst. Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHC 394C

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHC 394C

RE-INSPECTION

