

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0208/2022/JT
DATE : 21-Mar-22
WIP : 16334

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 21/3/22

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR TAY HUP HUAT
ADDRESS : 29 TERRASSE LANE
#05-48
SINGAPORE 544778
TELEPHONE : HP +65 97641134
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1900090699-01
VEHICLE NO : **SNC 1453 M**
MODEL CODE : AUDI SEDAN 2.0 TFSI 8W
MODEL YEAR : 23/4/2019
ENGINE NO : CVK 077141
CHASSIS NO : WAUZZZF49KA042009
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 19-Mar-22
PLACE OF ACCIDENT : SYED ALWI ROAD (PARKING LOT 53)

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SNC 1453 M

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHT, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00	X.
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 350.00	X.
3	TO REMOVE AND TRANSFER RHS FRONT DOOR RHS REAR DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$ 700.00	280 ✓
4	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER, BONNET, RHS FRONT DOOR AND RHS REAR DOOR. TO REPAIR RHS SILL PANEL. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 4,500.00	1000 ✓
5	TO RESPRAY FRONT BUMPER, BONNET, RHS FRONT FENDER, RHS FRONT DOOR, RHS WING MIRROR COVER, RHS REAR DOOR, DOOR HANDLE AND RHS SILL PANEL.	\$ 5,500.00	2350 4x550 = 2200 Mirror = 150 2350 ✓
6	TO RENEW RHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT.	S/N \$ 280.00	240 ✓
7	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 12,002.00	

55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNC 1453 M - FRONT

S/N	PARTS DESCRIPTION	QTY	ESTIMATED CHARGES	SURV S/NETT	DAMAGED PARTS & PRICES	REMARKS
1	FRONT BUMPER	1	\$	2,377.00	X	
2	FRONT BUMPER AIR GUIDE - RH	1	\$	72.00	X	
3	FRONT BUMPER SECURING STRIP	1	\$	40.00	X	
4	FRONT BUMPER GUIDE SECTION - RH	1	\$	41.00	X	
5	FRONT FENDER - RH	1	\$	861.00	X	
6	FRONT FENDER CLOSING ELEMENT - RH	1	\$	81.00	X	
7	FRONT FENDER BRACKET - RH	1	\$	41.00	X	
8	FRONT FENDER BRACE - RH	1	\$	132.00	X	
9	FRONT FENDER POP RIVET	6	\$	23.00	X	
10	FRONT FENDER BRACKET CENTER - RH	1	\$	55.00	X	
11	FRONT WHEEL HOUSING LINER - RH	1	\$	262.00	X	
12	FRONT WHEEL SPOILER	1	\$	82.00	X	
13	FRONT FENDER LEDGE COVER LONG - RH	1	\$	35.00	X	
14	FRONT FENDER LEDGE COVER SHORT - RH	1	\$	26.00	X	
15	BONNET	1	\$	3,425.00	X	
16	BONNET IMPACT PROTECTION - CENTER / LH / RH	3	\$	93.00	X	
17	HEADLIGHT - RH	1	\$	8,294.00	X	
18	FRONT DOOR - RH	1	\$	3,431.00	X	2744.8
19	FRONT DOOR OUTER SEAL - RH	1	\$	229.00	X	182.8
20	BONDING AGENT	1	\$	51.00	X	nn
SUB TOTAL SPARE PARTS			:	\$	19,651.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183


EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNC 1453 M - FRONT

ESTIMATED		DAMAGED PARTS & PRICES	
S/N DESCRIPTION	PARTS DESCRIPTION	QTY	S/NETT
21	CLEANING SOLUTION ?	1 \$	74.00 ? nn
22	APPLICATOR ?	1 \$	8.00 ? nn
23	FRONT DOOR BUNGS ne nec	1 \$	5.00 x
24	FRONT DOOR CATCH - RH ?	1 \$	116.00 ? nn
25	WING MIRROR MOUNTING - RH Dm d	1 \$	991.00 ✓ 792.8
26	WING MIRROR CAP - RH Ris	1 \$	308.00 +
27	WING MIRROR GLASS - RH Shattered	1 \$	1,757.00 ✓ 1405.6
28	TYRE PRESSURE DATA PLATE Nec	1 \$	42.00 ✓ 33.36
29	FRONT DOOR CORNER TRIM - RH ne m	1 \$	51.00 +
30	FRONT DOOR WINDOW GUIDE TRIM STRIP - RH m m	1 \$	287.00 +
31	FRONT DOOR WINDOW GUIDE - RH ne m	1 \$	501.00 +
32	FRONT DOOR WINDOW SLOT SEAL TRIM STRIP - RH ne m	1 \$	344.00 +
33	FRONT DOOR HANDLE TRIM PLATE - RH 3 m m	1 \$	98.00 +
34	FRONT DOOR HANDLE CAP COVER - RH	1 \$	7.00 +
35	FRONT STONE CHIP GUARD - RH ut	1 \$	57.00 ✓ 45.28
SUB TOTAL SPARE PARTS		:	\$ 4,646.00

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
SPARE PARTS ARE SPECIAL NETT.



PREMIUM AUTOMOBILES



PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNC 1453 M - REAR

ESTIMATED	SUB-DAMAGED PARTS & PRICES	DAMAGED PARTS & PRICES	ESTIMATED
S/N/REMARKS ON	S/N/DESCRIPTION	PARTS DESCRIPTION	QTY S/NETT

1	REAR DOOR - RH	<i>Not new Repair</i>	1 \$ 3,431.00 <i>x</i>
2	REAR DOOR OUTER SEAL - RH	<i>Not new</i>	1 \$ 229.00 <i>x</i>
3	BONDING AGENT		1 \$ 51.00 <i>x</i>
4	CLEANING SOLUTION		1 \$ 74.00 <i>x</i>
5	APPLICATOR		1 \$ 8.00 <i>x</i>
6	REAR DOOR BUNGS		1 \$ 5.00 <i>x</i>
7	REAR DOOR SEALING STRIP	<i>Not new</i>	1 \$ 19.00 <i>x</i>
8	REAR DOOR CATCH - RH		1 \$ 134.00 <i>x</i>
9	REAR DOOR WINDOW SLOT SEAL TRIM STRIP - RH	<i>new</i>	1 \$ 410.00 <i>x</i>
10	RHS FRONT RIM	<i>Repair</i>	S/N TBC <i>x</i>
11	STONE CHIP	<i>?</i>	S/N \$ 180.00 <i>? nn</i>
12	SUNDRIES	<i>?</i>	\$ 300.00 <i>? 4.32</i>

TOTAL SPARE PARTS (FRONT & REAR)	:	\$ 29,138.00
TOTAL LABOUR CHARGES	:	\$ 12,002.00
GRAND TOTAL	:	\$ 41,140.00

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian King*
 SURVEYED DATE : *21/03/22*
 AUTHORISED DATE :
 EXCESS COST :
 LIABILITY :
 REMARKS : *Not Authorised, 06 Days*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORA KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
 PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
 BODY REPAIR MANAGER

ALLAN WU
 CLAIMS CONSULTANT

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: