

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0208/2022/JT
DATE : 21-Mar-22
WIP : 16334

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 21/3/22

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

Hi Adrian,

6 days - ok - Jy - 20 May 22

OWNER'S NAME : MR TAY HUP HUAT
ADDRESS : 29 TERRASSE LANE
#05-48
SINGAPORE 544778
TELEPHONE : HP +65 97641134
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1900090699-01
VEHICLE NO : **SNC 1453 M**
MODEL CODE : AUDI SEDAN 2.0 TFSI 8W
MODEL YEAR : 23/04/2019
ENGINE NO : CVK 077141
CHASSIS NO : WAUZZZF49KA042009
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 19-Mar-22
PLACE OF ACCIDENT : SYED ALWI ROAD (PARKING LOT 53)

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SNC 1453 M

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTT, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$	480.00	
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$	350.00	
3	TO REMOVE AND TRANSFER RHS FRONT DOOR RHS REAR DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$	700.00	\$ 280.00
4	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER, BONNET, RHS FRONT DOOR AND RHS REAR DOOR. TO REPAIR RHS SILL PANEL. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	4,500.00	\$ 1,000.00
5	TO RESPRAY FRONT BUMPER, BONNET, RHS FRONT FENDER, RHS FRONT DOOR, RHS WING MIRROR COVER, RHS REAR DOOR, DOOR HANDLE AND RHS SILL PANEL.	\$	5,500.00	\$ 2,350.00
6	TO RENEW RHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT.	S/N \$	280.00	\$ 240.00
7	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	\$ 12,002.00	\$ 4,062.00

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNC 1453 M - FRONT

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER	1	\$ 2,377.00	
2	FRONT BUMPER AIR GUIDE - RH	1	\$ 72.00	
3	FRONT BUMPER SECURING STRIP	1	\$ 40.00	
4	FRONT BUMPER GUIDE SECTION - RH	1	\$ 41.00	
5	FRONT FENDER - RH	1	\$ 861.00	
6	FRONT FENDER CLOSING ELEMENT - RH	1	\$ 81.00	
7	FRONT FENDER BRACKET - RH	1	\$ 41.00	
8	FRONT FENDER BRACE - RH	1	\$ 132.00	
9	FRONT FENDER POP RIVET	6	\$ 23.00	
10	FRONT FENDER BRACKET CENTER - RH	1	\$ 55.00	
11	FRONT WHEEL HOUSING LINER - RH	1	\$ 262.00	
12	FRONT WHEEL SPOILER	1	\$ 82.00	
13	FRONT FENDER LEDGE COVER LONG - RH	1	\$ 35.00	
14	FRONT FENDER LEDGE COVER SHORT - RH	1	\$ 26.00	
15	BONNET	1	\$ 3,425.00	
16	BONNET IMPACT PROTECTION - CENTER / LH / RH	3	\$ 93.00	
17	HEADLIGHT - RH	1	\$ 8,294.00	
18	FRONT DOOR - RH	1	\$ 3,431.00	\$ 2,744.80
19	FRONT DOOR OUTER SEAL - RH	1	\$ 229.00	\$ 182.80
20	BONDING AGENT	1	\$ 51.00	
SUB TOTAL SPARE PARTS		:	\$ 19,651.00	\$ 2,927.60

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNC 1453 M - FRONT

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
		<i>c/f</i>		\$	2,927.60
21	CLEANING SOLUTION	1	\$ 74.00		
22	APPLICATOR	1	\$ 8.00		
23	FRONT DOOR BUNGS	1	\$ 5.00		
24	FRONT DOOR CATCH - RH	1	\$ 116.00		
25	WING MIRROR MOUNTING - RH	1	\$ 991.00	\$	792.80
26	WING MIRROR CAP - RH	1	\$ 308.00		
27	WING MIRROR GLASS - RH	1	\$ 1,757.00	\$	1,405.60
28	TYRE PRESSURE DATA PLATE	1	\$ 42.00	\$	33.36
29	FRONT DOOR CORNER TRIM - RH	1	\$ 51.00		
30	FRONT DOOR WINDOW GUIDE TRIM STRIP - RH	1	\$ 287.00		
31	FRONT DOOR WINDOW GUIDE - RH	1	\$ 501.00		
32	FRONT DOOR WINDOW SLOT SEAL TRIM STRIP - RH	1	\$ 344.00		
33	FRONT DOOR HANDLE TRIM PLATE - RH	1	\$ 98.00		
34	FRONT DOOR HANDLE CAP COVER - RH	1	\$ 7.00		
35	FRONT STONE CHIP GUARD - RH	1	\$ 57.00	\$	45.28
SUB TOTAL SPARE PARTS		:	\$ 4,646.00	\$	5,204.64

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNC 1453 M - REAR

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
		c/f		\$ 5,204.64
1	REAR DOOR - RH	1	\$ 3,431.00	
2	REAR DOOR OUTER SEAL - RH	1	\$ 229.00	
3	BONDING AGENT	1	\$ 51.00	
4	CLEANING SOLUTION	1	\$ 74.00	
5	APPLICATOR	1	\$ 8.00	
6	REAR DOOR BUNGS	1	\$ 5.00	
7	REAR DOOR SEALING STRIP	1	\$ 19.00	
8	REAR DOOR CATCH - RH	1	\$ 134.00	
9	REAR DOOR WINDOW SLOT SEAL TRIM STRIP - RH	1	\$ 410.00	
10	RHS FRONT RIM	S/N	TBC	
11	STONE CHIP	S/N	\$ 180.00	
12	SUNDRIES		\$ 300.00	\$ 4.32
TOTAL SPARE PARTS (FRONT & REAR)			\$ 29,138.00	\$ 5,208.96
TOTAL LABOUR CHARGES			\$ 12,002.00	\$ 4,062.00
GRAND TOTAL			\$ 41,140.00	\$ 9,270.96

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.

bl-25/04/22



Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 / Fax: 6256 4315

Estimate No.
Date
Service Advisor
Pages
Regn No
Model No

PA/OD/0208/2022/TF

23-Mar-22

TONY

1 of 1

SNC 1453 M

AUDI SEDAN 2.0 TFSI

Quantity	Description	Unit Price	Amount
<u>Labours</u>			
1	TO REAPPLY PAINT COATING ON AFFECTED AREA	\$ 350.00	
	(Owner not claiming)		
GRAND TOTAL		\$ 350.00	

For Premium Automobiles Pte Ltd

 Authorised Signature