

JM 6 BAN 22 A 8 H 015 4203

PREMIER APPRAISER SERVICES

Our Ref: PT2106002-L

Vehicle No: SLR 4818 U

| Qty | Parts Descriptions | Conditions | Repairer's Est. | Our Revised |
|-----|--|----------------|-------------------|---------------------|
| | LIST ITEMS: | | | |
| 1 | radiator grille | snapped | S\$ 581.60 | S\$ 581.60 |
| 1 | radiator grille o/s chromed mldg | chafed | 176.70 | 176.70 |
| 1 | radiator grille o/s chromed garnish | damaged | 31.20 | 31.20 |
| 1 | radiator grille badge | damaged | 44.20 | 44.20 |
| 4 | radiator grille clips | necessary | 24.00 | 24.00 |
| 1 | front bumper | damaged | 958.10 | 958.10 |
| 10 | front bumper clips | necessary | 60.00 | 60.00 40 |
| 1 | front bumper o/s side retainer | damaged | 18.70 | 18.70 |
| 1 | front bumper o/s side attachment | damaged | 28.10 | 28.10 |
| 1 | front bumper o/s signal lamp | snapped | 157.30 | 157.30 |
| 1 | front bumper o/s signal lamp bkt | damaged | 17.10 | 17.10 XNN |
| 1 | front bumper o/s fog lamp cover | chafed | 57.00 | 57.00 XNN |
| 1 | o/s headlamp | snapped | 2,245.00 | 2,245.00 |
| 1 | o/s front fender | badly dented | 333.90 | 333.90 |
| 1 | o/s front fender splash shield | warped | 129.30 | 129.30 |
| 8 | o/s front fender splash shield clips | necessary | 48.00 | 48.00 30 |
| 1 | o/s front wheel cap | damaged | 45.00 | 45.00 |
| 1 | o/s front wheel bearing hub | damaged | 146.40 | 146.40 XNN |
| 1 | o/s front shock absorber | bent/stiffened | 395.80 | 395.80 XNN |
| 1 | o/s front shock absorber mounting | serviceable | 114.30 | - |
| 1 | o/s front knuckle arm | damaged | 351.80 | 351.80 XNN |
| 1 | o/s front lower arm | bent | 391.30 | 391.30 XNN |
| 1 | wiper washer tank | crushed | 104.00 | 104.00 |
| 1 | wiper washer tank motor | damaged | 476.00 | 476.00 XNN |
| 1 | wiper washer tank motor bush | damaged | 5.90 | 5.90 XNN |
| | | | S\$ 6,940.70 | S\$ 6,826.40 |
| | | | LESS 20% 1,388.14 | 20% 1,365.28 |
| | | | 5,552.56 | 5,461.12 |
| | S/NETT ITEMS: | | | |
| 1 | o/s front wheel rim - alloy ^{Steel} | dented/warped | 998.00 | 998.00 XNN |
| 1 | o/s front tyre (Pay 60%) | damaged | 280.00 | 168.00 XNN |
| | TOTAL S/PARTS | | S\$ 6,830.56 | S\$ 6,627.12 |
| | Towing charges | | 80.00 | 80.00 60 |
| | Labour charges to repair, panel beat and straighten damaged parts and replace the above-mentioned parts. | | 1,200.00 | 1,000.00 400 |
| | To dismantle/replace o/s front suspension parts. | | 280.00 | 220.00 X |
| | To check and adjust wheel alignment. (Before & After) | | 240.00 | 160.00 60 |
| | To remove/replace o/s front wheel rim & o/s front tyre, include balancing. | | 120.00 | 50.00 X |
| | To check wiring functions. | | 50.00 | 30.00 ✓ |
| | Balance c/d | | S\$ 8,800.56 | S\$ 8,167.12 |

PREMIER APPRAISER SERVICES

Our Ref: PT2106002-L

Vehicle No: SLR 4818 U

| | Repairer's Est. | Our Revised |
|--|---------------------|---------------------|
| Balance b/f | S\$ 8,800.56 | S\$ 8,167.12 |
| To putty, apply primer & spray-paint the affected areas. | 1,000.00 | 880.00 <i>400</i> |
| To apply rust-proofing on repaired/replaced panels. | 150.00 | 90.00 |
| TOTAL | S\$ <u>9,950.56</u> | S\$ <u>9,137.12</u> |

4 days

Note: The repairer has agreed to undertake the repairs at our adjusted amount of **S\$ 7,300.00 lump sum** corresponding to supply of parts, labour and spray painting charges.
The estimated period of repairs is **FIVE (5) days**. Pursuant to your instruction we have **not** authorised repairs on your behalf.

PREMIER APPRAISER SERVICES


LESLIE K C LIM CAE (UK), MIMI (UK)
MSAAA, Automotive Appraiser
Dip.MTM. Automotive Engineer